



Agilent 81250 ParBERT Measurement Software

**Spectral Jitter
Measurement
Programming Reference**



Agilent Technologies

Important Notice

© Agilent Technologies, Inc. 2003

Manual Part Number

5988-9645EN

Revision

Revision May 2003

Printed in Germany

Agilent Technologies
Herrenberger Straße 130
D-71034 Böblingen
Germany

Authors: t3 medien GmbH

Warranty

The material contained in this document is provided "as is," and is subject to being changed, without notice, in future editions. Further, to the maximum extent permitted by applicable law, Agilent disclaims all warranties, either express or implied, with regard to this manual and any information contained herein, including but not limited to the implied warranties of merchantability and fitness for a particular purpose. Agilent shall not be liable for errors or for incidental or consequential damages in connection with the furnishing, use, or performance of this document or of any information contained herein. Should Agilent and the user have a separate written agreement with warranty terms covering the material in this document that conflict with these terms, the warranty terms in the separate agreement shall control.

Technology Licenses

The hardware and/or software described in this document are furnished under a license and may be used or copied only in accordance with the terms of such license.

Restricted Rights Legend

If software is for use in the performance of a U.S. Government prime contract or subcontract, Software is delivered and licensed as "Commercial computer software" as defined in DFAR 252.227-7014 (June 1995), or as a "commercial item" as defined in FAR 2.101(a) or as "Restricted computer software" as defined in FAR 52.227-19 (June 1987) or any equivalent agency regulation or contract clause. Use, duplication or disclosure of Software is subject to Agilent Technologies' standard commercial license terms, and non-DOD Departments and Agencies of the U.S. Government will receive no greater than Restricted Rights as defined in FAR 52.227-19(c)(1-2) (June 1987). U.S. Government users will receive no greater than Limited Rights as defined in FAR 52.227-14 (June 1987) or DFAR 252.227-7015 (b)(2) (November 1995), as applicable in any technical data.

Safety Notices

CAUTION

A CAUTION notice denotes a hazard. It calls attention to an operating procedure, practice, or the like that, if not correctly performed or adhered to, could result in damage to the product or loss of important data. Do not proceed beyond a CAUTION notice until the indicated conditions are fully understood and met.

WARNING

A WARNING notice denotes a hazard. It calls attention to an operating procedure, practice, or the like that, if not correctly performed or adhered to, could result in personal injury or death. Do not proceed beyond a WARNING notice until the indicated conditions are fully understood and met.

Trademarks

Windows NT ® and MS Windows ® are U.S. registered trademarks of Microsoft Corporation.

Contents

About this Reference	7
<hr/>	
Programming Reference	9
<hr/>	
Measurement Basics	10
AnalyzerSystem	12
AnalyzerSystemSetting	13
CloseMeasurement	14
CreateMeasEx	15
CreateMeasurementEx	16
DelayStartSystem	18
GeneratorSystem	19
GeneratorSystemSetting	20
GetAnalyzerSettingsCount	21
GetAnalyzerSettingsName	22
GetGeneratorSettingsCount	23
GetGeneratorSettingsName	24
InitMeasurement	25
IsFWSConnected	26
MeasurementType	27
Server	28
ServerPort	29
StartDelay	30
UseAnalyzerSettings	31
UseGeneratorSettings	32
Measurement Setup	33
AcquisitionDepth	35
DisplayPowerUnits	36
FFTWindow	37
FFTWindowList	38
FreqAxisRangeType	39
FreqRange	40
FreqRangeEnable	42
GetAnalyzerPortCount	43

GetAnalyzerPortName	44
GetAnalyzerTermCount	45
GetAnalyzerTermName	46
GetPortId	47
GetTerminalId	48
GridPrecision	49
NoiseThreshold	50
PassFailUse	51
PassFailValue	53
PassFailValuePower	54
PortInvolved	56
PropertiesTitle	57
RelativeReferenceFrequency	58
SamplePointOffset	59
Scale	60
SetFreqAxisRange	61
ShowGrid	62
ShowMarkers	63
ShowProperties	64
TermInvolved	65
TopFrequencyCount	66
ViewType	67
Running the Measurement	68
Download	69
MeasState	70
Run	71
Stop	72
SynchronousRun	73
Handling Events and Callbacks	74
OnMeasDataAvailable	75
OnMeasurementComplete	76
OnMeasurementState	77
SetMeasEventsCallback	79
Error Handling	80
GetLastMeasError	81
SilentMode	82

Handling Measurement Results	83
DataAvailable	84
GetMeasFreqPrecision	85
GetMeasPowerPrecision	86
GetPowerdataArray	87
GetPowerDataPoint	88
GetPowerDataPointCount	89
GetTermCalculatedValue	90
GetTopFreqPowerValue	92
Pass/Fail Functions	93
GetMeasPassValue	94
GetPortPassValue	96
GetTermPassValue	98
Copy/Paste Functions	100
CopyToClipboard	101
CutToClipboard	102
EditDelete	103
IsCopyAvailable	104
IsCutAvailable	105
IsEditDeleteAvailable	106
IsPasteAvailable	107
PasteFromClipboard	108
Persistence	109
SaveMeasurement	110
LoadMeasurement	111
ExecuteExport	112
ExportDelimiter	113
ExportFileName	114
ExportLocale	115
ExportToClipboard	116
Functions for General Purposes	117
BackColor	118
ForeColor	119
FrequencyRangesColor	120
MeasHelpPath	121
MeasureWinHelp	122
PowerMarkerColor	123

About this Reference

This document describes the functions, properties and methods for controlling the Spectral Jitter measurement from a remote application.

NOTE Basic knowledge on handling the *Agilent ParBERT 81250 Measurement Software* is assumed. For further information, refer to the *Framework User Guide* and the *Spectral Jitter Measurement User Guide*.

For general information on remote programming, refer to the *Measurement Software Programming Guide*.

Programming Reference

The following sections describe the methods and properties from a Visual Basic, VEE or LabView user perspective. Some differences in the syntax will exist for the Visual C (VC) user. The VC syntax is denoted in each of the properties and methods.

NOTE

- Some of the methods, events and properties are not available to the wrapper dll user.
- The methods `InitMeasurement` and `CloseMeasurement` are only available to the wrapper dll user.

The functions are sorted according to the following categories:

- “*Measurement Basics*” on page 10 shows the functions used to handle measurements, to establish the connection to the firmware server, and to work with the settings.
- “*Measurement Setup*” on page 33 shows the functions used to work with ports and terminals, and to set the parameters for the measurement.
- “*Running the Measurement*” on page 68 shows the functions used to run and stop the measurement.
- “*Handling Events and Callbacks*” on page 74 shows the functions used to handle events and callbacks for the measurement.
- “*Error Handling*” on page 80 shows the functions used to analyze errors.
- “*Handling Measurement Results*” on page 83 shows the functions used to get, calculate, and modify measurement results.
- “*Pass/Fail Functions*” on page 93 shows the functions used to set and evaluate pass/fail decisions.
- “*Copy/Paste Functions*” on page 100 shows the functions used to edit the data display.

- “*Persistence*” on page 109 shows the functions used to load/save measurements and to export data from the measurements.
- “*Functions for General Purposes*” on page 117 shows the functions used to access the online help, for example.

Measurement Basics

The following section shows the functions used to handle measurements, to establish the firmware connection and to work with systems and system settings.

Functions to Get/Delete Measurement Handles

The following table gives an overview on the methods, events and properties available to handle measurements:

Purpose	Refer to...
To close a specific measurement.	“ <i>CloseMeasurement</i> ” on page 14
To initialize a measurement.	“ <i>InitMeasurement</i> ” on page 25

Functions to Establish the Firmware Connection

The following table gives an overview on the methods, events and properties available to control measurements:

Purpose	Refer to...
To set the connection to the firmware server.	“ <i>Server</i> ” on page 28
To set the port the firmware server is connected to.	“ <i>ServerPort</i> ” on page 29
To specify the analyzer system.	“ <i>AnalyzerSystem</i> ” on page 12
To specify the generator system.	“ <i>GeneratorSystem</i> ” on page 19
To specify the name of a system to be delayed.	“ <i>DelayStartSystem</i> ” on page 18
To specify a start delay between two systems.	“ <i>StartDelay</i> ” on page 30
To create a new measurement.	“ <i>CreateMeasurementEx</i> ” on page 16
To prepare the measurement execution.	“ <i>CreateMeasEx</i> ” on page 15
To check whether the connection to the firmware server is valid.	“ <i>IsFWSConnected</i> ” on page 26

Working with Settings

The following table gives an overview on the methods, events and properties available to handle systems and system settings:

Purpose	Refer to...
To get the number of system settings defined for the analyzer.	"GetAnalyzerSettingsCount" on page 21
To get the names of the system settings defined for the analyzer.	"GetAnalyzerSettingsName" on page 22
To get the number of system settings defined for the generator.	"GetGeneratorSettingsCount" on page 23
To get the names of the system settings defined for the generator.	"GetGeneratorSettingsName" on page 24
To specify the system setting for the analyzer.	"AnalyzerSystemSetting" on page 13
To specify the system setting for the generator.	"GeneratorSystemSetting" on page 20
To send the analyzer's system setting to the firmware server.	"UseAnalyzerSettings" on page 31
To send the generator's system setting to the firmware server.	"UseGeneratorSettings" on page 32

AnalyzerSystem

ActiveX syntax Object.AnalyzerSystem = [sSystem]

For Visual C:

```
Object.SetAnalyzerSystem(sSystem)  
sSystem = Object.GetAnalyzerSystem()
```

Wrapper dll syntax SPECJITSetAnalyzerSystem(hMeasurement,
 sSystem)
SPECJITGetAnalyzerSystem(hMeasurement,
 bufferSize,
 *sSystem)

Description Sets/returns the name of the analyzer system. The analyzer system specifies the analyzer for the measurement together with the related system setting.

Parameters **hMeasurement** Only for the wrapper dll: Handle to the measurement created by InitMeasurement (data type: ViSession).

bufferSize Only for the wrapper dll: Specifies the size of the data buffer for the returned data (data type: ViInt32).

sSystem Specifies the name of the analyzer system (data type: string). For the wrapper dll GET function, this parameter is a pointer.

Example To set the analyzer system "DSRA":

```
m_SpectralJitterCTRL.AnalyzerSystem = "DSRA"
```

Related functions and methods *"AnalyzerSystemSetting" on page 13*
"GeneratorSystem" on page 19
"CreateMeasurementEx" on page 16

AnalyzerSystemSetting

ActiveX syntax Object.AnalyzerSystemSetting = [sSetting]

For Visual C:

```
Object.SetAnalyzerSystemSetting(sSetting)
sSetting = Object.SetAnalyzerSystemSetting()
```

Wrapper dll syntax SPECJITSetAnalyzerSystemSetting(hMeasurement,
 sSetting)
SPECJITGetAnalyzerSystemSetting(hMeasurement,
 bufferSize,
 *sSetting)

Description Sets/returns the name of the analyzer system setting specified in the *Agilent 81250 User Software*. The analyzer system specifies together with the related system setting the analyzer for the measurement.

Parameters **hMeasurement** Only for the wrapper dll: Handle to the measurement created by `InitMeasurement` (data type: `ViSession`).

bufferSize Only for the wrapper dll: Specifies the size of the data buffer for the returned data (data type: `ViInt32`).

sSetting Specifies the name of the analyzer system setting (data type: string). For the wrapper dll GET function, this parameter is a pointer.

Example To set the analyzer system setting "TEST_APP":

```
m_SpectralJitterCTRL.AnalyzerSystemSetting = "TEST_APP"
```

Related functions and methods *"AnalyzerSystem" on page 12*

CloseMeasurement

NOTE This method is only available when using the wrapper dll.

Wrapper dll syntax `SPECJITCloseMeasurement(hMeasurement)`

Description Closes the measurement. The handle to the measurement is deleted. Any subsequent property or method using the handle will return an error.

Input parameter **hMeasurement.** Handle to the measurement (data type: ViSession) returned by `InitMeasurement`.

Related functions and methods *"CreateMeasurementEx" on page 16*
"InitMeasurement" on page 25

CreateMeasEx

ActiveX syntax Object.CreateMeasEx()

Wrapper dll syntax SPECJITCreateMeasEx(hMeasurement)

Description Creates the connection to the server, sets the generator and analyzer systems, delay system, the delay, and the measurement type. It assumes that the server name, port number, analyzer and generator system, delay system, delay value, and measurement type have been set by using the appropriate objects properties.

Input parameter **hMeasurement** Only for the wrapper dll: Handle to the measurement created by InitMeasurement (data type: ViSession).

Remarks You have to set the following properties before using this method:
Server, ServerPort, AnalyzerSystem, GeneratorSystem, DelayStartSystem,
StartDelay, MeasurementType

Related functions and methods *“Server” on page 28*
“ServerPort” on page 29
“AnalyzerSystem” on page 12
“GeneratorSystem” on page 19
“DelayStartSystem” on page 18
“StartDelay” on page 30
“MeasurementType” on page 27

CreateMeasurementEx

ActiveX syntax Object.CreateMeasurement(sServer,
 sPort,
 sAnalyzer,
 sGenerator,
 sDelaySystem,
 dDelay,
 measType)

Wrapper dll syntax SPECJITCreateMeasurementEx(hMeasurement,
 sServer,
 sPort,
 sAnalyzer,
 sGenerator,
 sDelaySystem,
 dDelay,
 measType)

Description Creates the connection to the server, sets the generator and analyzer systems, delay system, delay, and the measurement type.

Input parameters **hMeasurement** Only for the wrapper dll: Handle to the measurement (data type: ViSession).

sServer IP address of the server or LOCALHOST, for example, "10.3.6.14" (data type: String).

sPort Port number, set 2203 for the default port (data type: String).

sAnalyzer Name of the analyzer system, for example, "DSRA" (data type: String).

sGenerator Name of the generator system, for example, "DSRB" (data type: string).

sDelaySystem Name of the delayed system. It should either be the same name as the analyzer system or the generator system. If the analyzer and generator systems are the same, set this to an empty string (data type: string).

dDelay Delay in seconds that the sDelaySystem is delayed from the other system (data type: Double).

measType Measurement type: can be either MeasTypeElectrical, MeasTypeOptical, or MeasTypeAll (data type: enum).

Example	To connect to the firmware server under IP address 10.3.6.14 , port number 2203 , using the system DSRA as analyzer and generator, with no start delay, for a system with only electrical connections:
	<pre>m_SpectralJitterCTRL.CreateMeasurementEx("10.3.6.14","2203","DSRA", "DSRA","","",0,MeasTypeElectrical)</pre>
Related functions and methods	<i>"AnalyzerSystem" on page 12</i> <i>"AnalyzerSystemSetting" on page 13</i> <i>"DelayStartSystem" on page 18</i> <i>"GeneratorSystem" on page 19</i> <i>"GeneratorSystemSetting" on page 20</i> <i>"MeasurementType" on page 27</i> <i>"StartDelay" on page 30</i>

DelayStartSystem

ActiveX syntax Object.DelayStartSystem = [sDelaySystem]

For Visual C:

```
Object.SetDelayStartSystem(sDelaySystem)  
sDelaySystem = Object.GetDelayStartSystem()
```

Wrapper dll syntax SPECJITSetDelayStartSystem(hMeasurement,
 sDelaySystem)
SPECJITGetDelayStartSystem(hMeasurement,
 bufferSize,
 *sDelaySystem)

Description Sets the name of the system that is delayed.

Parameters **hMeasurement** Only for the wrapper dll: Handle to the measurement created by InitMeasurement (data type: ViSession).

bufferSize Only for the wrapper dll: Specifies the size of the data buffer for the returned data (data type: ViInt32).

sDelaySystem Name (data type: String) of the delayed system. It should be either the name of the analyzer or generator system set by AnalyzerSystem and GeneratorSystem. The delay system can be a null string, resulting in no delay. For the wrapper dll GET function, this parameter is a pointer.

Example To define a delay for the system **DSRA**:

```
m_SpectralJitterCTRL.DelayStartSystem = "DSRA"
```

Related functions and methods *"AnalyzerSystem" on page 12*
"GeneratorSystem" on page 19

GeneratorSystem

ActiveX syntax Object.GeneratorSystem = [sSystem]

For Visual C:

```
Object.SetGeneratorSystem(sSystem)  
sSystem = Object.GetGeneratorSystem()
```

Wrapper dll syntax SPECJITSetGeneratorSystem(hMeasurement,
 sSystem)
SPECJITGetGeneratorSystem(hMeasurement,
 bufferSize,
 *sSystem)

Description Sets/gets the name of the generator system. The generator system specifies together with the related system setting the generator for the measurement.

Parameters **hMeasurement** Only for the wrapper dll: Handle to the measurement created by `InitMeasurement` (data type: `ViSession`).

bufferSize Only for the wrapper dll: Specifies the size of the data buffer for the returned data (data type: `ViInt32`).

sSystem Specifies the name of the generator system (data type: `string`). For the wrapper dll GET function, this parameter is a pointer.

Example To select the generator system "DSRA":

```
m_SpectralJitterCTRL.GeneratorSystem = "DSRA"
```

Related functions and methods *"AnalyzerSystem" on page 12*
"GeneratorSystemSetting" on page 20

GeneratorSystemSetting

ActiveX syntax Object.GeneratorSystemSetting = [sSetting]

For Visual C:

```
Object.GetGeneratorSystemSetting(sSetting)  
sSetting = Object.SetGeneratorSystemSetting()
```

Wrapper dll syntax SPECJITSetGeneratorSystemSetting(hMeasurement,
 sSetting)
SPECJITGetGeneratorSystemSetting(hMeasurement,
 bufferSize,
 *sSetting)

Description Sets/returns the name of the generator system setting specified in the *Agilent 81250 User Software*. The generator system specifies the generator for the measurement together with the related system setting.

Parameters **hMeasurement** Only for the wrapper dll: Handle to the measurement created by InitMeasurement (data type: ViSession).

bufferSize Only for the wrapper dll: Specifies the size of the data buffer for the returned data (data type: ViInt32).

sSetting Specifies the name of the generator system setting (data type: String). For the wrapper dll GET function, this parameter is a pointer.

Example To set the generator system setting "TEST_APP":

```
m_SpectralJitterCTRL.GeneratorSystemSetting = "TEST_APP"
```

Related functions and methods *"GeneratorSystem" on page 19*

GetAnalyzerSettingsCount

ActiveX syntax nItems = Object.GetAnalyzerSettingsCount()

Wrapper dll syntax SPECJITGetAnalyzerSettingsCount(hMeasurement,
 *nItems)

Description Returns the number of settings stored in firmware for the analyzer system.

Output parameter **nItems** Number of settings for the analyzer system (data type: Integer). For the wrapper dll GET function, this parameter is a pointer.

Input parameter **hMeasurement** Only for the wrapper dll: Handle to the measurement created by InitMeasurement (data type: ViSession).

Example To get the number of settings defined for the analyzer system:

```
Dim nItems as Integer  
nItems = m_SpectralJitterCTRL.GetAnalyzerSettingsCount()
```

Related functions and methods “*GetAnalyzerSettingsName*” on page 22

GetAnalyzerSettingsName

ActiveX syntax sSettingName = Object.GetAnalyzerSettingsName(nIndex)

Wrapper dll syntax SPECJITGetAnalyzerSettingsName(hMeasurement,
 nIndex,
 bufferSize,
 *sSettingName)

Description Returns the setting name of the analyzer for a designated index.

Output parameter **sSettingName** Name of the analyzer setting (data type: String). For the wrapper dll function, this parameter is a pointer.

Input parameter **hMeasurement** Only for the wrapper dll: Handle to the measurement created by InitMeasurement (data type: ViSession).

nIndex Unique identifier for the setting. This is an index beginning at 0 (data type: Integer).

bufferSize Only for the wrapper dll: Specifies the size of the data buffer for the returned data (data type: ViInt32).

Example To get the first setting name for the analyzer:

```
Dim sSettingName as String  
sSettingName = m_SpectralJitterCTRL.GetAnalyzerSettingsName(0)
```

Related functions and methods “*GetAnalyzerSettingsCount*” on page 21

GetGeneratorSettingsCount

ActiveX syntax nItems = Object.GetGeneratorSettingsCount()

Wrapper dll syntax SPECJITGetGeneratorSettingsCount(hMeasurement,
 *nItems)

Description Returns the number of settings stored in firmware for the generator system.

Output parameter **nItems** Number of settings (data type: Integer) for the generator system. For the wrapper dll function, this parameter is a pointer.

Input parameter **hMeasurement** Only for the wrapper dll: Handle to the measurement created by InitMeasurement (data type: ViSession).

Example To get the number of system settings defined for the generator system:

```
Dim nItems as Integer  
nItems = m_SpectralJitterCTRL.GetGeneratorSettingsCount()
```

GetGeneratorSettingsName

ActiveX syntax sSettingName = Object.GetGeneratorSettingsName(nIndex)

Wrapper dll syntax SPECJITGetGeneratorSettingsName(hMeasurement,
 nIndex,
 bufferSize,
 *sSettingName)

Description Returns the setting name of the generator for a designated index.

Output parameter **sSettingName** Name of the generator setting (data type: String).
For the wrapper dll GET function, this parameter is a pointer.

Input parameter **hMeasurement** Only for the wrapper dll: Handle to the
measurement created by InitMeasurement (data type: ViSession).

nIndex Unique identifier (data type: Integer) for the setting, an
index starting at 0.

bufferSize Only for the wrapper dll: Specifies the size of the data
buffer for the returned data (data type: ViInt32).

Example To get the first setting name for the generator:

```
Dim sSettingName as String  
sSettingName = m_SpectralJitterCTRL.GetGeneratorSettingsName(0)
```

InitMeasurement

NOTE This method is only available when using the wrapper dll.

Wrapper dll syntax

```
ViSession hMeasurement = VI_NULL;
SPECJITInitMeasurement(&hMeasurement)
```

Description Initializes the measurement and the handle to the measurement is returned. Any subsequent property or method calls should use the handle value that is returned.

Output parameter **hMeasurement** Handle to the measurement (data type: ViSession)

IsFWSConnected

ActiveX syntax bConnect = Object.IsFWSConnected()

Wrapper dll syntax SPECJITIsFWSConnected(hMeasurement,
 *bConnect)

Description Returns whether there is a connection to the firmware server. To run the measurement a connection to the firmware server must be established.

Output parameter **bConnect** The following constants (data type: Boolean) are returned:

Constant	Description
True	There is a connection to the firmware server.
False	There is no connection to the firmware server.

For the wrapper dll function, this parameter is a pointer.

Input parameter **hMeasurement** Only for the wrapper dll: Handle to the measurement created by InitMeasurement (data type: ViSession).

Example To check the connection to the firmware server:

```
Dim bConnect as Boolean  
bConnect = m_SpectralJitterCTRL.IsFWSConnected()
```

Related functions and methods *“Server” on page 28*
 “ServerPort” on page 29

MeasurementType

ActiveX syntax Object.MeasurementType = [measType]
[measType] = Object.MeasurementType

For Visual C:

```
Object.SetMeasurementType(measType)  
measType = Object.GetMeasurementType()
```

Wrapper dll syntax SPECJITSetMeasurementType(hMeasurement,
 measType)
SPECJITGetMeasurementType(hMeasurement,
 *measType)

Description Sets/returns the measurement's *type* (whether the measurement is electrical only, optical only, or a combination of both).

Parameters **hMeasurement** Only for the wrapper dll: Handle to the measurement created by InitMeasurement (data type: ViSession).

measType Type of the measurement (data type: enum). The value can be either MeasTypeElectrical, MeasTypeOptical, or MeasTypeAll (both types in one system). For the wrapper dll GET function, this parameter is a pointer.

Example To set the measurement type for electrical only:

```
m_SpectralJitterCTRL.MeasurementType = MeasTypeElectrical
```

Related functions and methods *"CreateMeasurementEx" on page 16*

Server

ActiveX syntax Object.Server = [sServer]

For Visual C:

```
Object.SetServer(sServer)  
sServer = Object.GetServer()
```

Wrapper dll syntax SPECJITSetServer(hMeasurement,
 sServer)
SPECJITGetServer(hMeasurement,
 bufferSize,
 *sServer)

Description Sets/returns the server name for the *81200 Firmware Server*.

Parameters **hMeasurement** Only for the wrapper dll: Handle to the measurement created by InitMeasurement (data type: ViSession).

bufferSize Only for the wrapper dll: Specifies the size of the data buffer for the returned data (data type: ViInt32).

sServer Address of the server (data type: String). If the 81200 firmware server is located on the local machine, any empty string "" is used. For the wrapper dll GET function, this parameter is a pointer.

Example To establish a connection to the server address "10.3.6.14":

```
m_SpectralJitterCTRL.Server = "10.3.6.14"
```

Related functions and methods *"ServerPort" on page 29*

ServerPort

ActiveX syntax Object.ServerPort = [sPort]

For Visual C:

```
Object.SetServerPort(sPort)  
SPort = Object.GetServerPort()
```

Wrapper dll syntax SPECJITSetServerPort(hMeasurement,
 bufferSize,
 sPort)
SPECJITGetServerPort(hMeasurement,
 *sPort)

Description Sets/returns the port id for the firmware server connection.

Parameters **hMeasurement** Only for the wrapper dll: Handle to the measurement created by InitMeasurement (data type: ViSession).

bufferSize Only for the wrapper dll: Specifies the size of the data buffer for the returned data (data type: ViInt32).

sPort Port number for the firmware server connection (data type: String). For the wrapper dll GET function, this parameter is a pointer.

Example To establish a connection to the server located at port "2203":

```
m_SpectralJitterCTRL.ServerPort = "2203"
```

Related functions and methods *"Server" on page 28*

StartDelay

ActiveX syntax Object.StartDelay = [dDelay]

For Visual C:

```
Object.SetStartDelay(dDelay)  
dDelay = Object.GetStartDelay()
```

Wrapper dll syntax SPECJITGetStartDelay(hMeasurement,
 *dDelay)
SPECJITSetStartDelay(hMeasurement,
 dDelay)

Description Sets the start delay between the two systems. The `DelayStartSystem` property defines which system is delayed, the generator or analyzer.

Input parameters **hMeasurement** Only for the wrapper dll: Handle to the measurement created by `InitMeasurement` (data type: `ViSession`).

dDelay Start delay in seconds between the two systems (data type: `Double`). For the wrapper dll GET function, this parameter is a pointer.

Example To set the delay time to 0.5 seconds:

```
m_SpectralJitterCTRL.StartDelay = 0.5
```

Related functions and methods *“DelayStartSystem” on page 18*

UseAnalyzerSettings

ActiveX syntax Object.UseAnalyzerSettings = [boolean]

For Visual C:

```
Object.SetUseAnalyzerSettings(boolean)  
boolean = Object.GetUseAnalyzerSettings()
```

NOTE This property is not available for the wrapper dll.

Description Sets/returns whether the analyzer settings will be sent to the firmware server.

Parameters **boolean** The following constants (data type: Boolean) are defined:

Constant	Description
True	Send the analyzer settings to the firmware server.
False	Do not send the analyzer settings to the firmware server (default setting).

Remarks If this parameter is set to TRUE, a setting must be selected for the analyzer.

Example To send the selected system setting for the analyzer to the firmware server:

```
m_SpectralJitterCTRL.UseAnalyzerSettings = True
```

UseGeneratorSettings

ActiveX syntax Object.UseGeneratorSettings = [boolean]

For Visual C:

```
Object.SetUseGeneratorSettings(boolean)  
Boolean = Object.GetUseGeneratorSettings()
```

NOTE This property is not available for the wrapper dll.

Description Sets/returns whether the generator settings will be sent to the firmware server.

Parameter **boolean** The following constants (data type: Boolean) are defined:

Constant	Description
True	Send the selected generator setting to the firmware server.
False	Do not send the generator setting to the firmware server (default setting).

Remarks If this parameter is set to true, a setting must be selected for the generator.

Example To send the system setting specified for the generator to the firmware server:

```
m_SpectralJitterCTRL.UseGeneratorSettings = True
```

Measurement Setup

The following section shows the functions used to handle the parameters for the measurement.

Working with Ports and Terminals

The following table gives an overview on the methods, events and properties available to handle ports and terminals involved into the measurement:

Purpose	Refer to...
To get the number of analyzer ports configured in the system.	"GetAnalyzerPortCount" on page 43
To get the names of analyzer ports configured in the system.	"GetAnalyzerPortName" on page 44
To get the number of analyzer terminals configured in the system.	"GetAnalyzerTermCount" on page 45
To get the name of one analyzer terminal.	"GetAnalyzerTermName" on page 46
To get a port id for a given index.	"GetPortId" on page 47
To get a terminal id for a given index and port.	"GetTerminalId" on page 48
To set/return if a given port is part of the measurement.	"PortInvolved" on page 56
To set/return if a given terminal is part of the measurement.	"TermInvolved" on page 65

Setting Spectral Jitter Parameters

The following table gives an overview on the methods, events and properties available to handle the values of the Parameters page:

Purpose	Refer to...
To set the number of bits to be compared and captured.	"AcquisitionDepth" on page 35
To set the analyzer sampling point offset.	"SamplePointOffset" on page 59
To obtain the list of available FFT windows.	"FFTWindowList" on page 38
To enable an FFT window.	"FFTWindow" on page 37

Setting the Spectral Jitter Pass/Fail Parameters

The following table gives an overview on the methods, events and properties available to handle the values of the *Pass/Fail* page:

Purpose	Refer to...
To set/get which pass/fail parameters are considered when measuring Spectral Jitter.	" <i>PassFailUse</i> " on page 51
To set/get pass/fail values for the bit error rate.	" <i>PassFailValue</i> " on page 53
To set/get pass/fail maximum power limits.	" <i>PassFailValuePower</i> " on page 54

Setting Spectral Jitter View Parameters

The following table gives an overview on the methods, events and properties available to handle the values of the *View* page:

Purpose	Refer to...
To specify if absolute spectral power, true relative, or relative power is displayed.	" <i>ViewType</i> " on page 67
To set/get the reference frequency for a relative power measurement.	" <i>RelativeReferenceFrequency</i> " on page 58
To set/get the noise threshold.	" <i>NoiseThreshold</i> " on page 50
To set/get the number of top frequency/power pairs.	" <i>TopFrequencyCount</i> " on page 66
To define a frequency range for analysis.	" <i>FreqRange</i> " on page 40
To enable/disable a frequency range.	" <i>FreqRangeEnable</i> " on page 42
To set/get the frequency scale of the graph to logarithmic or linear.	" <i>Scale</i> " on page 60
To toggle the display of power values between linear and dB.	" <i>DisplayPowerUnits</i> " on page 36
To set min/max values for the frequency zoom function.	" <i>SetFreqAxisRange</i> " on page 61
To enable/disable the frequency zoom function.	" <i>FreqAxisRangeType</i> " on page 39
To display/hide markers in the graphical display.	" <i>ShowMarkers</i> " on page 63
To show or hide the grid of the graph.	" <i>ShowGrid</i> " on page 62
To set/get the number of decimal places to be displayed in the numerical view.	" <i>GridPrecision</i> " on page 49

Specify the Properties Dialog

The following table gives an overview on the methods, events and properties available to display the *Properties* dialog:

Purpose	Refer to...
To set the title of the <i>Properties</i> dialog.	" <i>PropertiesTitle</i> " on page 57
To display the <i>Properties</i> dialog.	" <i>ShowProperties</i> " on page 64

AcquisitionDepth

ActiveX syntax Object.AcquisitionDepth = [eAcqDepth]
[eAcqDepth] = Object.AcquisitionDepth

For Visual C:

```
Object.SetAcquisitionDepth(eAcqDepth)  
eAcqDepth = Object.GetAcquisitionDepth()
```

Wrapper dll syntax SPECJITSetAcquisitionDepth(hMeasurement,
 eAcqDepth)
SPECJITGetAcquisitionDepth(hMeasurement,
 *eAcqDepth)

Description Sets/returns the acquisition depth. This is the number of bits to be captured and compared and hence the length of the time record for the FFT. For details see the *Spectral Jitter Measurement User Guide*.

Parameters **hMeasurement** Only for the wrapper dll: Handle to the measurement created by `InitMeasurement` (data type: `ViSession`).

eAcqDepth Specifies the acquisition depth (data type: `AcquisitionDepthEnums`). For the wrapper dll GET function, this parameter is a pointer.

Example To set the acquisition depth to 512 Kbit:

```
m_SpectralJitterCTRL.AcquisitionDepth = AD_512_Kbit
```

Related functions and methods [“FFTWindowList” on page 38](#)
[“FFTWindow” on page 37](#)

DisplayPowerUnits

ActiveX syntax Object.DisplayPowerUnits = [ePowUnit]

For Visual C:

```
Object.SetDisplayPowerUnits(ePowUnit)  
ePowUnit P= Object.GetDisplayPowerUnits()
```

NOTE This property is not available for the wrapper dll.

Description Sets the power unit to linear or dB.

Input parameter **ePowUnit** The following constants (data type: PowerUnitsEnums) are defined:

Constant	Description
PowerLinear	Displays unitless power values (linear).
PowerDB	Displays power values in dB (logarithmic).

Example To display power values in dB:

```
m_SpectralJitterCTRL.DisplayPowerUnits = PowerDB
```

Related functions and methods *“Scale” on page 60*

FFTWindow

ActiveX syntax Object.FFTWindow = [sWindow]
[sWindow] = Object.FFTWindow

For Visual C:

```
Object.SetFFTWindow(sWindow)  
sWindow = Object.GetFFTWindow()
```

Wrapper dll syntax SPECJITSetFFTWindow(hMeasurement,
 sWindow)
SPECJITGetFFTWindow(hMeasurement,
 bufferSize,
 *sWindow)

Description Sets/returns the window used for the FFT. For details see the *Spectral Jitter Measurement User Guide*.

Parameters **hMeasurement** Only for the wrapper dll: Handle to the measurement created by InitMeasurement (data type: ViSession).

bufferSize Only for the wrapper dll: Specifies the size of the data buffer for the returned data (data type: ViInt32).

sWindow The name of the window (data type: String). For the wrapper dll GET function, this parameter is a pointer.

Example To enable the Hanning window:

```
m_SpectralJitterCTRL.FFTWindow = "Hanning"
```

Related functions and methods *"FFTWindowList" on page 38*

FFTWindowList

ActiveX syntax [sWindowlist] = Object.FFTWindowList

For Visual C:

```
sWindowlist = Object.FFTWindowlist()
```

Wrapper dll syntax SPECJITFFTWindowList(hMeasurement,
 bufferSize,
 *sWindowlist)

Description Returns the list of available FFT windows.

Parameters **hMeasurement** Only for the wrapper dll: Handle to the measurement created by InitMeasurement (data type: ViSession).

bufferSize Only for the wrapper dll: Specifies the size of the data buffer for the returned data (data type: ViInt32).

sWindowlist The list of available windows (data type: String). For the wrapper dll GET function, this parameter is a pointer.

Example To get the list of available FFT windows:

```
Dim sWindows as String  
sWindows = m_SpectralJitterCTRL.FFTWindowList()
```

The string may return: "Uniform, Hanning, Hamming, Blackman"

Related functions and methods *"FFTWindow" on page 37*

FreqAxisRangeType

Syntax `Object.FreqAxisRangeType = [eAxisType]`

For Visual C:

```
Object.SetFreqAxisRangeType(eAxisType)
eAxisType = Object.GetFreqAxisRangeType()
```

NOTE This property is not available for the wrapper dll.

Description Sets/gets the type of the graph's horizontal frequency axis. The frequency axis can show either the whole frequency range of the measurement or a section.

Parameter **eAxisType** The following constants (data type: `AxisFreqRangeTypeEnum`s) are defined:

Constant	Description
<code>AFT_EntireRange</code>	The graph shows the whole frequency range.
<code>AFT_ZoomMinMax</code>	The graph zooms a range defined by a min and max frequency.

Example To set the graph's FreqAxisRangeType to show the whole frequency range:

```
m_SpectralJitterCTRL.FreqAxisRangeType = AFT_EntireRange
```

Related functions and methods *"SetFreqAxisRange" on page 61*
"Scale" on page 60

FreqRange

ActiveX syntax

```
Object.SetFreqRange(sIndex,
                     eFreqRangeType,
                     eFreqRangePower,
                     dVal1,
                     dVal2)

boolean = Object.GetFreqRange(sIndex,
                             *eFreqRangeType,
                             *eFreqRangePower,
                             *dVal1,
                             *dVal2)
```

Wrapper dll syntax

```
SPECJITSetFreqRange(hMeasurement,
                     sIndex,
                     eFreqRangeType,
                     eFreqRangePower,
                     dVal1,
                     dVal2)

SPECJITGetFreqRange(hMeasurement,
                     sIndex,
                     *eFreqRangeType,
                     *eFreqRangePower,
                     *dVal1,
                     *dVal2)
```

Description Sets/returns the characteristics of a contiguous frequency range. For details see the Spectral Jitter Measurement User Guide.

Parameters **hMeasurement** Only for the wrapper dll: Handle to the measurement created by InitMeasurement (data type: ViSession).

sIndex The identifier of the frequency range: 0 to 7 (data type: VInt16).

eFreqRangeType 0 = defined by middle and bandwidth, 1 = defined by min and max frequency (data type: FrequencyRangeTypeEnums).

eFreqRangePower 0 = total power, 1 = peak power (data type: FrequencyRangePowerEnums).

dVal1 First frequency range value – middle or minimum frequency, depending on eFreqRangeType (data type: ViInt64).

dVal2 Second frequency range value – bandwidth or maximum frequency, depending on eFreqRangeType (data type: ViInt64).

Example To define frequency range #1 with min/max (2.55 MHz to 2.65 MHz) and total power calculation:

```
m_SpectralJitterCTRL.FreqRange = 0,  
                                AD_512_Kbit,  
                                FFT_MinMax,  
                                FFT_TotalPower,  
                                2550000,  
                                2650000
```

Related functions and methods *"FreqRangeEnable" on page 42*

FreqRangeEnable

ActiveX syntax Object.SetFreqRangeEnable (sIndex, bEnable)
 boolean = Object.GetFreqRangeEnable (sIndex, bEnable)

Wrapper dll syntax SPECJITSetFreqRangeEnable(hMeasurement,
 sIndex,
 bEnable)
SPECJITGetFreqRangeEnable(hMeasurement,
 sIndex,
 *bEnable)

Description The Set command enables/disables a frequency range. The Get command returns the status of the frequency range.

Parameters **hMeasurement** Only for the wrapper dll: Handle to the measurement created by InitMeasurement (data type: ViSession).

sIndex The identifier of the frequency range: 0 to 7
(data type: ViInt16).

bEnable True = enable, false = disable (data type: Boolean).

Example To enable frequency range #1:

```
m_SpectralJitterCTRL.FreqRangeEnable = 0, true
```

Related functions and methods *"FreqRange" on page 40*

GetAnalyzerPortCount

ActiveX syntax nPorts = Object.GetAnalyzerPortCount()

Wrapper dll syntax SPECJITGetAnalyzerPortCount(hMeasurement,
 *nPorts)

Description Returns the number of analyzer ports configured on the 81200 hardware.

Output parameter **nPorts** Number of data ports (data type: Integer) configured on the 81200 hardware. For the wrapper dll function, this parameter is a pointer.

Input parameter **hMeasurement** Only for the wrapper dll: Handle to the measurement created by InitMeasurement (data type: ViSession).

Example To get the number of analyzer ports:

```
Dim nPorts as Integer  
nPorts = m_SpectralJitterCTRL.GetAnalyzerPortCount()
```

Related functions and methods *"GetAnalyzerPortName" on page 44*

GetAnalyzerPortName

ActiveX syntax `sName = Object.GetAnalyzerPortName(nPortID)`

Wrapper dll syntax `SPECJITGetAnalyzerPortName(hMeasurement,
 nPortID,
 bufferSize,
 *sName)`

Description Returns the analyzer port name for a designated port id.

Output parameters **nPortID** A port is addressed by the port number (data type: Integer). This is an index starting at 1.

sName Name of the port as configured on the GUI (data type: String).

Input parameter **hMeasurement** Only for the wrapper dll: Handle to the measurement created by `InitMeasurement` (data type: ViSession).

bufferSize Only for the wrapper dll: Specifies the size of the data buffer for the returned data (data type: ViInt32). For the wrapper dll function, this parameter is a pointer.

Example To get the name of port 1:

```
Dim sName as String  
sName = m_SpectralJitterCTRL.GetAnalyzerPortName(1)
```

Related functions and methods *"GetAnalyzerPortCount" on page 43*

GetAnalyzerTermCount

ActiveX syntax nTermCount = Object.GetAnalyzerTermCount(nPortID)

Wrapper dll syntax SPECJITGetAnalyzerTermCount(hMeasurement,
 nPortID,
 *nTermCount)

Description Returns the number of terminals for the specified port as configured on the 81200 hardware.

Output parameter **nTermCount** Number of terminals for the specified port (data type: Integer).

Input parameter **hMeasurement** Only for the wrapper dll: Handle to the measurement created by InitMeasurement (data type: ViSession).

nPortID A port is addressed by the port number (data type: Integer). This is an index starting at 1. For the wrapper dll function, this parameter is a pointer.

Example To get the number of terminals configured for port 1:

```
Dim nTermCount as Integer  
nTermCount = m_SpectralJitterCTRL.GetAnalyzerTermCount(1)
```

Related functions and methods *"GetAnalyzerTermName" on page 46*

GetAnalyzerTermName

ActiveX syntax sName = Object.GetAnalyzerTermName(nPortID, nTerminalID)

Wrapper dll syntax SPECJITGetAnalyzerTermName(hMeasurement,
 nPortID,
 nTerminalID,
 bufferSize,
 *sName)

Description Returns the analyzer terminal name for a designated terminal id.

Output parameter **sName** Name of the port as configured on the GUI (data type: String). For the wrapper dll function, this parameter is a pointer.

Input parameter **hMeasurement** Only for the wrapper dll: Handle to the measurement created by InitMeasurement (data type: ViSession).

nPortID A port is addressed by the port number (data type: Integer). This is an index starting at 1.

nTerminalID A terminal is addressed by the terminal number (data type: Integer). This is an index starting at 1 for each port.

bufferSize Only for the wrapper dll: Specifies the size of the data buffer for the returned data (data type: ViInt32).

Example To get the name of terminal 1:

```
Dim sName as String  
sName = m_SpectralJitterCTRL.GetAnalyzerTermName(1)
```

Related functions and methods “*GetAnalyzerTermCount*” on page 45

GetPortId

ActiveX syntax nPortID = Object.GetPortId(nIndex)

Wrapper dll syntax SPECJITGetPortId(hMeasurement,
 nIndex,
 *nPortID)

Description Returns the port ID associated with an index. In some configurations, the ports are not sequential and may not begin with port ID = 1. This method allows you to uniquely identify ports.

Output parameter **nPortID** A port is addressed by the port number (data type: Integer). This is an index starting at 1. For the wrapper dll function, this parameter is a pointer.

Input parameters **hMeasurement** Only for the wrapper dll: Handle to the measurement created by InitMeasurement (data type: ViSession).

nIndex Unique identifier (data type: Integer) for the port, an index starting at 0.

Example To get the ID of the first port:

```
Dim nPortID as Integer  
nPortID = m_SpectralJitterCTRL.GetPortId(0)
```

GetTerminalId

ActiveX syntax nTermID = Object.GetTerminalId(nIndex,
 nPortID)

Wrapper dll syntax SPECJITGetTerminalId(hMeasurement,
 nIndex,
 nPortID,
 *nTermID)

Description Returns the terminal id associated with an index and a port. In some configurations, the terminals are not sequential and may not begin with terminal ID = 1. This method allows you to uniquely identify terminals.

Output parameter **nTermID** Returned value: A terminal is addressed by the terminal number (data type: Integer). For the wrapper dll function, this parameter is a pointer.

Input parameters **hMeasurement** Only for the wrapper dll: Handle to the measurement created by InitMeasurement (data type: ViSession).

nIndex Index starting at 0 (data type: Integer).

nPortID A port is addressed by the port number (data type: Integer). This is an index starting at 1.

Example To get the terminal ID for the first index of port 1:

```
Dim nTermID as Integer  
nTermID = m_SpectralJitterCTRL.GetTerminalId(1, 1)
```

GridPrecision

ActiveX syntax Object.GridPrecision = [ePrecision]

For Visual C:

```
Object.SetGridPrecision(ePrecision)  
ePrecision = Object.GetGridPrecision()
```

NOTE This property is not available for the wrapper dll.

Description Sets/returns the number of decimal places shown in the numerical view.

Parameter **ePrecision** The possible values (data type: PrecisionEnums) used are the integers 0 – 10, written out (Zero, One, ... Ten).

Example To set the number of decimal places to be displayed to 2:

```
m_SpectralJitterCTRL.GridPrecision = Two
```

NoiseThreshold

ActiveX syntax

```
Object.SetNoiseThreshold(dValue, eUnit)  
boolean = Object.GetNoiseThreshold(dValue, eUnit)
```

Wrapper dll syntax

```
SPECJITSetNoiseThreshold(hMeasurement,  
                           dValue,  
                           eUnit)  
  
SPECJITGetNoiseThreshold(hMeasurement,  
                         *dValue,  
                         *eUnit)
```

Description Sets/returns the noise threshold. This is the threshold used to separate between total power and noise power.

Parameters **hMeasurement** Only for the wrapper dll: Handle to the measurement created by InitMeasurement (data type: ViSession).

dValue The threshold value (data type: VIReal64).

eUnit The power unit: Linear or dB (data type: PowerUnitsEnums).

Example To set the noise threshold to -45 dB:

```
m_SpectralJitterCTRL.NoiseThreshold = -45, PowerDB
```

PassFailUse

ActiveX syntax Object.SetPassFailUse(eTerm,
 bUsed)

 bUsed = Object.GetPassFailUse(eTerm)

Wrapper dll syntax SPECJITSetPassFailUse(hMeasurement,
 eTerm,
 bUsed)

 SPECJITGetPassFailUse(hMeasurement,
 eTerm,
 *bUsed)

Description This method allows you to set/get which pass/fail parameters are considered for the test.

NOTE This method only allows you to *define* whether a parameters is considered during the test. To *set* the pass/fail values, use the PassFailValue and PassFailValuePower methods.

Parameters **hMeasurement** Only for the wrapper dll: Handle to the measurement created by InitMeasurement (data type: ViSession).

eTerm Defines one Pass/Fail criterion for testing the DUT (data type: PassFailUseEnums). It can have one of the following values:

Constant	Description
PFE_FreqRange1	Test passes if the measured power is below limit.
PFE_FreqRange2	Test passes if the measured power is below limit.
PFE_FreqRange3	Test passes if the measured power is below limit.
PFE_FreqRange4	Test passes if the measured power is below limit.
PFE_FreqRange5	Test passes if the measured power is below limit.
PFE_FreqRange6	Test passes if the measured power is below limit.
PFE_FreqRange7	Test passes if the measured power is below limit.
PFE_FreqRange8	Test passes if the measured power is below limit.
PFE_BitErrorRate	Test passes if the BER stays within the limits.
PFE_TotalPower	Test passes if the total power is below limit.
PFE_NoisePower	Test passes if the noise power is below limit.

bUsed The following constants (data type: Boolean) are defined:

Constant	Description
True	Parameter is considered during the test.
False	Parameter is not considered during the test.

For the wrapper dll function, this parameter is a pointer.

Example To set up a test so that the total jitter power is evaluated:

```
With m_SpectralJitterCTRL
    .SetPassFailUse PFE_TotalPower, True
End With
```

Related functions and methods *"PassFailValue" on page 53*
"PassFailValuePower" on page 54

PassFailValue

ActiveX syntax

```
Object.SetPassFailValue(eTerm,  
                        dValue)  
  
dValue = Object.GetPassFailValue(eTerm)
```

Wrapper dll syntax

```
SPECJITSetPassFailValue(hMeasurement,  
                        eTerm,  
                        dValue)  
  
SPECJITGetPassFailValue(hMeasurement,  
                        eTerm,  
                        *dValue)
```

Description Sets the pass/fail values for the bit error rate (BER).

Input parameters

hMeasurement Only for the wrapper dll: Handle to the measurement created by `InitMeasurement` (data type: `ViSession`).

eTerm Defines the parameter (data type: `PassFailValueEnums`). For the wrapper dll GET function, this parameter is a pointer. The following table indicates which parameters you can set with this command.

Constant	Description
<code>PFV_BitErrorRateMin</code>	Sets/gets the minimum value.
<code>PFV_BitErrorRateMax</code>	Sets/gets the maximum value.

dValue The pass/fail value used (data type: `VIReal64`). For the wrapper dll GET function, this parameter is a pointer.

Example To set the maximum allowed BER to 0.27:

```
With m_SpectralJitterCTRL  
    .SetPassFailUse PFE_BitErrorRate, True  
    .SetPassFailValue PFV_BitErrorRateMax, 0.27  
End With
```

Related functions and methods

- “`PassFailUse`” on page 51
- “`PassFailValuePower`” on page 54

PassFailValuePower

ActiveX syntax

```
Object.SetPassFailValuePower(eTerm,
                             eUnits,
                             dValue)

dValue = Object.GetPassFailValuePower(eTerm,
                                      eUnits)
```

Wrapper dll syntax

```
SPECJITSetPassFailValuePower(hMeasurement,
                            eTerm,
                            eUnits,
                            dValue)

SPECJITGetPassFailValuePower(hMeasurement,
                            eTerm,
                            *eUnits,
                            *dValue)
```

Description Sets the pass/fail power value for Total Power, Noise Power, or a frequency range.

Input parameters **hMeasurement** Only for the wrapper dll: Handle to the measurement created by `InitMeasurement` (data type: `ViSession`).

eTerm Defines one Pass/Fail power limit (data type: `PassFailValueEnums`). The following table indicates which parameters you can set with this command.

Constant	Description
<code>PFV_FreqRange1</code>	Sets/gets the maximum power value.
<code>PFV_FreqRange2</code>	Sets/gets the maximum power value.
<code>PFV_FreqRange3</code>	Sets/gets the maximum power value.
<code>PFV_FreqRange4</code>	Sets/gets the maximum power value.
<code>PFV_FreqRange5</code>	Sets/gets the maximum power value.
<code>PFV_FreqRange6</code>	Sets/gets the maximum power value.
<code>PFV_FreqRange7</code>	Sets/gets the maximum power value.
<code>PFV_FreqRange8</code>	Sets/gets the maximum power value.
<code>PFV_TotalPowerMax</code>	Sets/gets the maximum power value.
<code>PFV_NoisePowerMax</code>	Sets/gets the maximum power value.

eUnits Unit used for the value (data type: `PowerUnitsEnums`). The unit can be `PowerLinear` or `PowerDB`. For the wrapper dll GET function, this parameter is a pointer.

dValue The value used for the parameter (data type: `ViReal64`). For the wrapper dll GET function, this parameter is a pointer.

Example To set the upper limit for frequency range #2 to -36 dB:

```
With m_SpectralJitterCTRL
    .SetPassFailUse PFE_FreqRange2, TRUE
    .SetPassFailValuePower PFV_FreqRange2, PowerDB, -36
End With
```

Related functions and methods *"PassFailUse" on page 51*
 "PassFailValue" on page 53

PortInvolved

ActiveX syntax

```
Object.SetPortInvolved(nPortID,  
                      boolean)  
  
boolean = Object.GetPortInvolved(nPortID)
```

Wrapper dll syntax

```
SPECJITSetPortInvolved(hMeasurement,  
                      nPortID,  
                      boolean)  
  
SPECJITGetPortInvolved(hMeasurement,  
                      nPortID,  
                      *boolean)
```

Description Sets/returns whether a port is involved in the measurement.

Input parameters

hMeasurement Only for the wrapper dll: Handle to the measurement created by `InitMeasurement` (data type: `ViSession`).

nPortID A port is addressed by the port number (data type: `Integer`). This is an index starting at 1.

boolean Indicates if the port is involved in the measurement. The following constants (data type: `Boolean`) are defined:

Constant	Description
True	Port is involved in the measurement.
False	Port is not involved in the measurement.

For the wrapper dll GET function, this parameter is a pointer.

Example To set port 1 involved in the measurement:

```
m_SpectralJitterCTRL.SetPortInvolved(1, True)
```

To get whether port 1 is involved in the measurement:

```
Dim bIsInvolved as Boolean  
bIsInvolved = m_SpectralJitterCTRL.GetPortInvolved(1)
```

Related functions and methods “*TermInvolved*” on page 65

PropertiesTitle

ActiveX syntax Object.PropertiesTitle = [sTitle]

For Visual C:

```
Object.SetPropertiesTitle(sTitle)  
sTitle = Object.GetPropertiesTitle()
```

NOTE This property is not available for the wrapper dll.

Description Sets/returns the title of the *Properties* dialog.

Parameter **sTitle** Specifies the title of the *Properties* dialog (data type: String).

Example To set the title of the *Properties* dialog to "Spectral Jitter":

```
m_SpectralJitterCTRL.PropertiesTitle = "Spectral Jitter"
```

RelativeReferenceFrequency

ActiveX syntax `Object.RelativeReferenceFrequency = [dValue]
[dValue] = Object.RelativeReferenceFrequency`

For Visual C:

```
Object.SetRelativeReferenceFrequency(dValue)  
dValue = Object.GetRelativeReferenceFrequency()
```

Wrapper dll syntax `SPECJITSetRelativeReferenceFrequency(hMeasurement,
 dValue)
SPECJITGetRelativeReferenceFrequency(hMeasurement,
 *dValue)`

Description Sets/returns the reference frequency for relative measurements. This takes effect if you set the *View* to “Relative”. The measured power at this frequency is considered 0 dB, and all other power values are calibrated to that power. For details see the *Spectral Jitter Measurement User Guide*.

Parameters **hMeasurement** Only for the wrapper dll: Handle to the measurement created by `InitMeasurement` (data type: `ViSession`).

dValue Specifies the reference frequency (data type: `ViReal64`). For the wrapper dll GET function, this parameter is a pointer.

Example To set the reference frequency to 625 MHz:

```
m_SpectralJitterCTRL.RelativeReferenceFrequency = 625000000
```

Related functions and methods “*ViewType*” on page 67

SamplePointOffset

ActiveX syntax `Object.SamplePointOffset = [dValue]
[dValue] = Object.SamplePointOffset`

For Visual C:

```
Object.SetSamplePointOffset(dValue)  
dValue = Object.GetSamplePointOffset()
```

Wrapper dll syntax `SPECJITSetSamplePointOffset(hMeasurement,
 dValue)
SPECJITGetSamplePointOffset(hMeasurement,
 *dValue)`

Description Sets/returns the offset of the sampling point for the measurement from the current sampling point in Unit Intervals (UI). For details see the *Spectral Jitter Measurement User Guide*.

Parameters **hMeasurement** Only for the wrapper dll: Handle to the measurement created by `InitMeasurement` (data type: `ViSession`).

dValue Specifies the offset in UI (data type: `ViReal64`). For the wrapper dll GET function, this parameter is a pointer.

Example To set the offset to -0.49 UI:

```
m_SpectralJitterCTRL.SamplePointOffset = -0.49
```

Scale

Syntax Object.Scale = [eScale]

For Visual C:

```
Object.SetScale(eScale)  
eScale = Object.GetScale()
```

NOTE This property is not available for the wrapper dll.

Description Sets/get the graph's horizontal frequency scale.

Parameter **eScale** The following constants (data type: SCALE) are defined:

Constant	Description
Logarithmic	The graph is displayed in logarithmic mode.
Linear	The graph is displayed in linear mode.

Example To set the graph's scale to logarithmic:

```
m_SpectralJitterCTRL.Scale = Logarithmic
```

Related functions and methods *“DisplayPowerUnits” on page 36*

SetFreqAxisRange

Syntax Object.SetFreqAxisRange(dMin, dMax)

NOTE This property is not available for the wrapper dll.

Description Sets the range for the frequency zoom function. The zoom function can be enabled/disabled with FreqAxisRangeType.

Parameters **dMin** Specifies the start frequency (data type: Double).

dMax Specifies the end frequency (data type: Double).

Example To define a range for the frequency zoom from 1 MHz to 2.5 MHz:

```
m_SpectralJitterCTRL.SetFreqAxisRange = 1e6, 2.5e6
```

Related functions and methods *"FreqAxisRangeType" on page 39*

ShowGrid

ActiveX syntax Object.ShowGrid = [boolean]

For Visual C:

```
Object.SetShowGrid(boolean)  
boolean = Object.GetShowGrid()
```

NOTE This property is not available for the wrapper dll.

Description Switches the display of the graphical grid on or off.

Input parameter **boolean** The following constants (data type: Boolean) are defined:

Constant	Description
True	Turn on the display of the grid.
False	Turn off the display of the grid.

Example To display the grid in the graphical view:

```
m_SpectralJitterCTRL.ShowGrid = True
```

ShowMarkers

ActiveX syntax Object.ShowMarkers = [boolean]

For Visual C:

```
Object.SetShowMarkers(boolean)  
boolean = Object.GetShowMarkers()
```

NOTE This property is not available for the wrapper dll.

Description Sets the display of markers on or off.

Input parameter **boolean** The following constants (data type: Boolean) are defined:

Constant	Description
True	Turn on the display of markers.
False	Turn off the display of markers (default setting)

Example To display markers in the graphical view:

```
m_SpectralJitterCTRL.ShowMarkers = True
```

ShowProperties

ActiveX syntax `Object.ShowProperties()`

NOTE This method is not available for the wrapper dll.

Description Displays the *Properties* dialog for the control.

Parameter None

TermInvolved

ActiveX syntax

```
boolean = Object.GetTermInvolved(nPortID,
                                 nTermID)
```

```
Object.SetTermInvolved(nPortID,
                       nTermID,
                       boolean)
```

Wrapper dll syntax

```
SPECJITGetTermInvolved(hMeasurement,
                       nPortID,
                       nTermID,
                       *boolean)
```

```
SPECJITSetTermInvolved(hMeasurement,
                       nPortID,
                       nTermID,
                       boolean)
```

Description Sets/returns whether a terminal is involved in the measurement.

Input parameters

hMeasurement Only for the wrapper dll: Handle to the measurement created by InitMeasurement (data type: ViSession).

nPortID A port is addressed by the port number (data type: Integer). This is an index starting at 1.

nTermID A terminal is addressed by the terminal number (data type: Integer). This is an index starting at 1 for each port.

boolean Indicates if the terminal is involved in the measurement. The following constants (data type: Boolean) are defined:

Constant	Description
True	Terminal is involved in the measurement.
False	Terminal is not involved in the measurement.

For the wrapper dll GET function, this parameter is a pointer.

Example To set port 1, terminal 1 not involved in the measurement:

```
m_SpectralJitterCTRL.SetTermInvolved(1, 1, False)
```

To get whether terminal 1 of port 1 is involved in the measurement:

```
Dim bIsInvolved as Boolean
bIsInvolved = m_SpectralJitterCTRL.GetTermInvolved(1, 1)
```

Related functions and methods “*PortInvolved*” on page 56

TopFrequencyCount

ActiveX syntax Object.TopFrequencyCount = [nValue]
[nValue] = Object.TopFrequencyCount

For Visual C:

```
Object.SetTopFrequencyCount(nValue)  
nValue = Object.GetTopFrequencyCount()
```

Wrapper dll syntax SPECJITSetTopFrequencyCount(hMeasurement,
 nValue)
SPECJITGetTopFrequencyCount(hMeasurement,
 *nValue)

Description Sets/returns the number of top frequency/power pairs to be displayed.

Parameters **hMeasurement** Only for the wrapper dll: Handle to the
measurement created by InitMeasurement (data type: ViSession).

nValue Specifies the number of top frequency/power pairs: 1 to 16
(data type: ViInt16). For the wrapper dll GET function, this parameter
is a pointer.

Example To display six top frequency/power pairs:

```
m_SpectralJitterCTRL.TopFrequencyCount = 6
```

Related functions and methods *"RelativeReferenceFrequency" on page 58*

ViewType

ActiveX syntax `Object.ViewType = [eViewType]`

`[eViewType] = Object.ViewType`

For Visual C:

```
Object.SetViewType(eViewType)
eViewType = Object.GetViewType()
```

Wrapper dll syntax `SPECJITSetViewType(hMeasurement,
 eViewType)`
`SPECJITGetViewType(hMeasurement,
 *eViewType)`

Description Sets/returns the view type. The view type defines whether power values are calculated as absolute, true relative, or relative-to-reference-frequency values. True relative values are normalized to the total spectral power. Relative values are normalized to the spectral power measured at a reference frequency.

Parameters **hMeasurement** Only for the wrapper dll: Handle to the measurement created by `InitMeasurement` (data type: `ViSession`).

eViewType The following constants (data type: `ViewTypeEnum`s) are defined:

Constant	Description
<code>AbsPowerVsFreq</code>	Displays absolute power ratios.
<code>TrueRelPowerVsFreq</code>	Displays power values normalized to the total spectral power.
<code>RelRefPowerVsFreq</code>	Displays power values normalized to the spectral power measured at the reference frequency.

Example To display the true relative power values:

```
m_SpectralJitterCTRL.ViewType = TrueRelPowerVsFreq
```

Related functions and methods “*RelativeReferenceFrequency*” on page 58

Running the Measurement

The following table gives an overview on the methods, events and properties available to run the measurement:

Purpose	Refer to...
To load the measurement settings to the firmware server.	<i>"Download" on page 69</i>
To start a measurement run.	<i>"Run" on page 71</i>
To get the status of a measurement.	<i>"MeasState" on page 70</i>
To ensure a synchronous run on several systems.	<i>"SynchronousRun" on page 73</i>
To stop a measurement run.	<i>"Stop" on page 72</i>

Download

ActiveX syntax Object.Download()

Wrapper dll syntax SPECJITMeasureDownload(hMeasurement)

Description Ensures that all sequences are downloaded to the firmware server, so that a subsequent run has repeatable runtime behavior.

Input parameter **hMeasurement** Only for the wrapper dll: Handle to the measurement created by InitMeasurement (data type: ViSession).

Related functions and methods *“Run” on page 71*

MeasState

ActiveX syntax `sState = Object.MeasState`

For Visual C:

```
sState = Object.GetMeasState()
```

Wrapper dll syntax `SPECJITMeasureState(hMeasurement,
 bufferSize,
 sState)`

Description Returns the status of the measurement object. This property is read-only.

Output parameter **sState** The following measurement states (data type: String) are defined:

Constant	Description
RUNN	Measurement is running.
SYNC	Measurement is synchronizing.
PROG	Measurement is ready.
HALT	Measurement is prepared to run but the clocks are not ready and therefore, the measurement is waiting for an external trigger to start.

Input parameters **hMeasurement** Only for the wrapper dll: Handle to the measurement created by `InitMeasurement` (data type: `ViSession`).

bufferSize Only for the wrapper dll: Specifies the size of the data buffer for the returned data (data type: `ViInt32`).

Example To check the state of the measurement:

```
Dim sState as String  
sState = m_SpectralJitterCTRL.MeasState
```

Run

ActiveX syntax Object.Run()

Wrapper dll syntax SPECJITMeasureRun(hMeasurement)

Description Starts the measurement and ensures that the systems are started in the proper order as specified. Necessary sequence downloads are performed before, so that the time between starting system 1 and system 2 is always the specified delay.

Input parameter **hMeasurement** Only for the wrapper dll: Handle to the measurement created by InitMeasurement (data type: ViSession).

Related functions and methods *"SynchronousRun" on page 73*

Stop

ActiveX syntax `Object.Stop()`

Wrapper dll syntax `SPECJITMeasureStop(hMeasurement)`

Description Stops the measurement.

Input parameter **hMeasurement** Only for the wrapper dll: Handle to the measurement created by `InitMeasurement` (data type: `ViSession`).

Related functions and methods *“Run” on page 71*

SynchronousRun

ActiveX syntax Object.SynchronousRun()

NOTE This method is not available for the wrapper dll.

The wrapper dll function is called Run.

Description Starts the measurement but it does not return until the measurement has been completed. This method also ensures that the systems are started in the proper order as specified, necessary sequence downloads are performed before, so that the time between starting system 1 and system 2 is always the specified delay.

Related functions and methods *“Run” on page 71*

Handling Events and Callbacks

The following table gives an overview on the methods, events and properties available to handle events and callbacks

Purpose	Refer to...
To indicate if result data is available.	<i>"OnMeasDataAvailable" on page 75</i>
To indicate if the measurement run is complete.	<i>"OnMeasurementComplete" on page 76</i>
To indicate that a transition in the measurement status occurred.	<i>"OnMeasurementState" on page 77</i>
To register a callback function for certain events.	<i>"SetMeasEventsCallback" on page 79</i>

OnMeasDataAvailable

ActiveX syntax Private Sub Object_OnMeasDataAvailable(lItemCount as Long)

NOTE This event is not available for the wrapper dll.

Description Returns the number of data items that are currently available in the measurement object. The returned number can be used to allocate the required buffer size for requesting measured data or to check whether data is available or not.

Input parameter **lItemCount** A long value that indicates the number of data points available.

Example To get the number of data points available and display the value in a message box:

```
Private Sub MeasureSpectralJitter1_OnMeasDataAvailable(lItemCount as Long)
    Dim msg as string
    msg = "Number of items:" + lItemCount
    MsgBox msg
End Sub
```

OnMeasurementComplete

ActiveX syntax Private Sub Object_OnMeasurementComplete(lStatus As Long)

NOTE This event is not available for the wrapper dll.

Description Returns the measurement status upon completion of the measurement.

Input parameter **lStatus** A long value that indicates that the measurement run has been completed.

Example To check whether the measurement run is finished and display the fact in a message box:

```
Private Sub MeasureSpectralJitter1_OnMeasurementComplete(  
                            ByVal lStatus As Long)  
    MsgBox "Measurement is complete"  
End Sub
```

OnMeasurementState

ActiveX syntax Private Sub Object_OnMeasurementState(eMeasState As Long)

NOTE This event is not available for the wrapper dll.

Description Returns the measurement status when a transition in the measurement status occurs.

Input parameter **eMeasState** Indicates the measurement status. Possible values (data type: MeasureStateEnums) are:

Constant	Value	Description
StateProg	1	Measurement data is transferred.
StateRunning	2	The measurement is running.
StateComplete	3	The measurement run has been completed.
StateAbort	4	The measurement run has been aborted.
StateError	5	An error occurred.
StateSync	6	The system is synchronizing.
StateHalt	7	The system is in halted state, waiting for external start.
StateRunPulse	8	Heartbeat state.

For further information on the states, refer to *Handle Events and Callbacks* in the *Measurement Software Programming Guide*.

Example To check the measurement status and display a message box when the measurement is complete:

```
Private Sub MeasureSpectralJitter1_OnMeasurementState
    (ByVal lStatus as Long)
    ' This event is called when the measurement state changes
    Select Case lStatus

        Case 1
        ' Data transferred

        Case 2
        ' Measurement running

        Case 3
        ' Measurement complete
        MsgBox "The measurement is complete."

        Case 4
        ' Measurement aborted

        Case 5
        ' Error occurred
```

```
Case 6
' System synchronizing

Case 7
' System waiting for start

Case 8
' Heartbeat state

End Select
End Sub
```

SetMeasEventsCallback

NOTE This function is only available when using the wrapper dll.

Wrapper dll syntax `SPECJITSetMeasEventsCallback(hMeasurement,
 lpMeasEventsFunc,
 lParamUserCBData)`

Description To register a callback function that is called for certain events. For further information, refer to *Handle Events and Callbacks* in the *Measurement Software Programming Guide*.

Parameters **hMeasurement** Only for the wrapper dll: Handle to the measurement created by `InitMeasurement` (data type: `ViSession`).

lpMeasEventsFunc Callback function, for example:

```
ViStatus CALLBACK MeasEventsProc(ViSession hMeasurement,  
                          LPARAM lUserData,  
                          LONG lEventId,  
                          LPARAM lParam)
```

lParamUserCBData Measurement information structure.

Error Handling

The following table gives an overview on the methods, events and properties available to handle errors:

Purpose	Refer to...
To get the most recent error number from the firmware server.	<i>"GetLastMeasError" on page 81</i>
To specify if errors are to be reported when running a measurement.	<i>"SilentMode" on page 82</i>

GetLastMeasError

ActiveX syntax `sError = Object.GetLastMeasError(lError)`

Wrapper dll syntax `SPECJITGetLastMeasError(hMeasurement,
 *lError,
 sError
 bufferSize)`

Description Returns the last measurement error description from the firmware server.

Output parameters **sError** Error description (data type: String).

Input parameter **hMeasurement** Only for the wrapper dll: Handle to the measurement created by `InitMeasurement` (data type: ViSession).

bufferSize Only for the wrapper dll: Specifies the size of the data buffer for the returned data (data type: ViInt32).

lError Error number (data type: Long). For the wrapper dll GET function, this parameter is a pointer.

Example `Dim sError as String
sError = m_SpectralJitterCTRL.GetLastMeasError()`

SilentMode

ActiveX syntax Object.SilentMode = [boolean]

For Visual C:

```
Object.SetSilentMode(boolean)  
boolean = Object.GetSilentMode()
```

NOTE This property is not available for the wrapper dll.

Description Turns the display of error messages on and off.

Input parameter **boolean** The following constants (data type: Boolean) are defined:

Constant	Description
True	Turn on the display of error messages.
False	Turn off the display of error messages (default setting).

Example To turn error messages on:

```
m_SpectralJitterCTRL.SilentMode = True
```

Handling Measurement Results

The following table gives an overview on the methods, events and properties available to get and calculate measurement results:

Purpose	Refer to...
To get the number of captured and compared data points for a terminal.	<i>"DataAvailable" on page 84</i>
To get the number of power values for a terminal.	<i>"GetPowerDataPointCount" on page 89</i>
To get the power values for a terminal.	<i>"GetPowerdataArray" on page 87</i>
To get the frequency and power values for one data point.	<i>"GetPowerDataPoint" on page 88</i>
To get the measured values of a terminal individually.	<i>"GetTermCalculatedValue" on page 90</i>
To get the measured values of a top frequency/power pair.	<i>"GetTopFreqPowerValue" on page 92</i>
To get the frequency resolution of the measurement.	<i>"GetMeasFreqPrecision" on page 85</i>
To get the power precision of the measurement.	<i>"GetMeasPowerPrecision" on page 86</i>

DataAvailable

ActiveX syntax Object.DataAvailable(nPortId,
 nTerminalID,
 *lNumPoints)

Wrapper dll syntax SPECJITDataAvailable(hMeasurement,
 nPortId,
 nTerminalID,
 *lNumPoints)

Description Returns the number of data points that have been captured and compared for a specified port and terminal.

Output parameter **INumPoints** The returned value (data type: long) specifies the number of points that are available in the measurement. This parameter is a pointer.

Input parameters **hMeasurement** Only for the wrapper dll: Handle to the measurement created by InitMeasurement (data type: ViSession).

nPortId A port is addressed by the port number (data type: Integer). This is an index starting at 1.

nTerminalID A terminal is addressed by the terminal number (data type: Integer). This is an index starting at 1 for each port.

Example To get the number of data points available for terminal 1 of port 1:

```
Dim nItems as Long  
m_SpectralJitterCTRL.DataAvailable(1, 1, nItems)
```

GetMeasFreqPrecision

ActiveX syntax `dValue = Object.GetMeasFreqPrecision()`

Wrapper dll syntax `SPECJITGetMeasFreqPrecision(hMeasurement,
 *dValue)`

Description Returns the frequency resolution of the measurement. This is calculated as the analyzer data rate divided by the acquisition depth.

Output parameter **dValue** The returned value (data type: ViReal64) specifies the frequency distance between adjacent power values.

Input parameters **hMeasurement** Only for the wrapper dll: Handle to the measurement created by `InitMeasurement` (data type: ViSession).

Example To get the frequency precision of the measurement:

```
Dim dValue as Double  
dValue = m_SpectralJitterCTRL.GetMeasFreqPrecision()
```

GetMeasPowerPrecision

ActiveX syntax `dValue = Object.GetMeasPowerPrecision(eUnit)`

Wrapper dll syntax `SPECJITGetMeasPowerPrecision(hMeasurement,
 eUnit,
 *dValue)`

Description Returns the power resolution of the measurement.

Output parameter **dValue** The returned value (data type: ViReal64) specifies the power precision.

Input parameters **hMeasurement** Only for the wrapper dll: Handle to the measurement created by `InitMeasurement` (data type: ViSession).

eUnit The power unit of dValue (data type: PowerUnitsEnums). Accepted values are `PowerLinear` and `PowerDB`.

Example To get the power precision of the measurement:

```
Dim dValue as Double  
dValue = m_SpectralJitterCTRL.GetMeasPowerPrecision(PowerDB)
```

GetPowerdataArray

```
ActiveX syntax Object.GetPowerDataArray(nPortId,  
                           nTerminalID,  
                           lStartItem,  
                           lItemCount,  
                           *lItemsRet,  
                           PowerData)
```

```
Wrapper dll syntax    SPECJITGetPowerDataArray(hMeasurement,
                           nPortId,
                           nTerminalID,
                           lStartItem,
                           lItemCount,
                           *lItemsRet,
                           PowerData)
```

Description Returns for a specified port and terminal a selectable number of consecutive power values.

Output parameter **IItemsRet** The number of returned power values (data type: ViInt32).

Input parameters **hMeasurement** Only for the wrapper dll: Handle to the measurement created by `InitMeasurement` (data type: `ViSession`).

nPortId A port is addressed by the port number (data type: Integer). This is an index starting at 1.

nTerminalID A terminal is addressed by the terminal number (data type: Integer). This is an index starting at 1 for each port.

IStartItem The start index (data type: ViInt32).

IItemCount The number of requested power values (data type: ViInt32).

Power Data The pointer to the array that receives the power values (data type: ViReal64).

Related functions and methods “*GetPowerDataPointCount*” on page 89
“*GetPowerDataPoint*” on page 88

GetPowerDataPoint

ActiveX syntax	<pre>Object.GetPowerDataPoint(nPortId, nTerminalID, lDataIndex, *dFrequency, *dPower)</pre>
Wrapper dll syntax	<pre>SPECJITGetPowerDataPoint(hMeasurement, nPortId, nTerminalID, lDataIndex, *dFrequency, *dPower)</pre>
Description	Returns for a specified port and terminal the frequency and power of a single data point.
Output parameters	dFrequency The returned value (data type: ViReal64) specifies the frequency of the data point. dPower The returned value (data type: ViReal64) specifies the power of the data point.
Input parameters	hMeasurement Only for the wrapper dll: Handle to the measurement created by InitMeasurement (data type: ViSession). nPortId A port is addressed by the port number (data type: Integer). This is an index starting at 1. nTerminalID A terminal is addressed by the terminal number (data type: Integer). This is an index starting at 1 for each port. lDataIndex The index number of the data point (data type: ViInt32).
Example	To get the frequency and power values of data point DPnum for terminal 1 of port 1: <pre>Dim DPnum as Long Dim dFreq, dPow as Double m_SpectralJitterCTRL.GetPowerDataPoint(1, 1, DPnum, dFreq, dPow)</pre>
Related functions and methods	<i>“GetPowerDataPointCount” on page 89</i> <i>“GetPowerdataArray” on page 87</i>

GetPowerDataPointCount

ActiveX syntax Object.GetPowerDataPointCount(nPortId,
 nTerminalID,
 *lNumPoints)

Wrapper dll syntax SPECJITGetPowerDataPointCount(hMeasurement,
 nPortId,
 nTerminalID,
 *lNumPoints)

Description Returns the number of power values that are available for a specified port and terminal.

Output parameter **INumPoints** The returned value (data type: long) specifies the number of power values that are available in the measurement. This parameter is a pointer.

Input parameters **hMeasurement** Only for the wrapper dll: Handle to the measurement created by `InitMeasurement` (data type: ViSession).

nPortId A port is addressed by the port number (data type: Integer). This is an index starting at 1.

nTerminalID A terminal is addressed by the terminal number (data type: Integer). This is an index starting at 1 for each port.

Example To get the number of power values available for terminal 1 of port 1:

```
Dim nValues as Long  
m_SpectralJitterCTRL.GetPowerDataPointCount(1, 1, nValues)
```

Related functions and methods *"GetPowerDataPoint" on page 88*
 "GetPowerdataArray" on page 87

GetTermCalculatedValue

ActiveX syntax

```
dValue = Object.GetTermCalculatedValue(nPortID,
                                         nTermID,
                                         eAnalysisTerm,
                                         *bValid)
```

Wrapper dll syntax

```
SPECJITGetTermCalculatedValue(hMeasurement,
                               nPortID,
                               nTermID,
                               eAnalysisTerm,
                               *bValid,
                               *dValue)
```

Description Returns the value of the requested analysis term measured at the designated terminal.

Output parameters

dValue Returned measured or calculated value (data type: Double). For the wrapper dll GET function, this parameter is a pointer.

bValid Returns whether the value returned is valid for the measurement. There are several cases where the value may not be valid. The following constants (data type: Boolean) are defined:

Constant	Description
True	Value is valid for measurement.
False	Value is not valid for measurement.

This parameter is a pointer.

Input parameters

hMeasurement Only for the wrapper dll: Handle to the measurement created by InitMeasurement (data type: ViSession).

nPortID A port is addressed by the port number (data type: Integer). This is an index starting at 1.

nTermID A terminal is addressed by the terminal number (data type: Integer). This is an index starting at 1 for each port.

eAnalysisTerm The following constants (data type: AnalysisTermEnums) are defined:

Constant	Corresponds to:
AT_FreqRange1	Power of frequency range #1
AT_FreqRange2	Power of frequency range #2
AT_FreqRange3	Power of frequency range #3

Constant	Corresponds to:
AT_FreqRange4	Power of frequency range #4
AT_FreqRange5	Power of frequency range #5
AT_FreqRange6	Power of frequency range #6
AT_FreqRange7	Power of frequency range #7
AT_FreqRange8	Power of frequency range #8
AT_BitErrorRate	Bit error rate
AT_TotalPower	Total power
AT_NoisePower	Noise power

Remarks You have to check if bValid = True before reporting or using the returned value.

Example To get the calculated power of frequency range #2 for terminal 3 of port 1:

```
Dim dValue as Double
Dim bValid as boolean
dValue = m_SpectralJitterCTRL.GetTermCalculatedValue(1,
    3,
    AT_FreqRange2,
    bValid)
```

GetTopFreqPowerValue

ActiveX syntax boolean = Object.GetTopFreqPowerValue(nPortID,
 nTermID,
 nDataIndex,
 *dFrequency,
 *dPower)

Wrapper dll syntax SPECJITGetTopFreqPowerValue(hMeasurement,
 nPortID,
 nTermID,
 nDataIndex,
 *dFrequency)
 *dPower)

Description Returns the frequency and power for the specified pair of top frequency/power values.

Input parameters **hMeasurement** Only for the wrapper dll: Handle to the measurement created by `InitMeasurement` (data type: `ViSession`).

nPortID A port is addressed by the port number (data type: `ViInt16`). This is an index starting at 1.

nTermID Terminal ID number within the port (data type: `ViInt16`).

nDataIndex The number of the pair of frequency/power values: 1 to 16 (data type: `ViInt32`).

Output parameters **dFrequency** The center frequency of the frequency bin (data type: `ViReal64`).

dPower The power of the frequency bin (data type: `ViReal64`).

Related functions and methods *“TopFrequencyCount” on page 66*

“GetTerminalId” on page 48

Pass/Fail Functions

The following sections show the functions used to set and evaluate pass/fail decisions.

The following table gives an overview on the methods, events and properties available to check if a measurement, port or terminal has passed or failed:

Purpose	Refer to...
To check if a parameter has passed for the complete measurement.	<i>"GetMeasPassValue" on page 94</i>
To check if a parameter has passed for a given port.	<i>"GetPortPassValue" on page 96</i>
To check if a parameter has passed for a given terminal.	<i>"GetTermPassValue" on page 98</i>

GetMeasPassValue

ActiveX syntax `bIsPass = Object.GetMeasPassValue(eAnalysisTerm)`

Wrapper dll syntax `SPECJITGetMeasPassValue(hMeasurement,
 eAnalysisTerm,
 *bIsPass)`

Description Returns whether a measurement parameter has passed or failed the pass/fail criterion. The criteria are set by separate pass/fail methods.

Output parameter **bIsPass** Returns whether the designated measurement parameter passed or failed. The following constants (data type: Boolean) are defined:

Constant	Description
True	Measurement passed.
False	Measurement failed.

For the wrapper dll GET function, this parameter is a pointer.

Input parameters **hMeasurement** Only for the wrapper dll: Handle to the measurement created by `InitMeasurement` (data type: `ViSession`).

eAnalysisTerm The following constants (data type: `AnalysisTermEnums`) are defined:

Constant	Corresponds to:
<code>AT_FreqRange1</code>	Power of frequency range #1
<code>AT_FreqRange2</code>	Power of frequency range #2
<code>AT_FreqRange3</code>	Power of frequency range #3
<code>AT_FreqRange4</code>	Power of frequency range #4
<code>AT_FreqRange5</code>	Power of frequency range #5
<code>AT_FreqRange6</code>	Power of frequency range #6
<code>AT_FreqRange7</code>	Power of frequency range #7
<code>AT_FreqRange8</code>	Power of frequency range #8
<code>AT_BitErrorRate</code>	Bit error rate
<code>AT_TotalPower</code>	Total power
<code>AT_NoisePower</code>	Noise power
<code>AT_AllAnalysis</code>	Values for all conditions

Remarks The criteria will always pass if the pass/fail criterion has been turned off using the PassFailUse.

You have to check if bValid = True before reporting or using the returned value.

Example To see if the measurement has passed the BER limits:

```
Dim bBERPassed as Boolean  
bBERPassed = m_SpectralJitterCTRL.GetMeasPassValue(AT_BitErrorRate)
```

Related functions and methods
“*GetPortPassValue*” on page 96
“*GetTermPassValue*” on page 98
“*PassFailUse*” on page 51

GetPortPassValue

ActiveX syntax

```
bPass = Object.GetPortPassValue(nPortID,
                               eAnalysisTerm,
                               *bValid)
```

Wrapper dll syntax

```
SPECJITGetPortPassValue(hMeasurement,
                        nPortID,
                        eAnalysisTerm,
                        *bValid,
                        *bPass)
```

Description Returns whether for a certain port a measurement parameter has passed or failed the pass/fail criterion. The criteria are set by separate pass/fail methods.

Output parameters

bPass Returns whether the designated measurement parameter passed or failed. The following constants (data type: Boolean) are defined:

Constant	Description
True	Port measurement value passed.
False	Port measurement value failed.

For the wrapper dll function, this parameter is a pointer.

bValid Returns whether the value returned is valid for the measurement. The following constants (data type: Boolean) are defined:

Constant	Description
True	Data is valid for the measurement.
False	Data is not valid for the measurement.

This parameter is a pointer.

Input parameters

hMeasurement Only for the wrapper dll: Handle to the measurement created by InitMeasurement (data type: ViSession).

nPortID A port is addressed by the port number (data type: Integer). This is an index starting at 1.

eAnalysisTerm The following constants (data type: AnalysisTermEnums) are defined:

Constant	Corresponds to:
AT_FreqRange1	Power of frequency range #1
AT_FreqRange2	Power of frequency range #2
AT_FreqRange3	Power of frequency range #3
AT_FreqRange4	Power of frequency range #4
AT_FreqRange5	Power of frequency range #5
AT_FreqRange6	Power of frequency range #6
AT_FreqRange7	Power of frequency range #7
AT_FreqRange8	Power of frequency range #8
AT_BitErrorRate	Bit error rate
AT_TotalPower	Total power
AT_NoisePower	Noise power
AT_AllAnalysis	Values for all conditions

Remarks The criteria will always pass if the pass/fail criterion has been turned off using the PassFailUse.

You have to check if bValid = True before reporting or using the returned value.

Example To check the pass/fail criterion *Total Power* for port 1:

```
Dim bPass, bValid as Boolean
bPass = m_SpectralJitterCTRL.GetPortPassValue(1, AT_TotalPower,
bValid)
```

Related functions and methods
"GetMeasPassValue" on page 94
"GetTermPassValue" on page 98
"PassFailUse" on page 51

GetTermPassValue

ActiveX syntax

```
bPass = Object.GetTermPassValue(nPortID,
                                nTermID,
                                eAnalysisTerm,
                                *bValid)
```

Wrapper dll syntax

```
SPECJITGetTermPassValue(hMeasurement,
                        nPortID,
                        nTermID,
                        eAnalysisTerm,
                        bValid,
                        bPass)
```

Description Returns whether for a certain terminal a measurement parameter has passed or failed the pass/fail criterion. The criteria are set by separate pass/fail methods.

NOTE Before GetTermPassValue can return a valid result, PassFailUse must have first been called for all parameters of interest.

If these values are not correctly set, GetTermPassValue always returns TRUE.

Output parameters

bPass Returns whether the designated measurement parameter passed or failed. The following constants (data type: Boolean) are defined:

Constant	Description
True	Terminal measurement value passed.
False	Terminal measurement value failed.

For the ActiveX function, this parameter is a pointer.

bValid Returns whether the value returned is valid for the measurement. The following constants (data type: Boolean) are defined:

Constant	Description
True	Data is valid for the measurement.
False	Data is not valid for the measurement.

This parameter is a pointer.

Input parameters	hMeasurement Only for the wrapper dll: Handle to the measurement created by InitMeasurement (data type: ViSession).																										
	nPortID A port is addressed by the port number (data type: Integer). This is an index starting at 1 for each clock group.																										
	nTermID A terminal is addressed by the terminal number (data type: Integer). This is an index starting at 1 for each port.																										
	eAnalysisTerm Defines the parameter to be checked. The following constants (data type: AnalysisTermEnums) are defined:																										
	<table border="1" data-bbox="612 665 1462 1235"> <thead> <tr> <th data-bbox="612 665 938 707">Constant</th><th data-bbox="938 665 1462 707">Corresponds to:</th></tr> </thead> <tbody> <tr> <td data-bbox="612 728 938 749">AT_FreqRange1</td><td data-bbox="938 728 1462 749">Power of frequency range #1</td></tr> <tr> <td data-bbox="612 770 938 792">AT_FreqRange2</td><td data-bbox="938 770 1462 792">Power of frequency range #2</td></tr> <tr> <td data-bbox="612 813 938 834">AT_FreqRange3</td><td data-bbox="938 813 1462 834">Power of frequency range #3</td></tr> <tr> <td data-bbox="612 855 938 876">AT_FreqRange4</td><td data-bbox="938 855 1462 876">Power of frequency range #4</td></tr> <tr> <td data-bbox="612 897 938 918">AT_FreqRange5</td><td data-bbox="938 897 1462 918">Power of frequency range #5</td></tr> <tr> <td data-bbox="612 939 938 960">AT_FreqRange6</td><td data-bbox="938 939 1462 960">Power of frequency range #6</td></tr> <tr> <td data-bbox="612 982 938 1003">AT_FreqRange7</td><td data-bbox="938 982 1462 1003">Power of frequency range #7</td></tr> <tr> <td data-bbox="612 1024 938 1045">AT_FreqRange8</td><td data-bbox="938 1024 1462 1045">Power of frequency range #8</td></tr> <tr> <td data-bbox="612 1066 938 1087">AT_BitErrorRate</td><td data-bbox="938 1066 1462 1087">Bit error rate</td></tr> <tr> <td data-bbox="612 1108 938 1129">AT_TotalPower</td><td data-bbox="938 1108 1462 1129">Total power</td></tr> <tr> <td data-bbox="612 1151 938 1172">AT_NoisePower</td><td data-bbox="938 1151 1462 1172">Noise power</td></tr> <tr> <td data-bbox="612 1193 938 1214">AT_AllAnalysis</td><td data-bbox="938 1193 1462 1214">Values for all conditions</td></tr> </tbody> </table>	Constant	Corresponds to:	AT_FreqRange1	Power of frequency range #1	AT_FreqRange2	Power of frequency range #2	AT_FreqRange3	Power of frequency range #3	AT_FreqRange4	Power of frequency range #4	AT_FreqRange5	Power of frequency range #5	AT_FreqRange6	Power of frequency range #6	AT_FreqRange7	Power of frequency range #7	AT_FreqRange8	Power of frequency range #8	AT_BitErrorRate	Bit error rate	AT_TotalPower	Total power	AT_NoisePower	Noise power	AT_AllAnalysis	Values for all conditions
Constant	Corresponds to:																										
AT_FreqRange1	Power of frequency range #1																										
AT_FreqRange2	Power of frequency range #2																										
AT_FreqRange3	Power of frequency range #3																										
AT_FreqRange4	Power of frequency range #4																										
AT_FreqRange5	Power of frequency range #5																										
AT_FreqRange6	Power of frequency range #6																										
AT_FreqRange7	Power of frequency range #7																										
AT_FreqRange8	Power of frequency range #8																										
AT_BitErrorRate	Bit error rate																										
AT_TotalPower	Total power																										
AT_NoisePower	Noise power																										
AT_AllAnalysis	Values for all conditions																										
Remarks	The parameter will always pass if its pass/fail criterion have been turned off using PassFailUse.																										
	You have to check if bValid = True before reporting or using the returned value.																										
Example	To check whether terminal 3 of port 1 has passed the test:																										
	<pre data-bbox="612 1510 1305 1668">Dim bTPass, bValid as Boolean bTPass=m_SpectralJitterCTRL.GetTermPassValue(1, 3, AT_AllAnalysis, &bBool);</pre>																										
Related functions and methods	"GetMeasPassValue" on page 94 "GetTermPassValue" on page 98 "PassFailUse" on page 51																										

Copy/Paste Functions

The following table gives an overview on the methods, events and properties available to cut, copy and delete measurement results:

Purpose	Refer to...
To copy data to the clipboard.	<i>"CopyToClipboard" on page 101</i>
To cut data from the measurement and copy the data to the clipboard.	<i>"CutToClipboard" on page 102</i>
To delete data from the numerical view.	<i>"EditDelete" on page 103</i>
To determine whether a copy function call is possible.	<i>"IsCopyAvailable" on page 104</i>
To determine whether a cut function call is possible.	<i>"IsCutAvailable" on page 105</i>
To determine whether a delete function call is possible.	<i>"IsEditDeleteAvailable" on page 106</i>
To determine whether a paste function call is possible.	<i>"IsPasteAvailable" on page 107</i>
To insert data previously copied to the clipboard.	<i>"PasteFromClipboard" on page 108</i>

CopyToClipboard

ActiveX syntax Object.CopyToClipboard(boolean)

NOTE This method is not available for the wrapper dll.

Description Copies the measurement window and the data of the numerical view to the clipboard.

To get the information from the clipboard, use *Paste Special* and then select *Enhanced Metafile* to get the graphics, *Unformatted Text* to get the data stored in the grid as comma delimited ASCII text, *HTML Format* to get the grid in HTML format. *Paste* gets the data displayed in the grid in HTML format.

In addition, data is stored in the clipboard in a format specific to the measurement software that can be returned using the *PasteFromClipboard* method.

Use the *IsCopyAvailable* method to determine if a copy operation can be performed before calling *CopyToClipboard*.

Input parameter **boolean** The following constants (data type: Boolean) are defined:

Constant	Description
True	The clipboard is cleared and the measurement window is copied to the clipboard. In addition, the measurement data in the numerical view is copied to the clipboard.
False	The clipboard is not cleared. However, the measurement window and measurement data are copied to the clipboard. Prior to this call, if there is other data formats in the clipboard, they will remain in the clipboard.

Example To clear the clipboard and copy measurement data to it:

```
m_SpectralJitterCTRL.CopyToClipboard(True)
```

Related functions and methods *CutToClipboard* on page 102
 PasteFromClipboard on page 108
 IsCopyAvailable on page 104

CutToClipboard

ActiveX syntax Object.CutToClipboard(boolean)

NOTE This method is not available for the wrapper dll.

Description Cuts data from the measurement and copies the data into the clipboard. To get the information from the clipboard, use *Paste Special* and then select *Enhanced Metafile* to get the graphics, *Unformatted Text* to get the data stored in the grid as comma delimited ASCII text, *HTML Format* to get the grid in HTML format. Paste returns the data displayed in the grid as HTML.

In addition, data is stored in the clipboard in a format specific to the measurement software that can be returned using the *PasteFromClipboard* method.

Use the *IsCutAvailable* method to determine if a cut operation can be performed before calling *CutToClipboard*.

Input parameter **boolean** The following constants (data type: Boolean) are defined:

Constant	Description
True	The clipboard is cleared out and the measurement window is copied to the clipboard. In addition the measurement data in the grid is copied into the clipboard.
False	The clipboard is not cleared out, however the measurement window and measurement data are copied into the clipboard. Prior to this call, if there is other data formats in the clipboard, they will remain in the clipboard.

Example To clear the clipboard, remove data from the measurement and copy the data to the clipboard:

```
m_SpectralJitterCTRL.CutToClipboard(True)
```

Related functions and methods *“CopyToClipboard” on page 101*
 “IsCutAvailable” on page 105

EditDelete

ActiveX syntax Object.EditDelete(boolean)

NOTE This method is not available for the wrapper dll.

Description Deletes copied data in the grid. What is deleted depends on where the focus is. If there is no focus then nothing is deleted. If there is focus on the copied data line then this data will be deleted.

Use the `IsEditDeleteAvailable` method to determine if deleting is possible before calling `EditDelete`.

Input parameter **boolean** The following constants (data type: Boolean) are defined:

Constant	Description
True	Deletes copied data.
False	Reserved for future use.

Example To delete copied data from the numerical view of the measurement:

```
m_SpectralJitterCTRL.EditDelete(True)
```

Related functions and methods *"IsEditDeleteAvailable" on page 106*

IsCopyAvailable

ActiveX syntax bCopy = Object.IsCopyAvailable()

NOTE This method is not available for the wrapper dll.

Description Returns whether a copy function can be called.

Output parameter **bCopy** The following constants (data type: Boolean) are defined:

Constant	Description
True	Copy is a valid operation to call
False	Copy is not a valid operation to call.

Example To check whether a copy operation is possible:

```
Dim bCopy as Boolean  
bCopy = m_SpectralJitterCTRL.IsCopyAvailable()
```

Related functions and methods *“IsCutAvailable” on page 105*

IsCutAvailable

ActiveX syntax `bCut = Object.IsCutAvailable()`

NOTE This method is not available for the wrapper dll.

Description Returns whether a cut function can be called.

Output parameter **bCut** The following constants (data type: Boolean) are defined:

Constant	Description
True	Cut operation can be called.
False	Cut operation can not be called.

Example To check whether a cut operation is possible:

```
Dim bCut as Boolean  
bCut = m_SpectralJitterCTRL.IsCutAvailable()
```

Related functions and methods *"IsCopyAvailable" on page 104*

IsEditDeleteAvailable

ActiveX syntax `bDelete = Object.IsEditDeleteAvailable()`

NOTE This method is not available for the wrapper dll.

Description Returns whether a delete function can be called.

Output parameter **bDelete** The following constants (data type: Boolean) are defined:

Constant	Description
True	Delete is a valid operation to call.
False	Delete is not a valid operation to call.

Example To check whether a delete operation is possible:

```
Dim bDelete as Boolean  
bDelete = m_SpectralJitterCTRL.IsEditDeleteAvailable()
```

IsPasteAvailable

ActiveX syntax `bPaste = Object.IsPasteAvailable()`

NOTE This method is not available for the wrapper dll.

Description Returns whether a paste function can be called. If there is anything on the clipboard, this function returns True.

Output parameter **bPaste** The following constants (data type: Boolean) will be returned:

Constant	Description
True	Paste operation can be called.
False	Paste operation can not be called.

Example To check whether a paste operation is possible:

```
Dim bPaste as Boolean  
bPaste = m_SpectralJitterCTRL.IsPasteAvailable()
```

Related functions and methods *"IsCutAvailable" on page 105*
"IsCopyAvailable" on page 104

PasteFromClipboard

ActiveX syntax `Object.PasteFromClipboard(boolean)`

NOTE This method is not available for the wrapper dll.

Description Pastes information into the grid. What is pasted depends on what was selected during the copy operation:

- If there is no focus during the copy operation, the paste will copy all of the rows into the grid.
- If the focus was on the measurement line, the paste will copy all of the rows into the grid.
- If the focus was on an individual port, only that port will be pasted.
- If the focus was on an individual terminal, only the terminal will be pasted.

Before calling `PasteFromClipboard`, use `IsPasteAvailable` to determine if a paste operation can be performed.

Input parameter **boolean** The following constants (data type: Boolean) are defined:

Constant	Description
True	Copies the information from the clipboard and then clears the clipboard.
False	Copies the information from the clipboard. The information remains in the clipboard.

Related functions and methods

[“CopyToClipboard” on page 101](#)

[“CutToClipboard” on page 102](#)

Persistence

The following section shows the functions used to load/save measurements and to export data from the measurements.

Functions to Load/Save Measurements

The following table gives an overview on the methods, events and properties available to get and calculate measurement results:

Purpose	Refer to...
To load a stored measurement.	<i>"LoadMeasurement" on page 111</i>
To save a measurement.	<i>"SaveMeasurement" on page 110</i>

Export Data from Measurements

The following table gives an overview on the methods, events and properties available to export measurement results:

Purpose	Refer to...
To export data to the clipboard or to a file.	<i>"ExecuteExport" on page 112</i>
To set the delimiter for the data export.	<i>"ExportDelimiter" on page 113</i>
To set the file name the data will be exported to.	<i>"ExportFileName" on page 114</i>
To set the date format for export.	<i>"ExportLocale" on page 115</i>
To specify if the results will be exported to file or clipboard.	<i>"ExportToClipboard" on page 116</i>

SaveMeasurement

ActiveX syntax Object.SaveMeasurement(sFileName)

Wrapper dll syntax SPECJITSaveMeasurement(hMeasurement,
 sFileName)

Description Saves the measurement into a designated file.

Input parameters **hMeasurement** Only for the wrapper dll: Handle to the measurement created by InitMeasurement (data type: ViSession).

sFileName Full path and name of the stored measurement file (data type: String). The MUI application stores these files with an extension of .mcp.

Example To save the measurement DUTSpectralJitter.mcp:

```
m_SpectralJitterCTRL.SaveMeasurement  
( "C:\\Temp\\\\DUTSpectralJitter.mcp" )
```

LoadMeasurement

ActiveX syntax Object.LoadMeasurement(sFileName)

Wrapper dll syntax SPECJITLoadMeasurement(hMeasurement,
 sFileName)

Description Loads the measurement stored in the designated file into the control.

Input parameters **hMeasurement** Only for the wrapper dll: Handle to the
measurement created by InitMeasurement (data type: ViSession).

sFileName Full path and name of the stored measurement file
(data type: String). The MUI application stores these files with the
extension .mcp.

Example To load the measurement DUTSpectralJitter.mcp:

```
m_SpectralJitterCTRL.LoadMeasurement  
( "C:\\\\Temp\\\\DUTSpectralJitter.mcp" )
```

ExecuteExport

ActiveX syntax Object.ExecuteExport()

Wrapper dll syntax SPECJITEExecuteExport(hMeasurement)

Description Exports the measurement data to the clipboard or to a file. The format of the export is determined by the Export properties: ExportLocale, ExportDelimiter, ExportFileName, ExportToClipboard.

Input parameter **hMeasurement** Only for the wrapper dll: Handle to the measurement created by InitMeasurement (data type: ViSession).

Example m_SpectralJitterCTRL.ExecuteExport

Related functions and methods *“ExportLocale” on page 115*
 “ExportDelimiter” on page 113
 “ExportFileName” on page 114
 “ExportToClipboard” on page 116

ExportDelimiter

ActiveX syntax Object.ExportDelimiter = [sDelimiter]

For Visual C:

```
Object.SetExportDelimiter(sDelimiter)  
sDelimiter = Object.GetExportDelimiter()
```

Wrapper dll syntax SPECJITGetExportDelimiter(hMeasurement,
 bufferSize,
 *sDelimiter)
SPECJITSetExportDelimiter(hMeasurement,
 sDelimiter)

Description Sets/returns the delimiter for export.

Input parameters **hMeasurement** Only for the wrapper dll: Handle to the measurement created by InitMeasurement (data type: ViSession).

bufferSize Only for the wrapper dll: Specifies the size of the data buffer for the returned data (data type: ViInt32).

sDelimiter The delimiter (data type: String) that will be used between data elements in the export. The delimiter can be a space, tab or any writable character, for example, "," or "~". For the wrapper dll GET function, this parameter is a pointer.

Example To set the delimiter between the data to "^":

```
m_SpectralJitterCTRL.ExportDelimiter = "^"
```

Related functions and methods *"ExecuteExport" on page 112*
"ExportFileName" on page 114
"ExportLocale" on page 115
"ExportToClipboard" on page 116

ExportFileName

ActiveX syntax Object.ExportFileName = [sFileName]

For Visual C:

```
Object.SetExportFileName(sFileName)  
sFileName = Object.GetExportFileName()
```

Wrapper dll syntax SPECJITGetExportFileName(hMeasurement,
 bufferSize,
 *sFileName)
SPECJITSetExportFileName(hMeasurement,
 sFileName)

Description Sets/returns the file name and the directory data will be exported to.

Input parameters **hMeasurement** Only for the wrapper dll: Handle to the measurement created by InitMeasurement (data type: ViSession).

bufferSize Only for the wrapper dll: Specifies the size of the data buffer for the returned data (data type: ViInt32).

sFileName Directory and name of the file that data will be exported to (data type: String). For the wrapper dll GET function, this parameter is a pointer.

Example To export data to the file "C:\\Temp\\export.txt":

```
m_SpectralJitterCTRL.ExportFileName = "C:\\Temp\\export.txt"
```

Related functions and methods *"ExecuteExport" on page 112*
"ExportDelimiter" on page 113
"ExportLocale" on page 115
"ExportToClipboard" on page 116

ExportLocale

ActiveX syntax Object.ExportLocale = [sLocale]

For Visual C:

```
Object.SetExportLocale(sLocale)  
sLocale = Object.GetExportLocale()
```

Wrapper dll syntax SPECJITGetExportLocale(hMeasurement,
 bufferSize,
 *sLocale)
SPECJITSetExportLocale(hMeasurement,
 sLocale)

Description Sets the language for the export which will define the date format and the default delimiter.

Input parameters **hMeasurement** Only for the wrapper dll: Handle to the measurement created by InitMeasurement (data type: ViSession).

bufferSize Only for the wrapper dll: Specifies the size of the data buffer for the returned data (data type: ViInt32).

sLocale Name of the language that the export format will default to. This will define the date format and the default delimiter (data type: String). For the wrapper dll GET function, this parameter is a pointer.

Related functions and methods *"ExecuteExport" on page 112*
"ExportDelimiter" on page 113
"ExportFileName" on page 114
"ExportToClipboard" on page 116

ExportToClipboard

ActiveX syntax Object.ExportToClipboard = [boolean]

For Visual C:

```
Object.SetExportToClipboard(boolean)
boolean = Object.GetExportToClipboard()
```

Wrapper dll syntax

SPECJITGetExportToClipboard(hMeasurement,	*boolean)
SPECJITSetExportToClipboard(hMeasurement,	
	boolean)

Description Sets whether the export will go to the clipboard or not.

Input parameters **hMeasurement** Only for the wrapper dll: Handle to the measurement created by InitMeasurement (data type: ViSession).

boolean The settings for boolean (data type: Boolean) are:

Constant	Description
True	Turns on the export to the clipboard.
False	Turns off the export to the clipboard (default setting). Data will be exported to file.

For the wrapper dll GET function, this parameter is a pointer.

Example To export data to the clipboard:

```
m_SpectralJitterCTRL.ExportToClipboard = True
```

Related functions and methods

- “*ExecuteExport*” on page 112
- “*ExportDelimiter*” on page 113
- “*ExportFileName*” on page 114

Functions for General Purposes

The following sections show the functions used to access the online help, for example.

The following table gives an overview on the methods, events and properties available:

Purpose	Refer to...
To set the background color of the graphical view.	"BackColor" on page 118
To set the color of the noise threshold marker.	"PowerMarkerColor" on page 123
To set the color of frequency ranges.	"FrequencyRangesColor" on page 120
To set the text color of the graphical display.	"ForeColor" on page 119
To set/return the name and the path of the help file.	"MeasHelpPath" on page 121
To set the help id for the measurement window.	"MeasureWinHelp" on page 122

BackColor

ActiveX syntax Object.BackColor = [nColor]

For Visual C:

```
Object.SetBackColor(nColor)
nColor = Object.GetBackColor()
```

NOTE This property is not available for the wrapper dll.

Description Sets/returns the color of the background of the graphical view.

Parameter **nColor** Sets the background color (data type: integer). The following table lists typical color values:

Color	RGB Values	nColor Value
White	255, 255, 255	16777215
Black	0, 0, 0	0
Gray	192, 192, 192	12632256
Dark gray	128, 128, 128	8421504
Red	255, 0, 0	255
Dark red	128, 0, 0	128
Yellow	255, 255, 0	65535
Dark yellow	128, 128, 0	32896
Green	0, 255, 0	65280
Dark green	0, 128, 0	32768
Cyan	0, 255, 255	16776960
Dark cyan	0, 128, 128	8421376
Blue	0, 0, 255	16711680
Dark blue	0, 0, 128	8388608
Magenta	255, 0, 255	16711935
Dark magenta	128, 0, 128	8388736

Example To set the background color of the graphical view to "Blue":

```
m_SpectralJitterCTRL.BackColor = 16711680
```

ForeColor

ActiveX syntax `Object.ForeColor = [nColor]`

For Visual C:

```
Object.SetForeColor(nColor)
nColor = Object.GetForeColor()
```

NOTE This property is not available for the wrapper dll.

Description Sets the color of the foreground (text) on the graph.

Input parameter **nColor** Sets the foreground color (data type: integer). The following table lists typical color values:

Color	RGB Values	nColor Value
White	255, 255, 255	16777215
Black	0, 0, 0	0
Gray	192, 192, 192	12632256
Dark gray	128, 128, 128	8421504
Red	255, 0, 0	255
Dark red	128, 0, 0	128
Yellow	255, 255, 0	65535
Dark yellow	128, 128, 0	32896
Green	0, 255, 0	65280
Dark green	0, 128, 0	32768
Cyan	0, 255, 255	16776960
Dark cyan	0, 128, 128	8421376
Blue	0, 0, 255	16711680
Dark blue	0, 0, 128	8388608
Magenta	255, 0, 255	16711935
Dark magenta	128, 0, 128	8388736

Example To set the text color of the graphical view to "Black":

```
m_SpectralJitterCTRL.ForeColor = 0
```

Related functions and methods *"BackColor" on page 118*

FrequencyRangesColor

ActiveX syntax Object.FrequencyRangesColor = [nColor]

For Visual C:

```
Object.SetFrequencyRangesColor(nColor)
nColor = Object.GetFrequencyRangesColor()
```

NOTE This property is not available for the wrapper dll.

Description Sets/returns the color of enabled frequency ranges.

Parameter **nColor** Sets the color frequency ranges (data type: integer). The following table lists typical color values:

Color	RGB Values	nColor Value
White	255, 255, 255	16777215
Black	0, 0, 0	0
Gray	192, 192, 192	12632256
Dark gray	128, 128, 128	8421504
Red	255, 0, 0	255
Dark red	128, 0, 0	128
Yellow	255, 255, 0	65535
Dark yellow	128, 128, 0	32896
Green	0, 255, 0	65280
Dark green	0, 128, 0	32768
Cyan	0, 255, 255	16776960
Dark cyan	0, 128, 128	8421376
Blue	0, 0, 255	16711680
Dark blue	0, 0, 128	8388608
Magenta	255, 0, 255	16711935
Dark magenta	128, 0, 128	8388736

Example To set the color of frequency ranges to "Green":

```
m_SpectralJitterCTRL.FrequencyRangesColor = 65280
```

MeasHelpPath

ActiveX syntax Object.MeasHelpPath = [sHelpPath]

For Visual C:

```
Object.SetMeasHelpPath(sHelpPath)  
sHelpPath = Object.GetMeasHelpPath()
```

NOTE This property is not available for the wrapper dll.

Description Sets/returns the default help file name.

Parameter **sHelpPath** Full path and name of help file (data type: String).

Example To set the path to the help file to "C:\Temp\tmSpectralJitterM.chm":

```
m_SpectralJitterCTRL.MeasHelpPath =  
"C:\\Temp\\\\tmSpectralJitterM.chm"
```

MeasureWinHelp

ActiveX syntax Object.MeasureWinHelp(lWndHandle,
 sHelpPath,
 lCommand,
 lData)

NOTE This method is not available for the wrapper dll.

Input parameters **IWndHandle** Window handle for the parent window
(data type: Long).

sHelpPath Path and name of the controls help file
(data type: String). The file must have a ".chm" extension. Can be obtained using the MeasHelpPath property.

lCommand Value should be set to 1 for context help support
(data type: Long). Not supporting any other help at this time.

lData Default control help ID, 131172 (data type: Long).

Example To call the online help with the default help id:

```
Dim helpstr as String
Dim helpID as Long
Dim frmMain as Form
helpstr = m_SpectralJitterCTRL.MeasHelpPath
helpID = m_SpectralJitterCTRL.DefaultHelpID
m_SpectralJitterCTRL.MeasureWinHelp(frmMain.hWnd, helpstr, 1,
helpID)
```

Related functions and methods *"MeasHelpPath" on page 121*

PowerMarkerColor

ActiveX syntax Object.PowerMarkerColor = [nColor]

For Visual C:

```
Object.SetPowerMarkerColor(nColor)
nColor = Object.GetPowerMarkerColor()
```

NOTE This property is not available for the wrapper dll.

Description Sets/returns the color of the noise threshold marker.

Parameter **nColor** Sets the noise power threshold marker color (data type: integer). The following table lists typical color values:

Color	RGB Values	nColor Value
White	255, 255, 255	16777215
Black	0, 0, 0	0
Gray	192, 192, 192	12632256
Dark gray	128, 128, 128	8421504
Red	255, 0, 0	255
Dark red	128, 0, 0	128
Yellow	255, 255, 0	65535
Dark yellow	128, 128, 0	32896
Green	0, 255, 0	65280
Dark green	0, 128, 0	32768
Cyan	0, 255, 255	16776960
Dark cyan	0, 128, 128	8421376
Blue	0, 0, 255	16711680
Dark blue	0, 0, 128	8388608
Magenta	255, 0, 255	16711935
Dark magenta	128, 0, 128	8388736

Example To set the color of the noise threshold marker to "Green":

```
m_SpectralJitterCTRL.PowerMarkerColor = 65280
```


Index

A

Absolute 67
AcquisitionDepth 35
AnalyzerSystem 12
AnalyzerSystemSetting 13

B

BackColor 118

C

CloseMeasurement 14
CopyToClipboard 101
CreateMeasEx 15
CreateMeasurementEx 16
CutToClipboard 102

D

DataAvailable 84
DelayStartSystem 18
DisplayPowerUnits 36
Download 69

E

EditDelete 103
ExecuteExport 112
ExportDelimiter 113
ExportFileName 114
ExportLocale 115
ExportToClipboard 116

F

FFTWindow 37
FFTWindowList 38
ForeColor 119
FreqAxisRangeType 39
FreqRange 40
FreqRangeEnable 42
FrequencyRangesColor 120

G

GeneratorSystem 19
GeneratorSystemSetting 20
GetAnalyzerPortCount 43
GetAnalyzerPortName 44
GetAnalyzerSettingsCount 21
GetAnalyzerSettingsName 22

GetAnalyzerTermCount 45
GetAnalyzerTermName 46
GetGeneratorSettingsCount 23
GetGeneratorSettingsName 24
GetLastMeasError 81
GetMeasFreqPrecision 85, 86
GetMeasPassValue 94
GetPortId 47
GetPortInvolved 56
GetPortPassValue 96
GetTermCalculatedValue 90
GetTerminalID 48
GetTermInvolved 65
GetTermPassValue 98
GetTopFreqPowerValue 92
GridPrecision 49

I

InitMeasurement 25
IsCopyAvailable 104
IsCutAvailable 105
IsEditDeleteAvailable 106
IsFWSConnected 26
IsPasteAvailable 107

L

LoadMeasurement 111

M

MeasHelpPath 121
MeasState 70
MeasurementType 27
MeasureWinHelp 122

N

NoiseThreshold 50

O

OnMeasDataAvailable 75
OnMeasurementComplete 76
OnMeasurementState 77

P

PassFailUse 51
PassFailValue 53
PassFailValuePower 54
PasteFromClipboard 108

PortInvolved 56
PowerMarkerColor 123
PropertiesTitle 57

R

Relative to frequency 67
RelativeReferenceFrequency 58
Run 71

S

SamplePointOffset 59
SaveMeasurement 110
Scale 60
Server 28
ServerPort 29
SetFreqAxisRange 61
SetMeasEventsCallback 79
SetPortInvolved 56
SetTermInvolved 65
ShowGrid 62
ShowMarkers 63
ShowProperties 64
SilentMode 82
StartDelay 30
Stop 72
SynchronousRun 73

T

TermInvolved 65
TopFrequencyCount 66
True relative 67

U

UseAnalyzerSettings 31
UseGeneratorSettings 32

V

ViewType 67

Copyright Agilent Technologies 2003
Printed in Germany May 2003



5988-9645EN



Agilent Technologies