

S E R V I C E N O T E

SUPERSEDES: None

10889B PC Servo-Axis Board

Serial Numbers: 0000A00000 / 3332A00432

Address switch S2 may have insufficient solder on some pins, resulting in intermittent address response when programming board.

To Be Performed By: Agilent-Qualified Personnel

Parts Required:

Part No.	Description
10889-13401	Program disk
10889-90006	Operating Manual

Situation:

Some boards have been found with insufficient solder on the pins of the address switch S2. The result can be intermittent, unusual, or non-repeating response from the board.

Solution/Action:

Inspect switch S2 for proper solder wetting. The problem may be fixed by resoldering all of the S2 pins. Switch S2 is shown on page 2-8 of the 10889-90006 manual and located at the bottom of the board near the empty row of pins on the backplane connector.

To test the board, you will need a PC/AT and software part # 10889-13401. Find the address setting for S2 on page 2-8, load the board into the PC, and run the READREV program under the HP89UTL director. The program will ask you for the board address, and the board should respond to the program.

DATE: July 1995

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input checked="" type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS:	Labor 0.5 hrs
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input checked="" type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	USED PARTS:	<input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AUTHOR: GM	ENTITY: 5500	AGILENT RESPONSIBLE UNTIL: July 1998	
		ADDITIONAL INFORMATION:	