

MODIFICATION RECOMMENDED –
CORRECTS MANUFACTURING OR DESIGN DEFECTS

SN 34908A-04B

S E R V I C E N O T E

Supersedes:
34908A-04A

34908A 40-Channel Single-Ended Multiplexer

Serial Numbers: <http://www.agilent.com/find/tempcardproblem>

The Problem – 34908A temperature measurements out of specification

To Be Performed By: Agilent-Qualified Personnel or Customer

Parts Required: Refer to the required equipments below

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input checked="" type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS: LABOR: 1.0 Hours	
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY: <input checked="" type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT	USED PARTS: <input checked="" type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: June 1, 2007	
AUTHOR: TP PRODUCT LINE: PLSP-SOURCE_MEAS			
ADDITIONAL INFORMATION:			

© AGILENT TECHNOLOGIES, INC. 2006
PRINTED IN U.S.A.



September 28, 2006

Situation:

It was discovered that the module cards 34908A were incorrectly calibrated in production. Inaccurately calibrated temperature sensors on these cards will cause thermocouple measurement error only using the internal temperature reference to exceed published specifications.

The mis-calibration only affects thermocouple measurements that use the internal reference, but do not affect thermocouple measurements using external and fixed temperature references. Other measurements such as voltage, resistance and current are not affected by the issue.

Solution/Action:Test and, if necessary, calibrate:

- All units within the described serial number ranges will exhibit the described problem with one exception. If a calibration has been performed on your card after it was shipped from Agilent, a second calibration is not necessary.

Test Equipment Required:

- J type calibrated thermocouple with 0.1 degree C or better accuracy
- Ice bath or Fluke 5520A Calibrator or equivalent

Test Procedure:

- Follow the procedures in section “Thermocouple Reference Junction Verification” on page 112 of the 34970A Service Guide manual

Calibration Equipment Required:

- One 34308A thermistor kit

Calibration Procedure:

- To perform your own calibration, follow the procedures in section “Thermocouple Reference Junction Adjustments” on page 113 of the 34970A Service Guide manual
- To request that Agilent calibrate your product, contact your local Agilent service center
 - **Note:** No calibration certificate will be provided