

MODIFICATION RECOMMENDED

34939A-01A

S E R V I C E N O T E

Supersedes: 34939A-01

34939A 64-Channel High Density Form-A GP Switch Module

Serial Numbers: MY44000621 – MY4400778

Relays may have contaminated contacts that can cause intermittent contact resistance in excess of 100 ohms.

Parts Required:

P/N 34939-60001 **Description** replacement 34939A module **Qty.** 1

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	<input checked="" type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS	LABOR: 0.5 Hours
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER <input type="checkbox"/> CHANNEL PARTNER	SERVICE INVENTORY: <input checked="" type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT	USED PARTS: <input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input checked="" type="checkbox"/> SEE TEXT
AVAILABILITY:	April 25, 2012	NO CHARGE AVAILABLE June 05, 2013	
<input type="checkbox"/> Calibration Required <input checked="" type="checkbox"/> Calibration NOT Required		PRODUCT LINE: BL AUTHOR: TP	
ADDITIONAL INFORMATION: Used parts are to be returned to factory for failure analysis.			

© AGILENT TECHNOLOGIES, INC. 2013
PRINTED IN U.S.A.

June 7, 2013

Rev. 19



Situation:

The relays (dark blue) used in these 34939A modules may have sulfide contaminated contacts that can cause intermittent contact resistance in excess of 100 ohms on the 64 form A channels.

Solution/Action:

If these symptoms are observed, contact Agilent Service for a replacement.

Revision History:

Revision Number	Date	Author	Reason For Change
2.0	6/7/13	TP	Updated Used Parts requirement