S E R V I C E N O T E

SUPERSEDES: 37743A-01

HP 37743A DS3 Test Set

Serial Numbers: 3206U00147 / 3206U00195

Modification to correct incorrectly loaded capacitor on the transmitter board

Note:

The following units are already modified:

3206U00158, 174, 176/179, 182/195.

Situation:

C56 has been incorrectly loaded on the transmitter board and should be replaced on servicing with HP p/n 0180-0648, 0.1uf 35V. The artwork on the board indicating the polarity of this capacitor is wrong. After taking appropriate static precautions, carry out the following steps.

- 1. Remove rear rubber bumpers.
- 2. Remove screw from rear center of the outside cover.
- 3. Remove feet.
- 4. Remove the outside cover by sliding it back from the rear of the instrument.
- 5. Remove the fiberglass board retaining brackets.
- 6. Remove the transmitter board, 3rd from the rear of the instrument.

Continued

DATE: 14 May 1993

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
MODIFICATION RECOMMENDED		
ACTION CATEGORY:	☐ IMMEDIATELY ☐ ON SPECIFIED FAILURE ■ AGREEABLE TIME	STANDARDS: LABOR: 0.5 Hours
LOCATION CATEGORY:	☐ CUSTOMER INSTALLABLE☐ ON-SITE☐ HP LOCATION	SERVICE RETURN USED RETURN INVENTORY: SCRAP SEE TEXT SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	RESPONSIBLE UNTIL : 01 January 1994
AUTHOR: GS	ENTITY: 1400	ADDITIONAL INFORMATION:

© 1993 HEWLETT-PACKARD COMPANY PRINTED IN U.S.A.



Page 2 SERVICE NOTE 37743A-01A

7. Locate C56, located on lower left hand side viewed from the component side of the board.

- 8. If the capacitor is installed with its positive end connected to the square pad on the PC board, then it should be replaced connecting it in reverse polarity.
- 9. If the capacitor has been replaced already, take no further action.
- 10. Re-insert the transmitter board, taking great care to align the connectors with those on the motherboard.
- 11. Re-assemble the instrument using the reverse procedure.
- 12. Power up the instrument and ensure that the self-test is carried out successfully.