SERVICE NOTE

SUPERSEDES:

HP MODEL 3960 TAPE RECORDER

Serial	Number	1040A-00601
11	67	1040A-00599
*1	ŧŧ	1040A-00597
11	H	1040A-00595
		and helow

A15 Power Supply Assembly HP Part Number 03960-60130

A15 POWER SUPPLY RESISTOR CHANGE

There has been an inadvertent interchange of Resistor R11 and R12 on the A15 Power Supply assembly. This discrepancy could possibly cause a failure of the -12 VDC Power Supply line.

R12, a 2.15K resistor, should be connected to the base lead of Q6 and resistor R11, a 680 ohm resistor, should be connected to the collector lead of Q6 for correct operation. Refer to the A15 Power Supply schematic supplied in the "3960 Service Manual." Also, see Figure 1 of this Service Note for correct location of parts.

PARTS AFFECTED:

Quantity	Description	HP Part No.
1	A15R11, 681 ohm 1/8 W %	0757-0419
1	A15R12, 2.15K ohm 1/2 W %	0698-0084

CORRECT INSTALLATION PROCEDURE:

Gain access to the Al5 Power Supply assembly. Refer to the Repair and Replacement section of the "3960 Service Manual." Remove resistors R11 and R12 and interchange them. Refer to Illustrated Parts section and the Schematic

* *

-over-

BW/ps/WA

1/71-42



For more information, call your local MP Sales Office or East (201) 265-5008 n Midwest (312) 677-8408 + South (494) 436-4181 West (213) 877-1282. Or, write: Hewlett-Packard, 1501 Page Mill Road, Palo Alto, California 94308. In Europe, 1217 Mayrin-Geneva

Printed in U B A

1

,4

diagram section of the service manual. Locate the figures which contain the component location of the Al5 Power Supply assembly and make the necessary changes to reflect the correct location of R11 and R12. The wiring diagram and material lists are correct.




FIGURE 1 - A15 Power Supply Assembly