

SAFETY – IMPLEMENTED DURING NORMAL COURSE  
OF PROVIDING SUPPORT

**4294A-02A-S**

# **S E R V I C E N O T E**

Supersedes:  
4294A-02-S

## **Agilent 4294A Precision Impedance Analyzer**

Serial Numbers: JP1KG00101/JP2KG00588

### **POSSIBLE ELECTRIC SHOCK HAZARD**

**WARNING**

**HAZARD CLASS #3**

**A broken AC inlet may potentially result in an electric shock hazard.**

#### **Parts Required:**

<b>P/N</b>	<b>Description</b>	<b>Qty.</b>
04294-00213	Rear Panel	1
2110-1303	Fuse	1

### **ADMINISTRATIVE INFORMATION**

SERVICE NOTE CLASSIFICATION:		
<b>SAFETY</b>		
ACTION CATEGORY: <b>IMMEDIATELY</b>	STANDARDS LABOR: Solution #1 (0.5 hours) ; Solution #2 (2.0 hours)	
LOCATION CATEGORY: <input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER <input type="checkbox"/> CHANNEL PARTNER	SERVICE INVENTORY: <input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT	USED PARTS: <input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY: ALWAYS	NO CHARGE AVAILABLE UNTIL: ALWAYS	
AUTHOR: LS	PRODUCT LINE: WN	
ADDITIONAL INFORMATION: 02G Repair Class		

© AGILENT TECHNOLOGIES, INC. 2012  
PRINTED IN U.S.A.


February 28, 2012

Rev. 21



**Situation:**

The AC inlet (P/N 1252-6951) has the potential to slip out of the instrument's rear panel slot if the AC power cord is forcefully pulled in a diagonal direction. When this happens, an exposed connection on the AC inlet module may touch the rear panel of the instrument and cause an electrical short if the AC power cord is still connected to the AC power outlet. See Figure 1.



**Figure 1. AC Inlet Connector**

In the worst case, there is also a possibility of an electric shock hazard to the user if the user completes a circuit between the instrument panel and another grounded connection while the AC power cord is still connected to the AC power outlet.

**Solution/Action:**

There are two possible solutions; one if the AC inlet is still seated in the instrument's rear panel, and a second if the AC inlet has been yanked out of the slot.

Replacement instructions in HTML format are available over the Agilent Intranet at URL [http://kobemktg.jpn.agilent.com/field\\_eng/](http://kobemktg.jpn.agilent.com/field_eng/) (CT-PGU Kobe Service Information)

Click on "Service FAQ", click on "AC Inlet".


[http://kobemktg.jpn.agilent.com/field\\_eng/service/faq/ac-inlet/index.htm](http://kobemktg.jpn.agilent.com/field_eng/service/faq/ac-inlet/index.htm)

**Solution 1. AC Inlet Still Intact.**

Since the required silicon seal P/N: 5183-4112 is obsolete, please proceed with "Solution2" by changing the whole rear panel assembly.

**Solution 2. AC Inlet Broken**

- Remove the AC power cable from the AC power outlet and the product.
- Remove the top, bottom, and side covers.
- Replace the rear panel assembly with P/N 04294-00213.
- Install the new fuse P/N 2110-1303.
- Perform Self Test to verify instrument operation.



**Fig. 2**

**Figure 2. Repair Completed Label**