S E R V I C E N O T E

SUPERSEDES

HP 4982A Network Advisor

Serial Numbers: 0000A00000/9999A99999

J2176A / Mainframe

Duplicate Service Notes: 4980A-07 and 4981A-07

Upgrading Hard Disk Drive to 105 MByte

Part Required:

HP P/N

Description

Qty U.S. List

0950-2173

105 MByte HD Drv

1 \$1000.00

Situation:

This will allow a network advisor with a 52 MByte Hard Disk drive to be upgraded to a 105 MByte Hard Drive.

Note

Take static precautions when handling these parts.

Continued

DATE: 26 May 1992

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION: MODIFICATION AVAILABLE			
LOCATION CATEGORY:	CUSTOMER INSTALLABLE ON-SITE HP LOCATION	AVAILABLE UNTIL: Product's Support Life	
AUTHOR: R.C.B.	ENTITY: 3800	ADDITIONAL INFORMATION:	

© 1992 HEWLETT-PACKARD COMPANY PRINTED IN U.S.A.



Page 2 Service Note 4982A-07

Solution/Action:

Use the 498X service manual, section 15, for reference in removing and installing the hard disk drive.

Procedure:

- 1. Remove the top cover to expose the internal parts of the network advisor.
- Locate the Hard Disk drive in the right rear corner of the chassis and follow the
 procedures in the service manual to remove the Hard Disk Drive from the chassis.
 Replace the 52 MByte drive with the 105 MByte drive.
- 3. Replace the 52 MByte drive with the 105 MByte drive.
- 4. Use the procedures in the service manual to install the new disk drive.

Once the new hard drive installation has been completed, the hard drive can be formatted and the network advisor software can be loaded. Follow the procedures in section 11 of the service manual to load the software.

Note

After installing the new hard disk drive the system configuration must be changed. When powering up the instrument and the RAM is done being tested, press CTRL-ALT-S to access the system configuration. Change the C drive type from 41 to 42. Press F10 softkey, this will save the new configuration and reboot the system.