S E R V I C E N O T E

SUPERSEDES: None

54601A Oscilloscope Option 002

Serial Numbers: 0000A00000 / 3134A99999

Test failure:

Fails to pass test listed below under Solution/Action.

Duplicate Service Notes:

54600A-06 54601A-06

Situation:

Due to an inadequate coating on a small number of filters used in the option #002, there may be a few installations that do not attenuate the display emitted signal to the required level.

Solution/Action:

Determine if you have a unit that may have inadequate filter coating.

- 1. Perform a key-down power-up retest.
- 2. Attach a 10:1 probe (10071A) with grabber to channel 1.
- 3. Move the grabber probe tip across the front of display and verify the signal on screen is less than or equal to 1 minor division.

Continued

DATE: 24 June 1992

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
MODIFICATION RECOMMENDED		
ACTION CATEGORY:	☐ IMMEDIATELY ☐ ON SPECIFIED FAILURE ☐ AGREEABLE TIME	STANDARDS: Labor 0.50 Hour
LOCATION CATEGORY:	☐ CUSTOMER INSTALLABLE☐ ON-SITE☐ SERVICE CENTER	SERVICE RETURN USED RETURN INVENTORY: SCRAP PARTS: SCRAP SEE TEXT SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: 01 July 1994
AUTHOR: NCW	ENTITY: 0800	ADDITIONAL INFORMATION:

© 1992 AGILENT TECHNOLOGIES PRINTED IN U.S.A.



This test will verify that the display filter is conductive and is properly attenuating the electrical field from the monitor.

If signal exceeds 1 minor division, return unit to service center or Colorado Springs division for installation of a new filter kit, P/N 54600-68704.