

MODIFICATION RECOMMENDED –  
CORRECTS MANUFACTURING OR DESIGN DEFECTS

**8510C-04**

# S E R V I C E N O T E

Supersedes:  
none

8510C rev C.08.00 and above

Serial Numbers: [0000A00000 / 9999Z99999]

**Unreadable softkey labels and syntax errors when using Electronic Calibration Modules (Ecal). Customers who upgrade their 8510C from the CRT version, rev C.07.xx and below, to the LCD version, rev C.08.xx and above, will have problems using Ecal.**

**To Be Performed By: Agilent-Qualified Personnel or Customer**

**Parts Required:**

P/N	Description	Qty.
-----	-------------	------

none

## ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
<b>MODIFICATION RECOMMENDED</b>			
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS:	LABOR: 0.0 Hours
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	USED PARTS:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AUTHOR: [initials]	PRODUCT LINE: WN		
ADDITIONAL INFORMATION:			

© AGILENT TECHNOLOGIES, INC. 2002  
PRINTED IN U.S.A.



September 23, 2002

**Situation:**

Ecal software overwrites the new 8510C LCD display, causing the soft keys labels to be partially off screen and un-readable. Also, timing differences between the CRT version and the LCD version of the 8510C can cause syntax errors.

**Solution/Action:**

A new Ecal.dll file, revision 1.10, is available on the external web at [www.agilent.com/find/ecal](http://www.agilent.com/find/ecal). Follow links to 85097A product page Software, Firmware & Drivers.

This upgrade is only needed when operating 8510C Network Analyzers with LCD displays, revision C.08.00 and above, with Electronic Calibration Modules. However, it is backwards compatible and will also work with earlier 8510 versions, C.07.xx and below.

Supported ECal configuration:

8506xB and 8509xA/B ECal with 85097A PC Interface.  
PC running Windows NT 4.0 or Windows 95.

Instructions for installation:

0. Log on to [www.agilent.com/find/ecal](http://www.agilent.com/find/ecal)
1. Follow links to 85097A product page "Software, Firmware & Drivers"
2. Click on the Ecal.dll, rev 1.10, download link and save file to your PC's Temp directory (usually C:\TEMP)
3. Determine where your current ECal.dll file is located.
  - 2.1 From the Windows Start menu, select Find -> Files or Folders...
  - 2.2 Type in ECal.dll and click on Find Now.
4. Rename old ECal.dll file Ecal\_1\_08.dll.
5. Move the new ECal.dll file from Temp directory to the location of your old Ecal.dll.
6. Your Electronic Calibration Module and PC Interface are now ready to use.