# S E R V I C E N O T E

SUPERSEDES: NONE

### 86100A Infiniium DCA

**Serial Numbers:** 0000A00000 / 9999Z99999

# 86100A Firmware Versions A.01.22 and below are no longer supportable.

#### Situation:

Agilent has made performance improvements to the service horizontal timebase calibration routine starting with version A.02.00. The linearity of the timebase hybrid devices we are receiving can no longer be compensated by an external polynomial calibration; therefore, this routine has moved internal to the firmware. The internal routine ensures accurate timebase linearity that cannot be obtained by any other method.

Any 86100A DCA that comes in for service or yearly calibration will require this performance firmware upgrade. After the upgrade is in place and the service calibration is performed, the firmware cannot be reverted to versions below A.02.00 (A.01.22 and below). Doing so will make the DCA's calibration invalid.

#### **Solution / Action:**

If the firmware has been upgraded because of this service note, notification should be given to the customer to explain why.

If the DCA already has A.02.00 or above it would be appropriate to contact the customer to see if they would prefer the latest firmware or not.

Refer to the 86100A Service Guide for information on calibration procedures.

DATE: June 2001

## ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
MODIFICATION RECOMMENDED		
ACTION CATEGORY:	☐ IMMEDIATELY ☐ ON SPECIFIED FAILURE ■ AGREEABLE TIME	STANDARDS: LABOR 0.25 Hours
LOCATION CATEGORY:	☐ CUSTOMER INSTALLABLE☐ ON-SITE☐ SERVICE CENTER	SERVICE
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: All units are modified
AUTHOR: DL	ENTITY: 5360	ADDITIONAL INFORMATION:

© 2001 AGILENT TECHNOLOGIES PRINTED IN U.S.A.

