

MODIFICATION RECOMMENDED

86100C-12

S E R V I C E N O T E

Supersedes:
NONE

86100C Digital Communications Analyzer Mainframe

Serial Numbers: MY45030387/ MY47440886, SG45030106/ SG47440118

Motherboard board mounting modification improves product reliability related to boot up issues.

Parts Required:
NONE

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	<input type="checkbox"/> ON SPECIFIED FAILURE x AGREEABLE TIME	STANDARDS LABOR: 0.5 Hours	
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE x SERVICE CENTER <input type="checkbox"/> CHANNEL PARTNER	SERVICE INVENTORY: <input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT	USED PARTS: <input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:		NO CHARGE AVAILABLE UNTIL: EOS Date	
AUTHOR: djs		PRODUCT LINE: 8F	
ADDITIONAL INFORMATION:			

© AGILENT TECHNOLOGIES, INC. 2010
PRINTED IN U.S.A.

January 8, 2010

Rev. 17




Situation:

Foam mounted underneath the microprocessor board to prevent vibration during shipment may flex the board more than desired on some units, resulting in intermittent power-on failures. Modifying the foam as described reduces the flex and improves reliability.

Solution/Action:

Modify the foam as described below. The modification will remove roughly half of the foam, equally from the front and rear, leaving a strip in the center.

**Instructions:**


The most common symptom is a boot up error as shown here. The mainframe will come to the point where all LEDs are lighted but will not progress through the boot sequence.

This can be either a hard failure or very intermittent.



To verify the problem is related to the board flexing issue:

1. Power the instrument off and remove the cover.
2. Loosen the four screws indicated here.
3. Re-boot the instrument.
4. If it boots normally, then board flex caused by the foam is a likely cause.



Instructions (continued):

To modify the mounting foam:

1. Completely remove the mother board and locate the mounting foam underneath the processor. (refer to 86100A/B/C Service Guide for detailed instructions)
2. Use a straight edge and pen to mark the foam with a line approximately 16mm from the front and rear edges of the foam as shown here.
3. Use a knife to cut and remove the front and rear portions leaving the center strip of foam intact.
4. There will be some adhesive left on the mounting tray as shown.
5. Re-install the motherboard and verify proper operation.

