86130A-09

SERVICE NOTE

Supersedes: NONE.

86130A BitAlyzer Error Performance Analyzer

Serial Numbers: [0000A00000 / 9999Z99999]

Install Teflon insulating sheets in A2 (PG Assy) / A3 (ED Assy) slots.

To Be Performed By: Agilent-Qualified Personnel

Parts Required:

P/N Description Qty.

86130-20174 Sheet Insulator 2

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:				
MODIFICATION RECOMMENDED				
ACTION CATEGORY:	[[]] IMMEDIATELY [[]] ON SPECIFIED FAILURE X AGREEABLE TIME	STANDARDS: LABOR: 0.5Hours		
LOCATION CATEGORY:	[[]] CUSTOMER INSTALLABLE [[]] ON-SITE X SERVICE CENTER	SERVICE [[]] RETURN INVENTORY: [[]] SCRAP [[]] SEE TEXT	USED [[]] RETURN PARTS: [[]] SCRAP [[]] SEE TEXT	
AVAILABILITY: Perform only if instrume	PRODUCT'S SUPPORT LIFE ent needs to be opened for other service	AGILENT RESPONSIBLE UNTIL: End of Support. vice.		
AUTHOR: RBS PRODUCT LINE: PI8F. ADDITIONAL INFORMATION: MFG Reference ECR1599				

© AGILENT TECHNOLOGIES, INC. 2004 PRINTED IN U.S.A.



Page 2 of 2 86130A-09

Situation:

Due to metal on metal contact, it is possible to create small aluminum filings when installing A2 (PG Assembly) or A3 (ED Assembly) into the 86130A mainframe. Although the filings have never been positively identified as root cause for any failures, there exists the potential that they could cause an internal short in the instrument, causing a failure.

Solution/Action:

Add Teflon insulating sheets to the bottom surfaces of the A2 and A3 mainframe slots to prevent metal on metal contact between the tray assemblies and the mainframe. Install the insulators only if the instrument is opened and the A2/A3 assemblies are removed.

- 1. Clean the slot mainframe surface with an alcohol wetted anti-static cloth to remove any foreign particles from the slot surface.
- 2. Install the white Teflon sheets as shown in Figure 1.




Figure 1 – location of Teflon insulating sheets in A2/A3 slots.

This quality improvement does not affect calibration.

End.