8922S-01

HP 8922S GSM MS Test Set HP 8922SR GSM MS Test Set

Serial Numbers:
0000A00000 / 9999Z99999

Y2K update information.

Product requires firmware revision B.07.07 or later to be Y2K compliant to be Y2K compliant to HP standards.(see situation). Firmware B.07.06 or below is not Y2K compliant to HP standards.

Duplicate Service Notes: 8922SR-01

To Be Performed By: HP-Qualified Personnel or Customer.

Parts Required:

HP P/N Description Quantity 08922-61149 8922S ROM UPGRADE 1

Situation:

Y2K investigation has identified that the response from the BASIC function TIMEDATE is defective. This defect exists now and a TIMEDATE call would fail now if called in any BASIC application. Detection of this bug has caused all 8922 instruments below firmware B.07.07 (or C.01.03 for 8922P,R,X,Y) to be classified as Y2K non-compliant. This bug has not been reported by customers which implies that it has not used in any applications to date.

Failure to install the Y2K upgrade will not cause the HP8922S to return an incorrect date/time stamp on 1st January 2000.

Solution / Action:

A firmware upgrade (ROM based) needs to be installed for firmware above B.07.07 to meet HP Y2K compliance standards. This fixes the TIMEDATE bug but does not affect any other date-related processes within the instrument.

The 8922S will return the correct date/time stamp on 1st January 2000 without modification. It is recommended that no upgrade is required.

Date: 24 August 1998

* :	******************	*****	*
*	*		*
*	* MODIFICATION AVAILABLE		*
*	*		*
*	*		*
*	* REASON: PERFORMANCE ENHANCEMEN'	NT _X	*
*	* -or- SERVICE/RELIABILITY ENHANCEMEN	NT	*
*	* ACTION CATEGORY: AGREEABLE TIME		*
*	* LOCATION CATEGORY: CUSTOMER INSTALLABLE _X ON-SIT	ΓE	*
*	* HP LOCATION _X		*
*	* AVAILABLE UNTIL: END OF SERVICE LIFE		*
*	* AUTHOR/ENTITY: AS/E600		*
*	* ADDITIONAL INFO:		*
*	*		*