

DAQ970A-01

Modification Recommended Service Note

Supersedes:
NONE

DAQ970A Data Acquisition System

Serial Numbers: MY58000101 - MY58001798

The Problem – DAQM909A when used in DAQ970A serial number MY58001798 and lower may exhibit higher-than-normal radiated emissions

Parts Required:

P/N	Description	Qty.
DAQ70-66101	DAQ970A, Data Acquisition System, with Standard Option, with SN prefix MY	1

ADMINISTRATIVE INFORMATION

ACTION	<input checked="" type="checkbox"/> ON SPECIFIED FAILURE	STANDARDS			
CATEGORY:	<input type="checkbox"/> AGREEABLE TIME	LABOR:	0.5 Hours		
LOCATION	<input type="checkbox"/> CUSTOMER INSTALLABLE	SERVICE:	<input type="checkbox"/> RETURN	USED	<input checked="" type="checkbox"/> RETURN
CATEGORY:	<input type="checkbox"/> ON-SITE (active On-site contract required)	INVENTORY:	<input type="checkbox"/> SCRAP	PARTS:	<input type="checkbox"/> SCRAP
	<input checked="" type="checkbox"/> SERVICE CENTER		<input type="checkbox"/> SEE TEXT		<input type="checkbox"/> SEE TEXT
	<input type="checkbox"/> CHANNEL PARTNERS				
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	NO CHARGE AVAILABLE UNTIL:	17 Jan 2021		
	<input type="checkbox"/> Calibration Required	PRODUCT LINE:	GM		
	<input checked="" type="checkbox"/> Calibration NOT Required	AUTHOR:	SL		

ADDITIONAL INFORMATION:

Situation:

When using with DAQ970A Data Acquisition System mainframe, the DAQM909A 4-Channel 24-bit Digitizer Module may cause higher-than-normal radiated emissions. This may lead to noisy measurements.

Solution/Action:

Please contact your nearest Keysight Contact Center at this link, www.keysight.com/find/assist to have your unit serviced.

Revision History:

Date	Service Note Revision	Author	Reason for Change
17 Jan 2020	01	SL	As Published