

S E R V I C E N O T E

SUPERSEDES: NONE

E1610A 34 Mb/s E3 Line Interface for Broadband Series**Serial Numbers:** AU00000000 / AU99999999 (All Serial Numbers)**Required modifications not completed on exchange parts.****To Be Performed By:** Agilent-Qualified Personnel**Parts Required:**

| P/N | Description | Qty. |
|-------------|-----------------|------|
| E1610-69000 | E1610A Exchange | 1 |

Situation:

Required modifications to some E1610A exchange modules P/N E1610-69001 were not fully implemented. The effect is that spurious alarms or errors may be generated when the exchange module is installed.

Solution / Action:

Identify the Circuit board revision as shown in the diagram and determine if ALL the modifications described have been done. All parts without the required modifications completed should be marked as such ****ON THE PART**** and returned as defective.

Continued

DATE: September 1997

ADMINISTRATIVE INFORMATION

| | | | |
|---------------------------------|--|--|---|
| SERVICE NOTE CLASSIFICATION: | | | |
| MODIFICATION RECOMMENDED | | | |
| ACTION CATEGORY: | <input checked="" type="checkbox"/> IMMEDIATELY <input type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME | STANDARDS: LABOR 0.5 Hours | |
| LOCATION CATEGORY: | <input type="checkbox"/> CUSTOMER INSTALLABLE <input checked="" type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER | SERVICE INVENTORY: <input checked="" type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT | USED PARTS: <input checked="" type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT |
| AVAILABILITY: | PRODUCT'S SUPPORT LIFE | | AGILENT RESPONSIBLE UNTIL: September 1998 |
| AUTHOR: DH | ENTITY: 0Y900 | ADDITIONAL INFORMATION: | |

Instructions

- Using proper ESD protection and a TORX driver tool, remove the screws which hold the module cover and shell together.
- Loosen the screws on the module front panel.
- Remove the module right hand cover (looking from the front).
- Remove the daughter cards from the assembly.
- Remove the screws holding the motherboard to the metalwork shell.
- Remove the motherboard for inspection of the underside.
- Inspect the motherboard (E1695-64001) for the revision number on the under side as shown in Figure 1.
- Check for the modifications as shown in Figure 1 and described below.

Revision C Motherboard PCA

- No Action required, the part can be used for service.

Revision A Motherboard PCA

If the version of the motherboard is REV A, the module is to be returned irrespective of modifications.

Revision B PCA

If the version of the motherboard is Rev B, then the following modifications should be apparent (See Fig 1 also).

- 51R1 Resistor and 1nf Capacitor from Pin 1 of U66 to ground.
- 51R1 Resistor and 1nf Capacitor from Pin 1 of U67 to ground.
- Wire link on rear of PCA between pin P1 of U6 and Pin 9 (lifted) of U5 then to pin 9 of U4 (lifted).
- 51R1 Resistor and 1nf Capacitor in series from U13 pin 3 to U13 pin7.
- 51R1 Resistor and 1nf Capacitor in series from U13 pin 11 to U13 pin7.
- 82R5 Resistor and 1nf Capacitor in series from U24 pin 5 to U25 pin 16.
- 82R5 Resistor and 1nf Capacitor in series from U24 pin 10 to U25 pin16


If all of the above modifications have not been done, please return the complete, reassembled module, with an accompanying note attached to the module, identifying it as "For modification as per Service Note E1610-02".

Please return the module properly packed for shipment, to:

Agilent Technologies Australia
Communications Measurements Division
347 Burwood Highway
Burwood East 3151
Victoria Australia
Att: Tracy Finnerty

For queries concerning this service note call:

Doug Hayne,
Communications Measurements Division
+61 3 92105518

E1610A E3 34 Mb/s LIF Modifications**Figure 1**