S E R V I C E N O T E

SUPERSEDES: NONE

E2496A IA-64 Preprocessor

Serial Numbers: US38490101 - US38490169

Stuck bits on data bus caused by Peltier Cooler problem

To Be Performed By: Agilent-Qualified Personnel

Parts Required:

P/N Description Quantity
E2496-69005 Rebuilt Analysis probe assembly 1

Situation:

The probes covered by this service note were shipped with faulty firmware. This firmware enables the Peltier coolers and begin cooling the chips in the probe too soon. The coolers cool the chips below room temperature before they heat up to final operating temperature. This can cause condensation on the chips and circuit board. Over time, data acquisition failures are observed in the analysis probe.

The symptom of this problem is stuck bits on the data bus. Stuck bits are only seen on the data bus. No catastrophic failures have occured, nor are they anticipated.

Continued

DATE: January 2001

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
MODIFICATION RECOMMENDED		
ACTION CATEGORY:	☐ IMMEDIATELY☐ ON SPECIFIED FAILURE☐ AGREEABLE TIME	STANDARDS: LABOR 1.0 Hours
LOCATION CATEGORY:	☐ CUSTOMER INSTALLABLE ☐ ON-SITE ☐ SERVICE CENTER	SERVICE RETURN USED RETURN PARTS: SCRAP SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: January 2003
AUTHOR: LW	ENTITY: 0800	ADDITIONAL INFORMATION:

© 2000 AGILENT TECHNOLOGIES PRINTED IN U.S.A.



Page 2 Service Note E2496A-01

Solution / Action:

A firmware upgrade will not fix the problem. Suspect units only within the serial number range indicated above shall be replaced on indicated failure.

Suspect units shall be returned to an Agilent repair center for replacement. Suspect units can also be replaced on-site.