

E4428C-04**S E R V I C E N O T E**Supersedes:
NONE**E4428C Analog Signal Generator**

Serial Numbers: MY45280907, MY45280908, MY45280911 – MY45280913, MY45280915, MY45280921, MY47380001, MY47380004, MY47380011, MY47380033 - MY47380036

Reference board 1GHz Unlock error**To Be Performed By:** Agilent-Qualified Personnel or Customer**Parts Required:**

P/N	Description	Qty.
E4423-60500	Reference Board	1 or
E4423-69500	EXCH Reference Board	1

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY: <input type="checkbox"/> IMMEDIATELY : <input checked="" type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME		STANDARDS LABOR: 1.0 Hours	
LOCATION CATEGORY: <input checked="" type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER		SERVICE INVENTORY: <input checked="" type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT	USED PARTS: <input checked="" type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY: PRODUCT'S SUPPORT LIFE		NO CHARGE AVAILABLE UNTIL: JAN 10 2010	
AUTHOR: PYong		PRODUCT LINE: 15	
ADDITIONAL INFORMATION:			

© AGILENT TECHNOLOGIES, INC. 2008
PRINTED IN U.S.A.



January 24, 2008

Page 1 of 2

Situation:

Potentially the instrument with the serial number listed on page 1 will exhibit “1GHz Unlock” error. This is due to A18, reference board in the instrument.

Solution/Action:

Replace the A18, reference board in the instrument and perform the A18 post repair procedures listed in the E4428C/E4438C ESG Service Guide. Defective part is to be returned back to factory for root cause analysis.