S E R V I C E N O T E

SUPERSEDES: NONE

ESG "B" Series RF Signal Generator

Serial Numbers: See below:

Duplicate Service Notes:

Duplicate Service Notes:			
E4400B-03A	Serial Numbers: US38440487/US39340699		
	GB38450200/GB39340269		
E4420B-02A	Serial Numbers: US38440464/US39340716		
	GB38450272/GB39340313		
E4421B-02A	Serial Numbers: US38440492/US39340834		
	GB38450457/GB39340827		
E4422B-02A	Serial Numbers: US38440311/US39340523		
	GB38450127/GB39340228		
E4430B-02A	Serial Numbers: US38440210/US39340287		
	GB38450163/GB39340178		
E4431B-02A	Serial Numbers: US38440236/US39340393		
	GB38450249/GB39340275		
E4432B-02A	Serial Numbers: US38441373/US39342028		
	GB38450432/GB39340694		
E4433B-01A	Serial Numbers: US38440715/US39341027		
E4422B-02A E4430B-02A E4431B-02A E4432B-02A	GB38450457/GB39340827 Serial Numbers: US38440311/US39340523 GB38450127/GB39340228 Serial Numbers: US38440210/US39340287 GB38450163/GB39340178 Serial Numbers: US38440236/US39340393 GB38450249/GB39340275 Serial Numbers: US38441373/US39342028 GB38450432/GB39340694		

Family Reference Board Module Replacement due to failure of 1 GHz VCO causing front panel display error 513 "Het band VCO Unlock" and frequency inaccuracy below 250 MHz.

GB38450413/GB39340593

Continued

DATE: February 2000

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:					
MODIFICATION RECOMMENDED					
ACTION CATEGORY:	☐ IMMEDIATELY ☐ ON SPECIFIED FAILURE ☐ AGREEABLE TIME	STANDARDS: LABOR 1.0 assy/6.0 automated adjust Hours			
LOCATION CATEGORY:	☐ CUSTOMER INSTALLABLE☐ ON-SITE☐ SERVICE CENTER	SERVICE			
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: Support Life			
AUTHOR: JE	ENTITY: 5331	ADDITIONAL INFORMATION:			

© 2000 AGILENT TECHNOLOGIES PRINTED IN U.S.A.



To Be Performed By: Agilent Technologies-Qualified Personnel

Parts Required:

P/N Description		Quantity
E4400-60010	Bd Assy Reference, TCXO(NEW)	1
E4400-60009	Bd Assy Reference, OCXO(Option 1E5)(New)	1

Situation:

The ESG E4400B instrument series Het band VCO unlocks due to a non-linearity in the tuning charactereristics of the surface acoustic wave oscillator used to generate the heterodyne band (below 250 MHz) in the ESG. This VCO is located on the Reference Board Assembly Module (A11). Instrument front panel error 513 results from this failure and frequency inaccuracy below 250 MHz. Information from the VCO vender indicates an expected failure rate of 8% to 12% may be experienced over the specific ESG population.

Solution / Action:

The resolution plan is to repair on failure. Replace the reference board assembly and recalibrate the ESG A/D RF Signal Generator in accordance to the Post-Repair Procedures; located in the ESG Service Guide (P/N: E4400-90155/Print Date Sept 99). Ship failed units to Agilent Technologies customer service center as described in the routing guide. Otherwise, post-repair may be performed using the ESG Service Software along with the ESG A/D Calibration Guide (P/N: E4400-90325/Print Date Nov 99). All defective Reference Board Assemblies have been purged from inventory and ALL failed E4400-60139/69139 and E4400-60140/69140 assemblies should be scrapped.

Changes to effected range of serial numbers or repair strategy will be communicated in revisions to this service note