# INFORMATION ONLY - DOES NOT COMMUNICATE A MODIFICATION OR SAFETY CONDITION

E5053A-02

## SERVICE NOTE

Supersedes: None

### E5053A 26.5 GHz Microwave Downconverter

Serial Numbers: MY45100101 / MY45100216

One or more of the secondary power supplies (+9V, +12V, +15V or -15V) on Channel 2 of the A12 PIS/DIGIFUL I.F. assembly (E5053-62012) are in error, due to Flat Cable Assembly short out.

To Be Performed By: Agilent-Qualified Personnel or Customer

**Parts Required:** 

P/N Description Qty.

E5053-61646 FLAT CABLE ASSEMBLY 1

#### **Situation:**

One or more of the secondary power supplies (+9V, +12V, +15V or -15V) on Channel 2 of the A12 PIS/DIGIFUL I.F. assembly (p/n E5053-62012) are in error, causing various P.O.S.T errors.

#### ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

## **INFORMATION ONLY**

AUTHOR: jm PRODUCT LINE: WN

ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2006 PRINTED IN U.S.A.



Page 2 of 2 E5053A-02

#### **Solution/Action:**

Replace the old FLAT CABLE ASSEMBLY (p/n E5053-61642) with the new one (p/n E5053-61646).

Replacement procedure

Step1. Remove the old power supply. (refer to E5053A service guide, section Power Supply Assembly Replacement)

Step2. Reverse the order of the removal procedure.

Step3. After replacing the power supply, check the following post repair procedure.

- No Adjustment needed.
- "E5053 Test" on Page 40 of E5053A service guide

**Retrofit Time**: 0.5 hour (test is included)