

MODIFICATION RECOMMENDED –  
CORRECTS MANUFACTURING OR DESIGN DEFECTS

**E5071A-02**

# **S E R V I C E N O T E**

Supersedes:  
NONE

E5071A ENA Series Network Analyzer, 300 kHz to 8.5 GHz

Serial Numbers: **JP1KJ00000 / JP1KJ00223**

**Firmware Update for Bug Fix**

**To Be Performed By: Customer**

**Parts Required: NONE**

## ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
<b>MODIFICATION RECOMMENDED</b>			
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input type="checkbox"/> ON SPECIFIED FAILURE <input checked="" type="checkbox"/> AGREEABLE TIME	STANDARDS: LABOR: 0.5 Hours	
LOCATION CATEGORY:	<input checked="" type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY: <input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT	USED PARTS: <input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE		
AGILENT RESPONSIBLE UNTIL: Dec 2004			
AUTHOR: TO		PRODUCT LINE: WN	
ADDITIONAL INFORMATION:			

© AGILENT TECHNOLOGIES, INC. 2002  
PRINTED IN U.S.A.



December 6, 2002

**Situation:**

The E5071A firmware revision 1.01 and below have a bug, which causes incorrect measurement results when the fixture simulator function is used. This bug has been fixed in the firmware revision 1.02 and above.

**Solution/Action:**

Install the latest revision 3.01 firmware (as of Dec 2002) in the E5071A. Customers can update the firmware of their own E5071A by downloading the revision 3.01 firmware from Agilent website as follows.

- 1) Access <http://www.agilent.com/find/ena>
- 2) Click "E5071A ENA Series Network Analyzer, 300kHz to 8.5 GHz".
- 3) Click "Software, Firmware & Drivers".
- 4) Click "E5071A ENA Series RF Network Analyzer, 300 kHz to 8.5 GHz Firmware Update".
- 5) Follow the "Download Instructions for Firmware" to download the revision 3.01 firmware and install it into the E5070A.