

MODIFICATION RECOMMENDED –  
CORRECTS MANUFACTURING OR DESIGN DEFECTS

**E5071B-08C**

# **S E R V I C E                      N O T E**

Supersedes:  
E5071B-08B

## **E5071B ENA Series Network Analyzer, 300 kHz to 8.5 GHz**

**Serial Numbers:**    **JP1KKxxxxx, MY421xxxx, MY422xxxxx**  
                              **MY42301053 to MY42301309**

**When a measurement trace or output power shows troubles between 1.3 GHz and 2.1 GHz, replace A1 module with the latest one (E5071-6x571), and update E5071B Operating system at the same time.**

**To Be Performed By:** Agilent-Qualified Personnel

**Parts Required:** See Solution/Action

## **ADMINISTRATIVE INFORMATION**

SERVICE NOTE CLASSIFICATION:			
<b>MODIFICATION RECOMMENDED</b>			
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input checked="" type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS: LABOR: 2.0 Hours	
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY: <input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT	USED PARTS: <input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE		
AGILENT RESPONSIBLE UNTIL: May 2007			
AUTHOR: KW                      PRODUCT LINE: WN			
ADDITIONAL INFORMATION:			

© AGILENT TECHNOLOGIES, INC. 2006  
PRINTED IN U.S.A.



May 26, 2006

**Situation:**

The E5070B and E5071B's A1 source board E5071-6x551 and E5071-6x561 module had high-failure rate component parts problem, thus it was re-designed to improve its reliability as E5071-6x571.

When the high-failure rate part has defective, the unit cannot output correct power level source or local signal, between 1.3 GHz and 2.1 GHz frequency range.

Typical symptoms are as follows:

- The trace shows spike at 1.3 GHz or 2.1 GHz at the preset situation.
- The trace between 1.3 GHz to 2.1 GHz is more noisy than other frequency ranges.
- The power level of 1.3 GHz to 2.1 GHz is lower than other frequency ranges.
- Internal test of A1 ALC shows fail at SOP (f=1.3G) or LOP (f=1.3G) as Figure 2.

Above symptoms tend to appear after 30-minute heat run.




Figure 1. Trace shows noise around 1.3 GHz to 2.1 GHz at preset setting.




Figure 2. A1 ALC in Internal test has failure at SOP (f=1.3G) or LOP (f=1.3G)

And the A1 board (E5071-66571, E5071-69571) requires firmware version Rev.A.5.00 or later. If customer unit's firmware version is less than Rev.A.5.00, it should be updated by changing the operating system. With Rev A.03.60 or below version firmware, an error message "Power on test failed (A1 not found)" is shown at lower left part on a display at power on. With Rev A.03.62 or A.04.00 version firmware, any of messages "Power on test failed (A1 DC-bus, 0x00000010)", "Power on test failed (A1 DC-bus, 0x00000020)", or "Power on test failed (A1 DC-bus, 0x00000030)" is shown at power on.

Please refer to the service note E5071B-07C for the detail.

#### **Solution/Action:**

**When customer's E5070B/71B shows any of the typical symptoms in "Situation" part, and the unit's original configurations are as follows:**

- **A1 source board part number is E5071-6x551 or E5071-6x561**
- **Firmware version is A.04.00 or below**

Replace the defective board with E5071-6x571, new A1 module. Also, update the operating system in accordance with the service note E5071B-10A to implement the firmware revision 5.00 or later. \*1

#### **Parts Required**

<b>P/N</b>	<b>Description</b>	<b>Qty.</b>
E5071-69571 (or E5071-66571)	A1 Source board module	1

After the installation, perform A1 "Source Board" in spot adjust menu in the E5070B/E5071B adjustment program.

Then execute the following programs to verify that the replacement has been successfully completed.

Internal/External Test

Performance test

At last, attach the last page of this note to the unit to inform customer that the firmware version has been updated.

\*1 Refer to the E5070B/E5071B service manual chapter 6, A1 Source board replacement part for the detail procedure

**When customer's E5070B/71B shows any of the typical symptoms in "Situation" part, and the unit's original configurations are as the followings:**

- **A1 source board part number is E5071-6x551 or E5071-6x561**
- **Firmware version is A.05.00 or later**

Replace the defective board with E5071-6x571 only.

#### **Parts Required**

<b>P/N</b>	<b>Description</b>	<b>Qty.</b>
E5071-69571 (or E5071-66571)	A1 Source board module	1

After the installation, perform A1 “Source Board” in spot adjust menu in the program.  
There is no need to update the operating system because customer’s firmware is a higher version.  
No need to attaché the last page.

**When customer’s E5070B/71B has a failure in A1 module, but the A1’s part number is as the followings:**

**E5071-6x571 or a higher part number version.**

The unit is not the eligible one for this service note, because it has already the latest A1 module and firmware.

**Retrofit Time**

Assembly Time:	0.5 hour
Adjustment Time:	0.5 hour
Performance Tests Time:	1.0 hour
Total Time:	2.0 hour

## Note to Customer: Firmware Upgrade Notice

Your unit is recognized as being eligible for failure correction under the Agilent Technologies service note E5071B-08B. Therefore, we changed the source board module to the latest model to improve reliability, and this was done to update the operating system. Along with this operating system update, the firmware version was updated to Rev.A.05.00 or later in order to assure correct operation of the new source board.

This firmware upgrade adds some new features as listed below, and it might require some changes in operational procedures at your location; however, this firmware update is necessary for using the latest source board module. Accordingly, we would like you to use these new features, however if you do not need them kindly turn them off. Please refer to the latest user's guide for detailed information on new features. Thanks for your understanding.

Agilent Technologies

You can download the latest user's guide by going to [www.agilent.com/find/ena](http://www.agilent.com/find/ena) and then selecting "Manuals & Guides" from the "Key library information" menu.

### **Additional features from Rev.A.04.00**

Changes of A.05.00, and

- Add Limit line offsets
- Add Ripple limit line
- Add Bandwidth limit

### **Additional features from Rev.A.03.62**

Changes of A.04.00, and

- Add Point trigger function
- Add Imbalance 3 and 4 parameters for SE-SE-Bal measurement (Fixture simulator)
- Add 7mm calibration kit such as 85031B and 85050C/D

### **Additional features from Rev.A.03.60**

No new features

### **Additional features from Rev.A.03.54**

Change of A.03.60, and

- Add Auto Power Range set function

### **Additional features from Rev.A.03.53**

Change of A.03.54, and

- Add Initial Source Port Control feature

### **Additional features from Rev.A.03.50**

Changes of A.03.53, and

- Maximum output power limitation (-10 dBm)
- Add "SDEV" to CALC:SEL:FUNC:TYPE command parameter

### **Additional features from Rev.A.03.01**

Changes of A.03.50, and

- VBA Usability Enhancement
- ECal Functionality Enhancement
- Embedding/De-embedding Enhancement

### **Additional features from Rev.A.03.00**

Changes of A.03.01, and

- Add system characteristic impedance (Z0) set feature