

MODIFICATION RECOMMENDED

E5071C-06

S E R V I C E N O T E

Supersedes:
NONE

E5071C ENA Series Network Analyzer, 9 kHz to 20 GHz

Serial Numbers: ALL

The S11 trace shows strange spurs at 68M to 2.1G, when the E5071C operator changes stop frequency to 6G, 6.5G, 7G etc.

Parts Required:

P/N	Description	Qty.
E5071-62091	Tested Synthesizer Module	2

Or

E5071-69091	Tested Synthesizer Module, Exchange	2
-------------	-------------------------------------	---

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	X ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS	LABOR: 2.0 Hours
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE X SERVICE CENTER <input type="checkbox"/> CHANNEL PARTNER	SERVICE INVENTORY: <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT	USED PARTS: <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	NO CHARGE AVAILABLE UNTIL: August 1, 2012	
AUTHOR:	jm	PRODUCT LINE: WN	
ADDITIONAL INFORMATION:			

© AGILENT TECHNOLOGIES, INC. 2010
PRINTED IN U.S.A.

August 9, 2010

Rev. 17




Situation:


Shortly after turning on the E5071C and then “Preset” key pressed, the S11 is fine. But when the E5071C operator changes stop frequency to 6G, 6.5G, 7G etc., the S11 trace shows strange spur at 68M to 2.1G. (The stop freq point varies around 4.39G to 7.0G)

The same symptom occurs on S22, S33 and S44.

The below is a sample failure symptom on S22.

**Solution/Action:**

1. Replace two synthesizer boards (item 4 at the below picture) for Local and Source.



2. Perform the required Adjustment and Perform Verification which is described at Post-Repair Procedures in the service manual.

-End of Document -