### S Ε R V I C E Ν Т Ε

SUPERSEDES: NONE

# E5100A/B Network Analyzer

Modification to fix "INPUFORM", "INPURAW", and INPUDATA" command errors

To Be Performed By: HP-qualified personnel

Parts Required:

Need one of the following firmware disks:

HP P/N	Qty.	Description	Used for
E5100-18003	1	FW DISK 2.10#509	E5100A with Option 509
E5100-18103	1	FW DISK 2.10 1BW	E5100B with black & white LCD
E5100-18203	1	FW DISK 2.10 1CL	E5100B with color LCD
E5100-18303	1	FW DISK 2.10 2BW	E5100A with black & white LCD (*1)
E5100-18403	1	FW DISK 2.10 2CL	E5 100A with color LCD

Note \*1: If the maximum number of sweep points of the HP E5100A is 801, P/N E5100-18103 should be used.

Continued

DATE: August 1996

# ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:  MODIFICATION RECOMMENDED				
ACTION CATEGORY:	☐ IMMEDIATELY ■ ON SPECIFIED FAILURE □ AGREEABLE TIME	STANDARDS:  LABOR 1.0 Hours		
LOCATION CATEGORY:	☐ CUSTOMER INSTALLABLE☐ ON-SITE☐ HP LOCATION	SERVICE		
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	HP RESPONSIBLE UNTIL: August 1998		
AUTHOR: KI	ENTITY: 3355	ADDITIONAL INFORMATION:		

© 1996 HEWLETT-PACKARD COMPANY PRINTED IN U.S.A.



### Situation:

When "INPUFORM", "INPURAW", or "INPUDATA" command is used to enter the measurement data to a data array, obtained data array may be incorrect.

<Example>

```
DIM A(1:201,1:2)
OUTPUT @E5100;"INPUDATA";A(*)
```

In the above program, obtained data array A(\*) may differ from the actual data in the HP E5100A/B.

This problem is caused by a firmware bug on revision 1.02 and below.

## Solution/Action:

This problem can be fixed by firmware update.

- 1. Firmware update procedure
- 1-1. Press [System], {MORE}, {SERVICE MENU}, {FIRMWARE REVISION} to confirm that the unit has a firmware revision 1.01 or below.
- 1-2. Confirm that the firmware disk is correct one to update the firmware of the unit. (see the part list of "Parts Required:")
- 1-3. Turn OFF the unit.
- 1-4. While pressing [Preset] and [0] keys at the same time, turn ON the E5100A/B, and wait for a while until some {firmware update} softkey is appeared on the display,
- 1-5. Press {Firmware Update} softkey.
- 1-6. Insert the firmware disk into the floppy disk drive of the HP E5100A/B.
- 1-7. Press {OK} softkey.
- 1-8. Press {EXECUTE UPDATE} softkey.
- 1-9. Press {OK} softkey to start the firmware update.

Note: It will take several minutes to complete the firmware update. When the firmware update is completed, the unit automatically execute preset operation.

- 2. Final operation check
- 2-1. Turn the E5100A/BON and confirm that the unit passes power on selftest.
- 2-2. Press [System], {MORE}, {SERVICE MENU}, {EXECUTE TEST} to start self-diagnoses.
- 2-3. Confirm that the unit passes the self-diagnoses.