S F F R V \mathbf{C} Ν O

SUPERSEDES: NONE

HP E5100A/B Network Analyzer Firmware Revision: 2.10 and below

Modification to fix "PROG:STAT?" command error in IEEE 64-bit floating point data transfer format (FORM3)

To Be Performed By: HP-qualified personnel

Parts Required:

Need one of the following firmware disks:

1. HP P/N E5100-180xx (FW DISK #509)

For: Firmware revision before modification ... REV.2.10 and below Installed optionOption 509

2. HP P/N E5100-181xx (FW DISK 1BW)

For: Firmware revision before modification ... REV.2.10 and below LCD display type Black and white Maximum number of sweep points 801 or 401

3. HP P/N E5100-182xx (FW DISK 1CL)

For: Firmware revision before modification ... REV.2.10 and below LCD display type Color Maximum number of sweep points 401

Continued

DATE: September 1998

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
MODIFICATION RECOMMENDED		
ACTION CATEGORY:	☐ IMMEDIATELY ■ ON SPECIFIED FAILURE ☐ AGREEABLE TIME	STANDARDS: LABOR 1.0 Hours
LOCATION CATEGORY:	☐ CUSTOMER INSTALLABLE☐ ON-SITE☐ HP LOCATION	SERVICE RETURN USED RETURN INVENTORY: SCRAP SEE TEXT SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	HP RESPONSIBLE UNTIL: September 2000
AUTHOR: KI	ENTITY:	ADDITIONAL INFORMATION:

© 1998 HEWLETT-PACKARD COMPANY PRINTED IN U.S.A.



Page 2 Service Note E5100A/B-21

Maximum number of sweep points1601

5. HP P/N E5100-184xx (FW DISK 2CL)

For: Firmware revision before modification ... REV.2.10 and below

LCD display type Color

Maximum number of sweep points 1601

Notes:

- * "xx" should be the latest number. (It must be "04" or later.) "04" is assigned for firmware revision 2.11 in which the problem described in this service note was solved.
- * Choose a correct firmware disk according to the installed option, LCD display type, and maximum number of sweep points of the HP E5100A/B. Installing incorrect firmware may cause serious trouble to the HP E5100A/B.
- * Firmware revision 3.00 or later (HP P/N E5100-185xx) should NOT be installed into the HP E5100A/B which currently has firmware revision 2.xx or below without hardware modification. Installing REV.3.xx without required hardware modification may cause serious trouble to the HP E5100A/B. To install the firmware revision 3.00 or later into the unit, the HP E5100A/B must be modified using a REV.3.xx upgrade kit. That hardware modification is NOT covered by this service note.

Situation:

Sending "PROG:STAT?" command when the HP E5100A/B is set to IEEE 64-bit floating point data transfer format (FORM3) may cause an error. If "FORM4" (ASCII data transfer format) command is sent before the "PROG:STAT?" command, this error does not occur. This problem is caused by a firmware bug on revision 2.10 and below, and it is fixed on revision 2.11.

Solution/Action:

This problem can be fixed by firmware update.

- 1.0. Firmware update procedure
- 1-1. Press [System], {MORE}, {SERVICE MENU}, {FIRMWARE REVISION} to confirm that the unit has a firmware revision 2.10 and below.
- 1-2. Confirm that the firmware disk is correct one to update the firmware of the unit. (see the part list of "Parts Required:")
- 1-3. Turn OFF the unit.
- 1-4. While pressing [Preset] and [0] keys at the same time, turn ON the E5100A/B, and wait for a while until some {firmware update} softkey is appeared on the display.
- 1-5. Press {Firmware Update} softkey.

Service Note E5100A/B-21 Page 3

- 1-6. Insert the firmware disk into the floppy disk drive of the HP E5100A/B.
- 1-7. Press {OK} softkey.
- 1-8. Press {EXECUTE UPDATE} softkey.
- 1-9. Press {OK} softkey to start the firmware update.

Note:

It will take several minutes to complete the firmware update. When the firmware update is completed, the unit automatically executes preset operation.

- 2-0. Final operation check
- 2-1. Turn the E5100A/B ON and confirm that the unit passes power on selftest.
- 2-2. Press [System],{MORE},{SERVICE MENU},{EXECUTE TEST} to start self-diagnoses.
- 2-3. Confirm that the unit passes the self-diagnoses.