S E R V I C E N O T E

SUPERSEDES: NONE

HP E5100A/B Network Analyzer

Firmware Revision: 2.10 and below

Modification to fix incorrect group delay trace data at first sweep point

To Be Performed By: HP-qualified personnel

Parts Required:

Need one of the following firmware disks:

1. HP P/N E5100-180xx (FW DISK #509)

For: Firmware revision before modification ... REV.2.10 and below Installed option Option 509

2. HP P/N E5100-181xx (FW DISK 1BW)

3. HP P/N E5100-182xx (FW DISK 1CL)

For: Firmware revision before modification REV.2.10 and below

continued

DATE: September 1998

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION: MODIFICATION RECOMMENDED		
ACTION CATEGORY:	☐ IMMEDIATELY ■ ON SPECIFIED FAILURE □ AGREEABLE TIME	STANDARDS: LABOR 1.0 Hours
LOCATION CATEGORY:	☐ CUSTOMER INSTALLABLE☐ ON-SITE☐ HP LOCATION	SERVICE RETURN USED RETURN INVENTORY: SCRAP PARTS: SCRAP SEE TEXT SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	HP RESPONSIBLE UNTIL: September 2000
AUTHOR: KI	ENTITY:	ADDITIONAL INFORMATION:

© 1998 HEWLETT-PACKARD COMPANY PRINTED IN U.S.A.

PACKARD

Page 2 Service Note E5100A/B-22

4. HP P/N E5100-183xx (FW DISK 2 BW)

5. HP P/N E5100-184xx (FW DISK 2CL)

For: Firmware revision before modification REV.2.10 and below

Notes:

- * "xx" should be the latest number. (It must be "04" or later.) "04" is assigned for firmware revision 2.11 in which the problem described in this service note was solved.
- * Choose a correct firmware disk according to the installed option, LCD display type, and maximum number of sweep points of the HP E5100A/B. Installing incorrect firmware may cause serious trouble to the HP E5100A/B.
- * Firmware revision 3.00 or later (HP P/N E5100-185xx) should NOT be installed into the HP E5100A/B which currently has firmware revision 2.xx or below without hardware modification. Installing REV.3.xx without required hardware modification may cause serious trouble to the HP E5100A/B. To install the firmware revision 3.00 or later into the unit, the HP E5100A/B must be modified using a REV.3.xx upgrade kit. That hardware modification is NOT covered by this service note.

Situation:

Group delay trace data at the first sweep point may be incorrect. The first sweep point on the display may look extremely low compared with the other trace data. This problem is caused by a firmware bug on revision 2.10 and below, and it is fixed on revision 2.11.

Solution/Action:

This problem can be fixed by firmware update.

- 1.0. Firmware update procedure
- 1-1. Press [System], {MORE}, {SERVICE MENU}, {FIRMWARE REVISION} to confirm that the unit has a firmware revision 2.10 and below.
- 1-2. Confirm that the firmware disk is correct one to update the firmware of the unit. (see the part list of "Parts Required:")
- 1-3. Turn OFF the unit.
- 1-4. While pressing [Preset] and [0] keys at the same time, turn ON the E5100A/B, and wait for a while until some {firmware update} softkey is appeared on the display.

Service Note E5100A/B-22 Page 3

- 1-5. Press {Firmware Update} softkey.
- 1-6. Insert the firmware disk into the floppy disk drive of the HP E5100A/B.
- 1-7. Press {OK} softkey.
- 1-8. Press {EXECUTE UPDATE} softkey.
- 1-9. Press {OK} softkey to start the firmware update.

Note:

It will take several minutes to complete the firmware update. When the firmware update is completed, the unit automatically executes preset operation.

- 2.0. Final operation check
- 2-1. Turn the E5100A/B ON and confirm that the unit passes power on selftest.
- 2-2. Press [System],{MORE},{SERVICE MENU},{EXECUTE TEST} to start self-diagnoses.
- 2-3. Confirm that the unit passes the self-diagnoses.