F S F R V \mathbf{C} N F O

SUPERSEDES: NONE

HP E5100A/B Network Analyzer

Firmware Revision: 2.10 and below

Modification to improve rotary knob's data adjustment resolution in measuring at narrow sweep span

To Be Performed By: HP-qualified personnel

Parts Required:

Need one of the following firmware disks:

1. HP P/N E5100-180xx (FW DISK #509)

For: Firmware revision before modification ... REV.2.10 and below Installed option Option 509

2. HP P/N E5100-181xx (FW DISK 1BW)

For: Firmware revision before modification ... REV.2.10 and below LCD display type Black and white Maximum number of sweep points801 or 401

3. HP P/N E5100-182xx (FW DISK 1CL)

For: Firmware revision before modification ... REV.2.10 and below LCD display type Color Maximum number of sweep points401

continued

DATE: September 1998

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION: MODIFICATION RECOMMENDED					
ACTION CATEGORY:	☐ IMMEDIATELY ■ ON SPECIFIED FAILURE □ AGREEABLE TIME	STANDARDS: LABOR 1.0 Hours			
LOCATION CATEGORY:	☐ CUSTOMER INSTALLABLE☐ ON-SITE☐ HP LOCATION	SERVICE INVENTORY:	☐ RETURN ☐ SCRAP ☐ SEE TEXT	USED PARTS:	☐ RETURN ■ SCRAP ☐ SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	HP RESPONSIBLE UNTIL: September 2000			
AUTHOR: KI	ENTITY:	ADDITIONAL INFORMATION:			

© 1998 HEWLETT-PACKARD COMPANY PRINTED IN U.S.A.



Page 2 Service Note E5100A/B-23

4. HP P/N E5100-183xx (FW DISK 2BW)

5. HP P/N E5100-184xx (FW DISK 2CL)

Notes:

- * "xx" should be the latest number. (It must be "04" or later.) "04" is assigned for firmware revision 2.11 in which the problem described in this service note was solved.
- * Choose a correct firmware disk according to the installed option, LCD display type, and maximum number of sweep points of the HP E5100A/B. Installing incorrect firmware may cause serious trouble to the HP E5100A/B.
- * Firmware revision 3.00 or later (HP P/N E5100-185xx) should NOT be installed into the HP E5100A/B which currently has firmware revision 2.xx or below without hardware modification. Installing REV.3.xx without required hardware modification may cause serious trouble to the HP E5100A/B. To install the firmware revision 3.00 or later into the unit, the HP E5100A/B must be modified using a REV.3.xx upgrade kit. That hardware modification is NOT covered by this service note.

Situation:

When the rotary knob is used to adjust such parameters like center frequency in narrow sweep span, its adjustment resolution may be too coarse to set it to appropriate value. This problem is solved on firmware revision 2.11

Solution/Action:

This problem can be fixed by firmware update.

- 1.0. Firmware update procedure
- 1-1. Press [System], {MORE}, {SERVICE MENU}, {FIRMWARE REVISION} to confirm that the unit has a firmware revision 2.10 and below.
- 1-2. Confirm that the firmware disk is correct one to update the firmware of the unit. (see the part list of "Parts Required:")
- 1-3. Turn OFF the unit.
- 1-4. While pressing [Preset] and [0] keys at the same time, turn ON the E5100A/B, and wait for a while until some {firmware update} softkey is appeared on the display.
- 1-5. Press {Firmware Update} softkey.
- 1-6. Insert the firmware disk into the floppy disk drive of the HP E5100A/B.

continued

Service Note E5100A/B-23 Page 3

- 1-7. Press {OK} softkey.
- 1-8. Press {EXECUTE UPDATE} softkey.
- 1-9. Press {OK} softkey to start the firmware update.

Note:

It will take several minutes to complete the firmware update. When the firmware update is completed, the unit automatically executes preset operation.

- 2.0. Final operation check
- 2-1. Turn the E5100A/B ON and confirm that the unit passes power on selftest.
- 2-2. Press [System],{MORE},{SERVICE MENU},{EXECUTE TEST} to start self-diagnoses.
- 2-3. Confirm that the unit passes the self-diagnoses.