

E6640A-01

Modification Recommended Service Note

Supersedes:
None

E6640A EXM Wireless test set

Serial Numbers: All Units

The Problem –E6640A units using V9077B/Y9077B WLAN measurement application.

Using EXM to make SEM measurement for 80MHz WLAN signal with 240MHz span, because EXM has no image protection, the DUT 1812GHz spur and 5GHz spur get mixed into the SEM span range and cause high SEM failure rate for customer DUT.

Parts Required:

None

ADMINISTRATIVE INFORMATION

ACTION	X- ON SPECIFIED FAILURE	STANDARDS			
CATEGORY:	<input type="checkbox"/> AGREEABLE TIME	LABOR:	0.5 Hours		
LOCATION	X - CUSTOMER INSTALLABLE	SERVICE:	<input type="checkbox"/> RETURN	USED	<input type="checkbox"/> RETURN
CATEGORY:	<input type="checkbox"/> ON-SITE (active On-site contract required)	INVENTORY:	<input type="checkbox"/> SCRAP	PARTS:	<input type="checkbox"/> SCRAP
	X- SERVICE CENTER		<input type="checkbox"/> SEE TEXT		<input type="checkbox"/> SEE TEXT
	<input type="checkbox"/> CHANNEL PARTNERS				
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	NO CHARGE AVAILABLE UNTIL:	31 March 2019		
	<input type="checkbox"/> Calibration Required	PRODUCT LINE:	PL13		
	X - Calibration NOT Required	AUTHOR:	MW		

ADDITIONAL INFORMATION:

Situation:

E6640A units using V9077B/Y9077B WLAN measurement application
Using EXM to make SEM measurement for 80MHz WLAN signal with 240MHz span, because EXM has no image protection, the DUT 1812GHz spur and 5GHz spur get mixed into the SEM span range and cause high SEM failure rate for customer DUT.

Increase the measurement Bandwidth of the EXM TRX module eliminates the Spurs.

Solution/Action:

License key upgrade for B85 to B1X (160 MHz analysis bandwidth)
Units with M9432A TRX module get E6640AW-BU5 Upgrade from 80 to 160 MHz on 2FD TRX
Units with M9433A TRX module get E6640AT-BU5 Upgrade from 80 to 160 MHz on 2FD TRX

Revision History:

Date	Service Note Revision	Author	Reason for Change
13 February 2018	01	Michael Woichik	As Published