

**E8267D-24A**

**S E R V I C E N O T E**

Supersedes:  
E8267D-24

**E8267D Digital Signal Generator**

**Serial Numbers:**  
**MY00000000/MY50350067and US00000000/US50350044**

**Intermittent CPU boot-up and/or No display**

**Parts Required:**

P/N	Description	Qty.
None		

**ADMINISTRATIVE INFORMATION**

SERVICE NOTE CLASSIFICATION:			
<b>MODIFICATION RECOMMENDED</b>			
ACTION CATEGORY:	X ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS	LABOR: 0.5 Hours
LOCATION CATEGORY:	X CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE X SERVICE CENTER <input type="checkbox"/> CHANNEL PARTNER	SERVICE INVENTORY: <input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT	USED PARTS: <input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	Always	NO CHARGE AVAILABLE UNTIL 2/2/13	
<input type="checkbox"/> Calibration Required X Calibration NOT Required	PRODUCT LINE: 15 AUTHOR: PY		
ADDITIONAL INFORMATION:			

© AGILENT TECHNOLOGIES, INC. 2012  
PRINTED IN U.S.A.

October 15, 2012  
Rev. 20



**Situation:**

The clock buffer, U7 on the CPU board (E8251-60006 or E8251-60661 Revision 004 and below), may cause intermittent boot up and/or no display when the instrument is powered up. It is recommended that this modification is performed on any instrument within the serial numbers above that exhibits an intermittent boot-up and/or a blank display.

**Solution/Action:**

Using the appropriate soldering technique and ESD station, perform a modification on the U7 circuit on the CPU board. Connect U7 pin 8 to 3.4V (wire pin 8 to pin 4) and connect U7 pin 9 to DCOM (wire pin 9 to pin 12).

**U7 modification procedure:**

1. Refer to E8257D Service Guide for the A18 CPU removal procedure.
2. Refer to Figure 1 for U7.
3. Use 30 AWG wire for wiring pin 8 to pin 4, and pin 9 to pin 12 per Figure 1.
4. Re-install CPU and cover.
5. Run self test.
6. No calibration is required.

Figure 1 U7 wire modification

