

E8357A-02D**S E R V I C E****N O T E**Supersedes:
E8357A-02C**E8357A PNA Series RF Network Analyzers****Serial Numbers: 00000000 thru 46999999**

Many of the Front Panel Interface (FPI) boards which were installed per Service Note E8357A-02B need to be modified or replaced because the RPG shaft can disconnect, and the front panel keyboard and RPG can respond intermittently upon boot up.

FPI boards are causing “won’t boot” conditions and USB signal integrity problems. Installing a new FPI board corrects these problems.

If the front panel assembly is removed, remember to add the new bracket modification described in Service Note E8357A-03.

To Be Performed By: Agilent-Qualified Personnel**Parts Required:**

P/N	Description	Qty.
E8361-63061	Printed-circuit assembly board	1

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	☐ IMMEDIATELY ☐ ON SPECIFIED FAILURE X AGREEABLE TIME	STANDARDS: Labor: Models w/ Opt 014 or 015: 2 hrs (add 2 hrs for E8361A) Models w/o Opt 014 or 015: 1 hr	
LOCATION CATEGORY:	CUSTOMER INSTALLABLE X ON-SITE X SERVICE CENTER	SERVICE ☐ RETURN INVENTORY: X SCRAP ☐ SEE TEXT	USED ☐ RETURN PARTS: X SCRAP ☐ SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE		
NO CHARGE AVAILABLE UNTIL: January 1, 2010			
AUTHOR: MF PRODUCT LINE: WN ADDITIONAL INFORMATION: Model-specific Service Notes on the same topic were written for the following PNA models: E8356/7/8A, N3381/2/3A, E8801/2/3A, E8361/2/3/4A, E8362/3/4B, and N5230A. Service Note History: -02A, Sept05, E8356-60003 does not need to be replaced. / -02B, Nov05, Add bracket Don't replace E8361-20061 FPI board. / -02C, Jul07, / -02D, Nov07, E8356-60003 is not to be replaced if still functional.			

© AGILENT TECHNOLOGIES, INC. 2007

PRINTED IN U.S.A.

**Agilent Technologies**

November 15, 2007

Situation:

FPI boards E8356-60209 and the older E8356-60029 were both identified as causing a serious “won’t boot” condition and a USB signal integrity issue. These issues were noticed in production as well as service centers. The booting issue was due to a tantalum capacitor (C58, 4.7uF, and 50V) reversed biased at 10 percent of its rated voltage. Both issues were fixed with a board layout change of the E8361-63061, revisions 001 to 007 FPI boards. Older E8361-63061 revision 008 FPI boards were identified as having an intermittent front panel keyboard and RPG lockup problems. This problem has been traced to an incorrect voltage applied to a pin on the U4 IC.

Solution/Action:

The Agilent Service Parts Organization is currently stocking E8361-63061 revision 009 FPI boards. This board should be used to replace all E8356-60029, E8356-60209, E8361-63061 revisions 001 to 007, and E8361-63061 revision 008 FPI boards. Rather than replacing the E8361-63061 revision 008, it can be modified using the information on pages 3 and 4.

The E8356A/57A/58A analyzers originally shipped with E8356-60003 FPI boards. These boards should NOT be replaced if they are still functional.

NOTE: The PNA may already have the E8361-63061 FPI board installed. Before replacing the FPI board, remove the round knob (RPG) from the front panel by gently pulling the knob forward. Examine the FPI board’s RPG spindle. A dot of red paint on the end of the spindle indicates a revision 001 through 008 FPI board. A dot of black paint on the end of the spindle indicates a revision 009 FPI board. If there is no red or black dot on the RPG spindle, remove the outer cover of the PNA so that you can see the FPI board. On the FPI board, next to the barcode label, is a revision sticker. If this sticker reads “009” it is not necessary to replace the FPI board. In this case, mark the end of the RPG spindle with a black permanent marker and reassemble the PNA.

Action:

Replace the following FPI boards with the E8361-63061 revision 009 FPI board. You can find instructions for replacing the FPI board in the Service Guide for your PNA¹.


- E8356-60029
- E8356-60209
- E8361-63061 revisions 001 to 007
- E8361-63061 revision 008. This FPI board can be modified, rather than replaced, using the following procedure.

NOTE: While the front panel assembly is removed, remember to add the new bracket modification described in Service Note E8801A-02.

The following procedure can also be found online at:

<http://na.tm.agilent.com/pna/frontpanelmod.html>.

Figure 1



Refer to Figure 1 for the two modification areas to be addressed. Note that while this picture happens to show the FPI board completely removed from the front frame assembly, this is not necessary to perform the required modifications.

- Modification #1 consists of shorting two pins of U4 together with a small amount of solder.
- Modification #2 consist of removing L1.

Modification #1

Carefully solder pins 21 and 22 together on U4. Refer to Figure 2 for the exact location. Use care so that no other pins are shorted. Use of a very fine tip soldering iron is recommended and a large work-task magnifying glass is very helpful.

Modification #2

Unsolder and completely remove the black surface mount inductor L1 from the front panel assembly board. This is no longer needed and can be discarded.


Identification Items

When the modifications have been completed, you need to change the board revision number from its existing version to version 009. You can cross off the existing revision label and write in "009" or you can create your own label to place over it.

Look at the date code on the side of the RPG (Rotary Pulse Generator or optical encoder). If the date code is between 0609 and 0718 (inclusive) then skip this step and read the next paragraph. Otherwise, remove the front panel knob and place a large **black** dot on the end of the RPG shaft using a permanent marking pen and then replace the knob. This will indicate to others (service centers and repair personnel) that this modification has already been made. This location is used so that the PNA does not need to be first disassembled.

Warning! If the date code of the RPG is from 0609 to 0718, then you may have problems removing the knob. On these units, the RPG shaft may be pulled out of the RPG while trying to remove the knob, thus destroying the RPG. While Agilent will replace this for free, this would incur more unwanted downtime. For these cases you may just want to place a label on the back of the PNA, to the left of the CPU board. This label should read simply "FPI 009." If needed, the Agilent part number for the RPG is 1990-1865.

Figure 2



Action 2 (Only for models with Option 014 or 015): Perform Source Calibration and Receiver Calibration.

PNA models with Option 014 or 015 that have had an E8361-63061 FPI board installed require a new Source calibration and Receiver calibration. For instructions on performing these calibrations, refer to the calibration section of PNA Help that is embedded in the analyzer. PNA Help can also be viewed online. Use the Action 1 steps A-C above, but in Step C, click on the title/hyperlink for PNA Help.

Action 3: Perform tests on the A1, A2, and A3 assemblies to verify correct operation of the new FPI board.

You can find instructions for performing the necessary tests in the Service Guide for your PNA. To view this Service Guide information online, use the steps in the footnote below, but in Step F locate the chapter "Troubleshooting". Next, click on the title/hyperlink for the section "Front Panel Troubleshooting." Perform the tests for the A1, A2, and A3 assemblies.

¹To view this Service Guide information online, use the following steps:

- A. Go to <http://www.agilent.com>.
- B. Enter your PNA model number (Ex: E8356A) in the Search function and click **Search**.
- C. Click on **Manuals**.
- D. Click on the title/hyperlink for the Service Guide. If you don't find your Service Guide listed on the Web page that is displayed initially, click on the **More** hyperlink.
- E. When the PDF of the Service Guide is displayed, click on the bookmark for the Contents section.
- F. Scroll through the Contents section to locate the chapter "Repair & Replacement Procedures."
- G. Click on the title/hyperlink for the section "Removing & Replacing Front Panel Subassemblies."
- H. Follow the instructions in the subsection "Removing the A3 Front Panel Interface Board Assembly."