

Modification Recommended Service Note

Supersedes:
J7201B-01

J7201B Attenuation Control Unit, DC to 18 GHz, 0 to 121 dB, 1-dB Steps

Serial Numbers: MY59400001 to MY61410177

The Problem – There is a potential issue where some instruments are unable to boot up and are stuck on the boot-up screen. They are not functioning.

Parts Required:

P/N	Description	Qty.
J7201-63004	PPMC PCA-Programmed for J7201X	1

ADMINISTRATIVE INFORMATION

ACTION	☒ ON SPECIFIED FAILURE	STANDARDS	
CATEGORY:	☐ AGREEABLE TIME	LABOR:	1.0 Hours
LOCATION	☐ CUSTOMER INSTALLABLE (No Parts involved)	SERVICE:	☐ RETURN
	☒ SERVICE CENTER	INVENTORY:	☐ SCRAP
CATEGORY:	☐ ON-SITE (active On-site contract required)		☐ SEE TEXT
	☐ CHANNEL PARTNERS		☐ SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	NO CHARGE AVAILABLE UNTIL:	5 May 2026
	☒ Calibration Required	PRODUCT LINE:	PLWN
	☐ Calibration NOT Required	AUTHOR:	CT


ADDITIONAL INFORMATION:

Situation:


The instrument is unable to boot up and is stuck on the boot-up screen as follows. It is not functioning.



Failure analysis had indicated defective on P0600-63004 board where insufficient solder was observed at 2 locations. The insufficient solder was due to Via in Pad (VIP) where the melted solder had flown to the secondary side of the PCB.



The improvements were made from Via in Pad (VIP) to Via in Pad Plated Over (VIPPO) as per below.



The improved PPMC board have Serial number P06006300423**2413**000007 onwards.

Solution/Action:

Replace PPMC board P0600-63004 with Programmed PPMC board serial number P06006300423**2413**000007 onwards where 13 is the work week and 24 is the year.



After PPMC board replace with J7201-63004 Programmed PPMC board, continue with instrument repair procedure.

Revision History:

Date	Service Note Revision	Author	Reason for Change
05 May 2025	01	Lam CT	As Published
11 Aug 2025	02	Lam CT	Update Part required