Modification Recommended Service Note

Supersedes: NONE

M9155C PXI Hybrid Dual SPDT Coaxial Switch, DC to 26.5 GHz, Unterminated

Serial Numbers: TH60450001 - TH61350508

The Problem – The cycle count of the unit is abnormally high. Fresh units from the factory have a cycle count of 16777215 cycles. This number is the default value for the EEPROM that stores the cycle count information. Due to a factory process issue, the cycle count was not reset. When users start using the switch, the cycle count starts from 16777215 onwards.


Parts Require P/N	ed: Description	Qty.	
NONE			
ADMINISTRAT	IVE INFORMATION		
ACTION CATEGORY:	[] ON SPECIFIED FAILURE [] AGREEABLE TIME	STANDARDS LABOR: 0.5 Hours	
LOCATION CATEGORY:	[X] CUSTOMER INSTALLABLE (No Parts involved) [] SERVICE CENTER [] ON-SITE (active On-site contract required) [] CHANNEL PARTNERS	1N1) (ENITOD) ([] 00DAD	SED [] RETURN RTS: [] SCRAP [] SEE TEXT
AVAILABILITY	: PRODUCT'S SUPPORT LIFE	NO CHARGE AVAILABLE UNTIL: N/A	
	Calibration Required Calibration NOT Required	PRODUCT LINE: WN AUTHOR: CT	
	INFORMATION: cycle count per Action below. No unit return.		



Situation:


The cycle count of the unit is abnormally high. Fresh units from the factory have a cycle count of 16777215 cycles. This number is the default value for the EEPROM that stores the cycle count information. Due to a factory process issue, the cycle count was not reset. When users start using the switch, the cycle count starts from 16777215 onwards.

Rest assured that there is no impact on quality and function. The unit can work normally even with this high cycle count.



Solution/Action:

Clear the Cycle count using the Soft Front Panel (Keysight Switch Module) Utility -> Clear Cycle Count -> Clear Counter -> Yes



Revision History:

	Note Revision	Author	Reason for Change
21 May 2025	01	CT	As Published