N4906B-02A

SERVICE NOTE

Supersedes: N4906B-02

N4906B - Serial Bit Error Ratio Tester

Serial Numbers: DE45200370 – DE45200400

MY45200500 - MY45200520

An incorrect setting within the Agilent IO Libraries may lead to programmatic inaccessibility and communication failure of the N4906B when connected via the GPIB bus. There are 3 items to verify and modify when this occurs.

Parts Required: P/N	Description	Qty.
NONE		

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:				
MODIFICATION RECOMMENDED				
ACTION CATEGORY:	[[]] ON SPECIFIED FAILURE XX AGREEABLE TIME	STANDARDS LABOR: 0.3 Hours		
LOCATION CATEGORY:	XX CUSTOMER INSTALLABLE XX ON-SITE XX SERVICE CENTER XX CHANNEL PARTNER	SERVICE [[]] RETURN INVENTORY: [[]] SCRAP XX SEE TEXT	USED [[]] RETURN PARTS: [[]] SCRAP XX SEE TEXT	
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	NO CHARGE AVAILABLE UNTIL: 31-Jan-2012		
AUTHOR: HK		PRODUCT LINE: PL24		
ADDITIONAL INFORMATION:				

© AGILENT TECHNOLOGIES, INC. 2010 PRINTED IN U.S.A.



November 5, 2010

Rev. 17

Page 2 of 10 N4906B-02A

Situation:

There are 3 items to verify and modify if required:

1. An older version of the Agilent IO-Libraries may lead to problems. Verify whether the correct version is installed.

- 2. Verify the configuration of the Agilent IO Libraries "Internal Instruments".
- 3. An incorrect setting within the Agilent IO Libraries may lead to programmatic inaccessibility and communication failure of the N4906B when connected via the GPIB bus.

Verify installed version of Agilent IO-Libraries

Units in the specified range of serial numbers may have an older version of the Agilent IO Libraries installed which shows unwanted behavior.

Please check the installed version of the Agilent IO Libraries:

- 2. On the menu bar of the Agilent Connection Expert select Help \rightarrow About



The version number should be at least **15.5.13009.1**. If that is the case please continue with the steps in the next chapter: "Check the configuration of the Agilent IO Libraries "Internal Instruments"

- 3. If the installed version is lower than that please do the following:
 - a. Install the newer version on top of the older version. You can get it from here: \\wbbnps03\ftp_support\All-Support\PV_Software\Agilent_IO_Libs\IO_Libs_15.5\\IOLibSuite 15 5 13009 1.exe
 - Reboot the N4906B.
 Please check whether the N4906B application starts up without any errors (firmware server and GUI). You should not have to install the N4906B application again after the Agilent IO-Libs update.
 - c. Continue with the steps in the next chapter: "Check the configuration of the Agilent IO Libraries "Internal Instruments"

Page 3 of 10 N4906B-02A


Verify the configuration of the Agilent IO Libraries "Internal Instruments"

Please check whether all "Internal Instruments" are set up correctly.

- 1. Close the Agilent Connection Expert, which may still be open from the previous step.
- 2. Start the IO Configuration Manager "iocfg32.exe" on the N4906B which is located in the directory

C:\Program Files\Agilent\IO Libraries Suite\bin.

You will get the following window:



3. On the left side, under "Available Interface Types" you should see a line "Internal Instruments".

If you do not have the line "Internal Instruments" please do the following:

- a. Exit the IO Configuration Manager" by pressing ok.
- b. Go to the following directoryC:\Program Files\Agilent\N4906B\GPIB
- c. Execute the program "install.exe" by double-clicking on it.
- d. Again start the IO Configuration Manager "iocfg32.exe" on the N4906B which is located in the directory
 - C:\Program Files\Agilent\IO Libraries Suite\bin.
- e. Now you should have a line item "Internal Instruments" on the left side.
- **4.** On the right side you should see the following important configured interfaces: ASRL1, ASRL2, GPIB0, GPIB1, GPIB2, TCPIP0 and USB0. Now let's check the configuration for each of the important ones.

NOTE: At the bottom of this list you find instructions on how to correct the configurations in case they do not match the descriptions!

Page 4 of 10 N4906B-02A

5. GPIB0

GPIB0 is a virtual GPIB interface ("Internal Instrument") which allows programmatic access to the N4906B via GPIB.




6. GPIB1

GPIB1 is a virtual LAN interface ("Internal Instrument") which allows programmatic access to the N4906B via LAN



7. GPIB2


GPIB2 is the physical 82350 PCI GPIB card that is accessible from the rear side of the N4906B. The serial number of the N4906B is shown in the field at the top.



Page 5 of 10 N4906B-02A


8. TCPIP0

TCPIP0 is the physical LAN interface of the N4906B, accessible from the rear side of the N4906B.



9. USB0


USB0 is the physical USB interface of the N4906B. There may be entries in the table below depending on whether one of the following devices was connected to the instrument: N4916A, N4916B, N4876A or alike.



Page 6 of 10 N4906B-02A

In case the configurations you find do not match the descriptions above, please change them using the following steps:

- 1. Exit the Agilent Connection Expert on the N4906B.
- 2. Start the IO configuration manager "iocfg32.exe" on the N4906B which is located in the directory
 - C:\Program Files\Agilent\IO Libraries Suite\bin.
- 3. Delete all incorrectly configured interfaces from the list of interfaces below: select the mismatching interface and press "Remove" in the window below (step #1 and #2).



4. Select "Internal Instrument" in the window above and press "Configure" (step #3 and #4).

NOTE: Enter the fields (e.g. SICL interface Name, VISA Interface name, etc.) exactly as shown in the above descriptions of the interfaces (previous page)!

Reboot the N4906B and check again. Use the ViFind32 debug utility to check the results



The important line is circled in yellow:

```
C:\PROGRA-1\IVIFOU-1\VISA\winnt\agvisa\vifind32.exe

This application is using the 32-bit Agilent UISA


Found 4 resources:

2: GPIB0::11::INSTR
2: GPIB1::INTEC
4: GPIB2::INTEC

Done
Press <return> to exit
```

Page 7 of 10 N4906B-02A

The Agilent Connection Expert shows the following:



Page 8 of 10 N4906B-02A

Verify GPIB Controller Configuration


The N4906B instrument has a GPIB connector on the back which may be used for programmatic control of the unit. On a GPIB bus there are several slaves and one master, which usually would be an external PC connected to the GPIB bus acting as a controller. However, in the noted serial number range of the N4906B there may be the case that the N4906B may act as master, too. This leads to a communication failure of the complete GPIB bus.

It is necessary to change the settings of the built-in GPIB controller card with the help of the Agilent IO Libraries ("Agilent Connection Expert").

Solution/Action:

Please execute the following steps to correctly configure the N4906B GPIB interface card:

- 2. You will see the following window:



Identify the GPIB2 interface, select it with the mouse and right-click it to get the menu shown above. In the menu select "Change Properties".

Page 9 of 10 N4906B-02A

3. You will see the following picture:



You will find the 2 checkboxes checked as shown in the picture above.

4. Please **uncheck** both checkboxes as shown in the next picture:



The **correct** settings shown in the picture above will make sure that the N4906B does not act as GPIB master and does not disturb communication on the GPIB bus.


Page 10 of 10 N4906B-02A

5. Click **ok** in the window above (step 4) and return to the main screen of the "Agilent Connection Expert".



Identify the GPIB0 interface, select it with the mouse and right-click it to get the menu shown above. In the menu select "**Ignore**".

6. The green next to the GPIB0 in the list should change to purple as shown in the picture below. "Ignore" means, that the "Agilent Connection Expert" will ignore devices connected to this interface on future device scans. This will prevent the "Agilent Connection Expert" from reconfiguring devices connected to this interface and the configuration steps described above will persist.



7. Now reboot the N4906B to check for the firmware/hardware handshake and then verify the implemented "Agilent Connection Expert" configuration is unchanged.