

MODIFICATION RECOMMENDED

N9912A-04

S E R V I C E N O T E

Supersedes:
NONE

N9912A - FieldFox RF Analyzer

Serial Numbers: ALL

Potential frequency accuracy shifted when booting N9912A from standby mode.

Parts Required:

P/N	Description	Qty.
------------	--------------------	-------------

NONE

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	X ON SPECIFIED FAILURE	STANDARDS LABOR: 0.25 Hours	
LOCATION CATEGORY:	X CUSTOMER INSTALLABLE X ON-SITE X SERVICE CENTER X CHANNEL PARTNER	SERVICE INVENTORY: SEE TEXT	USED PARTS: SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE NO CHARGE AVAILABLE UNTIL: END OF SUPPORT		
AUTHOR: DYCS		PRODUCT LINE: WN	
ADDITIONAL INFORMATION: N/A			

© AGILENT TECHNOLOGIES, INC. 2010
PRINTED IN U.S.A.

August 24, 2010

Rev. 17



Situation:

Firmware versions earlier than A.05.17 may cause the N9912A to be out of specification for frequency accuracy when booted from standby mode during an NA or SA measurement.

Solution/Action:

New firmware (starting from A.05.17) has been developed to enhance the FieldFox N9912A system performance.

Instruction to download the updated firmware is available at the FieldFox support page link, <http://na.tm.agilent.com/fieldfox/>.