

# MODIFICATION RECOMMENDED

## P9001A-02

# S E R V I C E N O T E

Supersedes:  
NONE

P9001A Agilent P9000 series Massively Parallel  
Parametric Test System

Serial Numbers: JP51320103, JP52020101/JP52020169

Industrial PC requires SATA digital cable and DVI extension cable to replace

### Parts Required:

P/N	Description	Qty.
8121-2464	Cable-Assembly (SATA digital)	3
8121-2649	Cable-Assembly (DVI Extension)	1

### ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
<b>MODIFICATION RECOMMENDED</b>		
ACTION <input type="checkbox"/> ON SPECIFIED FAILURE CATEGORY: <input checked="" type="checkbox"/> AGREEABLE TIME	STANDARDS LABOR: 1.0 Hours	
LOCATION <input type="checkbox"/> CUSTOMER INSTALLABLE CATEGORY: <input checked="" type="checkbox"/> ON-SITE ( <b>active On-site contract required</b> ) <input type="checkbox"/> SERVICE CENTER <input type="checkbox"/> CHANNEL PARTNER	SERVICE <input type="checkbox"/> RETURN INVENTORY: <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT	USED <input type="checkbox"/> RETURN PARTS: <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY: PRODUCT'S SUPPORT LIFE	NO CHARGE AVAILABLE UNTIL: March 2016	
<input type="checkbox"/> Calibration Required <input checked="" type="checkbox"/> Calibration NOT Required	PRODUCT LINE: PL1H AUTHOR: J.Ito	
ADDITIONAL INFORMATION:		

© AGILENT TECHNOLOGIES, INC. 2014  
PRINTED IN U.S.A.

March 14, 2014

Rev. 22



**Situation:**

Agilent industrial PC includes SATA digital cables and bundle DVI extension cable. These cables are provided by same vendor with SATA power conversion cable that should be replaced as Service Note P9001A-01. Though these cables don't have manufacturing problem, but Agilent offers to replace.

**Solution/Action:**

Remove industrial PC from system cabinet, and replace PN 8121-2464 SATA digital cables (x 3ea) and PN 8121-2649 DVI extension cable.

SATA digital cable:




Old cable is longer (=1m)

New cable (PN 8121-2464) is shorter (=30cm)

DVI extension cable:



Old cable has ferrite core on both sides



New cable (PN 8121-2649) has ferrite core on only one side

**Replacement Procedure**

1. Shutdown industrial PC and power off the P9001A.
2. Un-mount the Agilent industrial PC from P9001A system cabinet.
3. Replace SATA digital cables (x 3ea). For how to service IPC, check the support material “IPC Support Supplemental 2<sup>nd</sup> Edition” from HSTD,SVC-SUPPORT to SSE (System Support Engineer).

**Revision History:**

Revision Number	Date	Author	Reason For Change
1.0	2014/3/14	J.Ito	As published