

MODIFICATION RECOMMENDED

U2000A-04

S E R V I C E N O T E

Supersedes:
NONE

10MHz – 18GHz USB Power Sensor

Serial Numbers: SG00000000-SG99999999, MY00000000-MY99999999

USB sensor returns incorrect power reading when offset is introduced programmatically with the measurement unit is in Watt.

To Be Performed By: Agilent-Qualified Personnel or Customer

Parts Required:

P/N	Description	Qty.
-----	-------------	------

NONE

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	X IMMEDIATELY <input type="checkbox"/> ON SPECIFIED FAILURE : <input type="checkbox"/> AGREEABLE TIME	STANDARDS LABOR: 0.0 Hours	
LOCATION CATEGORY:	X CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY: <input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT	USED PARTS: <input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY: PRODUCT'S SUPPORT LIFE		NO CHARGE AVAILABLE UNTIL: ALWAYS	
AUTHOR: LCH		PRODUCT LINE: WC	
ADDITIONAL INFORMATION:			

© AGILENT TECHNOLOGIES, INC. 2008
PRINTED IN U.S.A.



March 27, 2008

Situation:

When an offset value is introduced programmatically and the measurement unit is in Watt, the USB sensor will return incorrect power measurement.

Solution/Action:

Customer is recommended to update the USB sensor with the latest revision of firmware. The latest revision of firmware can be downloaded from Agilent web site.