S E R V I C E N O T E

SUPERSEDES: NONE

3235A Switch/Test Unit

Serial Numbers: 2843A00000 / 2843A03110

Incorrectly Labeled Line Voltage Switches May Cause Switch Setting Confusion

Situation:

Some units may have incorrectly labeled line voltage selection switches installed. The correct settings appear silkscreened on the instrument rear panel. The incorrect settings are silkscreened on the voltage selection switches themselves.




Figure 1. AC Line Voltage Switch Positions

Solution/Action:

No action is required. However, to avoid confusion, the incorrectly silkscreened line voltages may be easily scratched off using a flat-head screwdriver.

DATE: 09 September 1991

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
INFORMATION ONLY		
AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:
СМС	0900	

© 1991 AGILENT TECHNOLOGIES PRINTED IN U.S.A.

