

MODIFICATION RECOMMENDED

33250A-02

S E R V I C E N O T E

Supersedes:
None

33250A 80 MHz Function/Arbitrary Waveform Generator

Serial Numbers: MY40023753/MY40024085
SG40006597/SG40006599

Flatness Calibration Error

Parts Required:

P/N	Description	Qty.
NONE		

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	<input type="checkbox"/> ON SPECIFIED FAILURE <input checked="" type="checkbox"/> AGREEABLE TIME	STANDARDS	LABOR: 1.0 Hours
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER <input type="checkbox"/> CHANNEL PARTNER	SERVICE INVENTORY: <input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input checked="" type="checkbox"/> SEE TEXT	USED PARTS: <input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input checked="" type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	NO CHARGE AVAILABLE UNTIL: September 2010	
AUTHOR:	LH	PRODUCT LINE: SP	
ADDITIONAL INFORMATION:			

© AGILENT TECHNOLOGIES, INC. 2009
PRINTED IN U.S.A.

August 24, 2009

Rev. 16



Situation:

Agilent has recently discovered an error during flatness calibration for the units with the serial numbers listed in the table below. If your serial number is not located in this table then your unit was not affected and this service note does not apply.

MY40023753	MY40024021	MY40024062
MY40023976	MY40024024	MY40024063
MY40023981	MY40024025	MY40024064
MY40023989	MY40024026	MY40024066
MY40023991	MY40024028	MY40024067
MY40023994	MY40024029	MY40024068
MY40024001	MY40024030	MY40024069
MY40024003	MY40024031	MY40024071
MY40024006	MY40024033	MY40024072
MY40024007	MY40024034	MY40024073
MY40024008	MY40024035	MY40024074
MY40024010	MY40024052	MY40024077
MY40024011	MY40024053	MY40024078
MY40024012	MY40024054	MY40024081
MY40024015	MY40024055	MY40024082
MY40024016	MY40024056	MY40024083
MY40024017	MY40024057	MY40024085
MY40024018	MY40024059	SG40006597
MY40024019	MY40024060	SG40006598
MY40024020	MY40024061	SG40006599

Solution/Action:

We recommend the unit be sent to the nearest local service center for a FREE recalibration.