A MODIFICATION ONLY - DOES NOT COMMUNICATE

34908A -03

<u>SERVICE NOTE</u>

Supersedes: NONE

34908A 40 Channel Multiplexer Single Ended

Serial Numbers: ALL US, MY, SG

New Relay Verification Procedures: 34901A, 34902A, 34904A, 34908A Modules

Parts Required:

NONE

Situation:

The relay verification procedures have been redesigned for the 34901A, 34902A, 34904A and 34908A. The new procedures use an external DMM to make 4 wire resistance measurements across various paths containing relay contacts. The procedure allows you to identify bad relays. It is more complete compared to the old procedure.

Solution/Action:

The new procedures can be found in Edition 3 of the 34970A Service Guide. The 34970A Service Guide can be obtained by:

- 1) Downloading/Viewing Service Guide via the web Go to <u>www.agilent.com/find/34970A</u> scroll to the bottom of the page and select link "Manuals, Guides and Notifications"
- 2) Ordering the 34970A manual set, part number 34970-90101.

ADMINISTRATIVE INFORMATION

INFORMATION ONLY

AUTHOR: DAA PRODUCT LINE: 9E

SERVICE NOTE CLASSIFICATION:

ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2003 PRINTED IN U.S.A.



June 18, 2003