34931A-02

# S E R V I C E N O T E

Supersedes: NONE

## 34931A Dual 4x8 Armature Matrix Module for 34980A

**Serial Numbers:** MY44000591-MY44000704

Intermittent contact resistance with Analog Bus (ABus) relays.

**Parts Required:** 

P/N Description Qty.

34931-60001 Dual 4x8 Armature Matrix new replacement unit 1

### **ADMINISTRATIVE INFORMATION**

| SERVICE NOTE CLASSIFICATION:   |   |  |   |  |  |
|--|---|--|---|--|--|
| MODIFICATION RECOMMENDED   |   |  |   |  |  |
| ACTION<br>CATEGORY:  | √ ON SPECIFIED FAILURE<br>[[]] AGREEABLE TIME   | STANDARDS  LABOR: 0.5 Hours                                |   |  |  |
| LOCATION<br>CATEGORY:  | [[]] CUSTOMER INSTALLABLE<br>[[]] ON-SITE<br>√ SERVICE CENTER<br>[[]] CHANNEL PARTNER | SERVICE √ RETURN<br>INVENTORY: [[]] SCRAP<br>[[]] SEE TEXT | USED [[]] RETURN<br>PARTS: [[]] SCRAP<br>√ SEE TEXT |  |  |
| AVAILABILITY: PRODUCT'S SUPPORT LIFE   |   | NO CHARGE AVAILABLE UNTIL: 7/1/2014                        |   |  |  |
| [[]] Calibration Required  √ Calibration NOT Required                                  |   | PRODUCT LINE: BL<br>AUTHOR: TP                             |   |  |  |
| ADDITIONAL INFORMATION: Used parts are to be returned to factory for failure analysis. |   |  |   |  |  |

© AGILENT TECHNOLOGIES, INC. 2013 PRINTED IN U.S.A.



Page 1 of 2

June 7, 2013

Rev. 20

Page 2 of 2 34931A-02

#### **Situation:**

The ABus relays used in these affected 34931A modules may exhibit intermittent high contact resistance. This can affect two wire resistance measurements and can cause excessive voltage drop in sensitive signal routing applications.

#### **Solution/Action:**

If these symptoms are observed, contact Agilent Service for a replacement.

#### Note:

- New specifications apply to module replacement with serial number MY52490001/ SG52490001 and above. Please refer to the 34980A datasheet in the product website (<a href="http://www.agilent.com/find/34980A">http://www.agilent.com/find/34980A</a>) for latest specifications.
- If you use Y1131A verification software version 1.0, July 2005, please update to the latest version at the Y1131A product website (<a href="http://www.home.agilent.com/en/pd-1383501-pn-Y1131A/verification-and-diagnostic-tools?nid=-33253.778753.00&cc=US&lc=eng">http://www.home.agilent.com/en/pd-1383501-pn-Y1131A/verification-and-diagnostic-tools?nid=-33253.778753.00&cc=US&lc=eng</a>) to test to the latest specifications.

**Revision History:** 

| Revision<br>Number | Date   | Author | Reason For Change |
|--------------------|--------|--------|-------------------|
| 1.0                | 6/7/13 | TP     | As Published      |
|                    |        |        |                   |