

INFORMATION ONLY – DOES NOT COMMUNICATE  
A MODIFICATION OR SAFETY CONDITION

**37718A-05**

**S E R V I C E                      N O T E**

---

Supersedes:  
None

**37718/9A Build Status 3.xx and 4.xx OmniBER**

**Serial Numbers: GB00000001 and up**

**Option 350 changes to option 355 in 37718A units**

**Option 355 will replace 350 in all new production units and retrofitted units**

**Parts Required:**

<b>P/N</b>	<b>Description</b>	<b>Qty.</b>
None		

**ADMINISTRATIVE INFORMATION**

SERVICE NOTE CLASSIFICATION: <b>INFORMATION ONLY</b>
AUTHOR: John Crawford      PRODUCT LINE: 2Q
ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2002  
PRINTED IN U.S.A.

March 25, 2002



**Situation:**

Dear valued customer,

Please note that if your 37718/9A instrument was initially shipped with or had option 350 installed, as a consequence of our OmniBER follow on developments, we are pleased to inform you that we have enabled extra functionality for your unit free of charge.

As a result of this, on the options page on your instrument, #355 will now appear instead of #350.

**Detail of extra functionality :**

Advanced APS measurements

Service Disruption measurement at OC-48C/12C and STM-16C/4C

Event history captures first 10 measurements

Time stamping for event correlation

**Solution/Action:**

None