

S E R V I C E N O T E

SUPERSEDES: None

37721A Digital Transmission Analyzer

Serial Numbers: 3015U00100 / 9999U99999

Replacement of Coaxial Cable Assembly

In the event of the 75ohm SIGNAL OUT and 75ohm SIGNAL IN coaxial cables becoming intermittent, it is recommended that the cables are replaced. The part number of the cable is 37721-60025.

DATE: 31 October 1991

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
INFORMATION ONLY		
AUTHOR: JH	ENTITY: 1400	ADDITIONAL INFORMATION: