

S E R V I C E N O T E

SUPERSEDES: NONE

37722/32A Telecom Analyzer Options B01/B48

Serial Numbers: 0000U00000/9999U99999

Impulse noise on external DC Supply may cause the unit to shutdownDuplicate Service Notes: 37722A-04
37732A-09**Situation:**

Impulse noise on external DC Supply may cause the unit to shutdown.

Solution / Action:

This can be rectified by adding 2 0.47mf capacitors to an earth lug.

Parts Required

P/N	Description	Quantity
0160-7716	CF MP 0.47mf 250V	2
0360-0040	TRM-SLDR LG 1/4L	1

DATE: May 1999

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	☐ IMMEDIATELY ☒ ON SPECIFIED FAILURE ☐ AGREEABLE TIME	STANDARDS: LABOR .05 Hours	
LOCATION CATEGORY:	☒ CUSTOMER INSTALLABLE ☐ ON-SITE ☐ SERVICE CENTER	SERVICE INVENTORY: ☐ RETURN ☒ SCRAP ☐ SEE TEXT	USED PARTS: ☐ RETURN ☒ SCRAP ☐ SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE		AGILENT RESPONSIBLE UNTIL: 2001
AUTHOR: GS	ENTITY: E610	ADDITIONAL INFORMATION:	