

S E R V I C E N O T E

SUPERSEDES: NONE

**4062F Semiconductor Parametric Test System**

Serial Numbers : JP10B00101 / JP10B00152

**Design Change of Cabinet Front Door**

**Parts Required :**

P/N	QTY	Description
04062-60417	1	Front Door Assy

**Situation :**

The 8110A PGs in the 4062F can overheat and cease functioning after sufficient stress. When this happens, the error message which the PGs report is "SELFTTEST ERROR."

**Solution / Action :**

The 4062F front door design is changed to prevent the PGs from heating up by themselves. The new front door has additional air holes to ventilate the system cabinet. The part number of the new door is 04062-60417, stocked at SMO.

If the PGs in the 4062F are broken by the heat problem, the front door must be replaced by using this service note.

DATE: January 1997

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
<b>MODIFICATION RECOMMENDED</b>			
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input checked="" type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS:	LABOR 0.5 Hours
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input checked="" type="checkbox"/> ON-SITE <input type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY:	<input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	USED PARTS:	<input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AUTHOR: SY	ENTITY: 3301	AGILENT RESPONSIBLE UNTIL:	January 1999
		ADDITIONAL INFORMATION: Relative Service Note 4062F-03	