

S E R V I C E N O T E

SUPERSEDES: None

41800A Active Probe

Serial Numbers: 2850J03319 / 2850J03338

Recommended replacement nose assembly for probe pin

To Be Performed By: Agilent-Qualified Personnel

Parts Required:

P/N	Description	Qty.
41800-60002	Nose Assembly	1

Situation:

The rubber on the bottom of the probe pin is designed as loosely pressed. But when the nose assembly is made of poor quality, it may be pressed too much and possibly broken. The failure nose assembly was made at most four each. They may be shipped as a part of the 41800A model, but they were never shipped as replacement parts.

Solution/Action:

Replace the nose assembly with the new one listed above.

DATE: October 1994

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input checked="" type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS:	Labor 0.5 Hours
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	USED PARTS:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input checked="" type="checkbox"/> SEE TEXT
AUTHOR: AY	ENTITY: 3355	AGILENT RESPONSIBLE UNTIL: October 1996	
		ADDITIONAL INFORMATION:	