

4339B-05

Modification Recommended Service Note

Supersedes:
NONE

4339B High Resistance Meter

Serial Numbers: MY43103671 to MY43104431

Offset Voltage Test might fail, during PVT

Parts Required:

P/N	Description	Qty.
04339-66503	Printed Circuit Assembly, Ammeter Board Assembly	1

ADMINISTRATIVE INFORMATION

ACTION	<input checked="" type="checkbox"/> ON SPECIFIED FAILURE	STANDARDS			
CATEGORY:	<input type="checkbox"/> AGREEABLE TIME	LABOR:	3.5 Hours		
LOCATION	<input type="checkbox"/> CUSTOMER INSTALLABLE	SERVICE:	<input type="checkbox"/> RETURN	USED	<input type="checkbox"/> RETURN
CATEGORY:	<input type="checkbox"/> ON-SITE (active On-site contract required)	INVENTORY:	<input type="checkbox"/> SCRAP	PARTS:	<input checked="" type="checkbox"/> SCRAP
	<input checked="" type="checkbox"/> SERVICE CENTER		<input type="checkbox"/> SEE TEXT		<input type="checkbox"/> SEE TEXT
	<input type="checkbox"/> CHANNEL PARTNERS				
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	NO CHARGE AVAILABLE UNTIL:	1-Dec-2022		
	<input checked="" type="checkbox"/> Calibration Required	PRODUCT LINE:	WN		
	<input type="checkbox"/> Calibration NOT Required	AUTHOR:	jm		

ADDITIONAL INFORMATION:

Situation:

Offset Voltage Test at Ammeter Offset and Input R Test might fail, due to a component part issue.

Solution/Action:

When Offset Voltage Test fails, replace defective 04339-66503 with a new 04339-66503.

Revision History:

Date	Service Note Revision	Author	Reason for Change
7 Sep 2017	4339B-05	jm	As Published