INFORMATION ONLY - DOES NOT COMMUNICATE A MODIFICATION OR SAFETY COMMUNICATE

54	8	3	1	R	_(16
JT	v	J			_	JV

<u>SERVICE NOTE</u>

Supersedes: NONE

54831B

Serial Numbers: [0000A00000 / 9999Z99999]

Update on errors in service manual 54830-97006. They will be corrected in next revision.

Parts Required:

P/N Description Qty.

NONE

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR: [initials] PRODUCT LINE: 1A

ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2002 PRINTED IN U.S.A.



August 5, 2002

Page 2 of 2 54830B-06

Situation:

In CH 7 "Replaceable Parts" Add the following replaceable parts.

MP40 54832-01201	CLIP FOR LOGIC CABLE	qty:1
MP41 54832-09103	PS HOLE SPRING	qty:1
MP42 54832-09102	CRT SPRING	qty:1
MP43 9170-2094	FERRITE CORE	qty:1
MP44 54832-40601	BNC SPRING	qty:1

On Chapter 7-12 to 7-13

Item W12, the p/n for Keyboard Cable is 54826-61601 instead of 54826-61602. Item MP12, the quantity should be 1 instead of 2.

On Chapter 7-11

Item A8, the Mesa HDD has been changed from 0950-3933 (5GB) to 0950-4166 (10GB) hard disk.

Solution/Action:

They will be corrected in next revision of service manual.