

S E R V I C E N O T E

SUPERSEDES: None

66106A System DC Power Supply

Serial Numbers: 3207A-00101 to 3207A-00160

Output connector cover assemblies crack

Duplicate Service Notes:

- 66101A-01
- 66102A-01
- 66103A-01
- 66104A-01
- 66105A-01
- 66106A-01

To Be Performed By: Agilent-Qualified Personnel or Customer

Parts Required:

| P/N | Description |
|-----------|-----------------------|
| 5040-1682 | Bottom Cover assembly |
| 5040-1683 | Top cover assembly |

Situation:

The DC Power Module output connector covers crack near the screw holes.

Continued

DATE:

ADMINISTRATIVE INFORMATION

| | | | |
|---------------------------------|--|---|---|
| SERVICE NOTE CLASSIFICATION: | | | |
| MODIFICATION RECOMMENDED | | | |
| ACTION CATEGORY: | <input type="checkbox"/> IMMEDIATELY <input checked="" type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME | STANDARDS: Labor 0.5 Hours | |
| LOCATION CATEGORY: | <input checked="" type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER | SERVICE INVENTORY: <input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT | USED PARTS: <input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT |
| AVAILABILITY: | PRODUCT'S SUPPORT LIFE | AGILENT RESPONSIBLE UNTIL: December 1995 | |
| AUTHOR: DF | ENTITY: 2100 | ADDITIONAL INFORMATION: | |

Solution/Action:

New cover assemblies are available. The new cover assemblies have been modified to strengthen the areas most likely to be stressed during installation. Screws should be evenly hand-tightened only and the use of thread locking adhesives should be avoided.