# S E R V I C E N O T E

SUPERSEDES: NONE

## 6673A DC Power Supply

**Serial Numbers:** 0000A00000 / 3501A00796

Downprogramming FETs Q901 and Q902 no longer have an isolated package.

#### **Duplicate Service Notes:**

6573A-01 Serials: 0000A00000 / 3432A00187 6574A-01 Serials: 0000A00000 / 3423A00258 6575A-02 Serials: 0000A00000 / 3423A00208 6673A-03 Serials: 0000A00000 / 3501A00796 6674A-03 Serials: 0000A00000 / 3501A00941 6675A-04 Serials: 0000A00000 / 3502A00551 6682A-01 Serials: 0000A00000 / 3514A00168 6683A-01 Serials: 0000A00000 / 3514A00178

To Be Performed By: Agilent-Qualified Personnel

Parts Required: Kit, Dwnprgmr-Svc, 5063-3403 (1 kit per FET)

Continued

DATE: January 1996

### ADMINISTRATIVE INFORMATION

ı	SERVICE NOTE CLASSIFICATION:		
INFORMATION ONLY			
Γ	AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:
l	DF	2100	
l			
l			
AUTHOR: ENTITY: ADDITIONAL INFORMA			

© 1996 AGILENT TECHNOLOGIES PRINTED IN U.S.A.



### **Situation:**

The original part, part number 1855-0835 has been discontinued by the manufacturer and the replacement part does not have an isolated package. Therefore, it cannot be mounted directly to the heat sink.

### **Solution/Action:**

If the original part fails, it may be replaced by the service kit 5063-3403. The kit consists of a new FET, 1855-1003, and an insulator, 0340-1507.