

S E R V I C E N O T E

SUPERSEDES: NONE

HP 83751A Synthesized Sweeper

Serial Numbers: 0000A00000 / 9999Z99999

Instructions on replacing defective on/off power switch**Duplicate Service Notes:**

83751B-05

83752A-06

83752B-05

Situation:

The "Power" on/off switches on some of the 8375X Series Synthesized Sweeper have failed to latch in the "ON" position. After evaluating the switch, it appears the switch may have a mechanical reliability problem. Currently, there is no new design for the replacement switch.

Solution/Action:

If the "Power" on/off switch will not latch in the "ON" position, replace the switch.

DATE: March 1997

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input checked="" type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS: LABOR 1.0 Hours	
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> HP LOCATION	SERVICE INVENTORY: <input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT	USED PARTS: <input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE		HP RESPONSIBLE UNTIL: March 1999
AUTHOR: DM	ENTITY: 5320	ADDITIONAL INFORMATION:	